

Rocky Mtn. Prep Creekside @ Southeast Annex (190B)

All results <15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/28/2016				
Sample ID	Sample Description	Lead Result	Units	Action
190B-124-SK-01	Classroom sink, room 124	<1.0* ¹	µg/L	
190B-126-SK-02	Classroom sink, room 126	<1.0	µg/L	
190B-128-DF-03	Drinking fountain, hallway 128, next to restrooms	<1.0	µg/L	
190B-135-SK-04	Classroom sink, room 135	<1.0	µg/L	
190B-148-SK-05	Classroom sink, room 148	<1.0	µg/L	
190B-156-SK-06	Classroom sink, room 156	2.7	µg/L	
190B-154-SK-07	Sink, room 154, next to lobby	<1.0	µg/L	
190B-154-DF-08	Drinking fountain, lobby 154, next to restrooms	<1.0	µg/L	
190B-101D-SK-09	Nurse sink, room 101D	<1.0	µg/L	
190B-155-SK-10	Classroom sink, room 155	<1.0	µg/L	
190B-100-DF-11	Bottle fill, hallway 100, across from 107	<1.0	µg/L	
190B-100-DF-12	Drinking fountain, hallway 100, associated with bottle fill, across from 107	<1.0	µg/L	
190B-100-DF-13	Drinking fountain, hallway 100, next to bottle fill, across from 107, right bubbler	<1.0	µg/L	
190B-100-DF-14	Drinking fountain, hallway 100, next to bottle fill, across from 107, left bubbler	<1.0	µg/L	
190B-109-DF-15	Drinking fountain, hallway 109, across from 110	<1.0	µg/L	
190B-109-DF-16	Drinking fountain, hallway 109, across from 113	<1.0	µg/L	
Phase II Sampled on 4/12/2017				
190B-134-SK-17	Classroom sink, room 134	<1.0	µg/L	
190B-145-SK-18	Classroom sink, room 145	<1.0	µg/L	

*1. Result less than 1.0 ppb is the lowest level that can be reported by the lab.