

Valdez Elementary (205)

August 2017: All issues addressed, results below action level, no further actions at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/27/2016					
Sample ID	Sample Description	Lead Result	Follow Up Results	Units	Action
205-135-SK-01	Kitchen prep sink, north wall	<1.0* ¹		µg/L	
205-135-SK-02	Kitchen kettle faucet	3.9		µg/L	
205-134-DF-03	Drinking fountain, all purpose room 134	<1.0		µg/L	
205-118G-SK-04	Staff lounge sink, room 118G	<1.0		µg/L	
205-118-DF-05	Drinking fountain, hallway 118, next to 118D	4.4		µg/L	
205-123-DF-06	Drinking fountain, hallway 123, next to restrooms, left bubbler	2.5		µg/L	
205-123-DF-07	Drinking fountain, hallway 123, next to restrooms, right bubbler	<1.0		µg/L	
205-124-DF-08	Drinking fountain, gymnasium, left fixture	1.8		µg/L	
205-124-DF-09	Drinking fountain, gymnasium, right fixture	<1.0		µg/L	
205-125-DF-10	Drinking fountain, hallway 125, next to gymnasium	<1.0		µg/L	
205-132-SK-11	Classroom sink, room 132, lower counter on left	<1.0		µg/L	
205-131-SK-12	Classroom sink, room 131, lower counter on right	2.2		µg/L	
205-127-SK-13	Classroom sink, room 127, upper counter	<1.0		µg/L	
205-128-SK-14	Classroom sink, room 128, upper counter	1.8		µg/L	
205-126-DF-15	Drinking fountain, hallway 126, next to room 129, left bubbler	<1.0		µg/L	
205-126-DF-16	Drinking fountain, hallway 126, next to room 129, right bubbler	<1.0		µg/L	
205-130-SK-17	Classroom sink, room 130	2.3		µg/L	
205-117-DF-18	Drinking fountain, hallway 117, next to room 119, left bubbler	1.8		µg/L	
205-117-DF-19	Drinking fountain, hallway 117, next to room 119, right bubbler	3.2		µg/L	
205-138B-SK-20	Staff lounge sink, room 138B	4.4		µg/L	
205-138C-SK-21	Staff lounge sink, room 138C	1.1		µg/L	
205-138A-DF-22	Drinking fountain, hallway 138A, adjacent to room 138	4.4		µg/L	
205-101A-SK-23	Nurse sink, room 101A	<1.0		µg/L	
205-106-DF-24	Bottle fill, hallway 106, across from room 113	<1.0		µg/L	
205-106-DF-25	Drinking fountain, hallway 106, across from room 113, left fixture	<1.0		µg/L	
205-106-DF-26	Drinking fountain, hallway 106, across from room 113, right fixture	<1.0		µg/L	
205-200-DF-27	Bottle fill, hallway 200, between restrooms	<1.0		µg/L	
205-200-DF-28	Drinking fountain, hallway 200, between restrooms, left fixture	<1.0		µg/L	
205-200-DF-29	Drinking fountain, hallway 200, between restrooms, right fixture	<1.0		µg/L	
205-204-DF-30	Bottle fill, hallway 204, between restrooms	<1.0		µg/L	

205-204-DF-31	Drinking fountain, hallway 204, between restrooms, left fixture	<1.0		µg/L	
205-204-DF-32	Drinking fountain, hallway 204, between restrooms, right fixture	<1.0		µg/L	
Phase II Sampled on 4/11/2017					
205-136-SK-33	Classroom sink, room 136	<1.0		µg/L	
205-130-SK-34	Classroom sink, room 130	1.0		µg/L	
205-129-SK-35	Classroom sink, room 129, tall counter	<1.0		µg/L	
205-129-SK-36	Classroom sink, room 129, short counter	2.0		µg/L	
205-128-SK-37	Classroom sink, room 128, short counter	<1.0		µg/L	
205-131-SK-38	Classroom sink, room 131, tall counter	3.0		µg/L	
205-127-SK-39	Classroom sink, room 127, short counter	<1.0		µg/L	
205-132-SK-40	Classroom sink, room 132, tall counter	<1.0		µg/L	
205-138-SK-41	Classroom sink, room 138	2.0		µg/L	
205-116-SK-42	Classroom sink, room 116	<1.0		µg/L	
205-116-DF-43	Drinking fountain, room 116	<1.0		µg/L	
205-115-SK-44	Classroom sink, room 115	<1.0		µg/L	
205-115-DF-45	Drinking fountain, room 115	<1.0		µg/L	
205-114-SK-46	Classroom sink, room 114, on south wall	<1.0		µg/L	
205-114-SK-47	Classroom sink, room 114, on west wall by stair A	<1.0		µg/L	
205-110-SK-48	Classroom sink, room 110	<1.0		µg/L	
205-109-SK-49	Classroom sink, room 109	<1.0		µg/L	
205-105-SK-50	LMC/IMC sink, room 105	2.0		µg/L	
205-217-SK-51	Classroom sink, room 217	20.0	9.0* ²	µg/L	Faucet replaced 7/26/2017
205-201-SK-52	Classroom sink, room 201	<1.0		µg/L	
205-214-SK-53	Classroom sink, room 214, on south wall	<1.0		µg/L	
205-214-SK-54	Classroom sink, room 214, on west wall, left faucet	<1.0		µg/L	
205-214-SK-55	Classroom sink, room 214, on west wall, right faucet	<1.0		µg/L	
205-207-SK-56	Classroom sink, room 207	<1.0		µg/L	
205-210-SK-57	Classroom sink, room 210	<1.0		µg/L	
205-211-SK-58	Classroom sink, room 211	<1.0		µg/L	
205-206-SK-59	Classroom sink, room 206	<1.0		µg/L	
205-202-SK-60	Classroom sink, room 202	<1.0		µg/L	
205-216-SK-61	Classroom sink, room 216, left sink on south wall	<1.0		µg/L	
205-215-SK-62	Classroom sink, room 215	<1.0		µg/L	

*1. Result less than 1.0 ppb is the lowest level that can be reported by the lab.

*2. Follow up sampling occurred on 8/29/2017 and tested with a Palintest SA1100 scanning analyzer.