

Carson Elementary (217) – 5420 E. 1st Ave.

SY 2019/2020 Long Term Sampling – Action Level 10 µg/L

Sample Date: 12/12/2019

Sample ID	Location Description	Lead Result (µg/L)	Action
217-H120G-SK01-01	Sink, PTA room H120G	7	
217-KIT-SK01-01	Kitchen sink, north wall, left faucet	<1.0 ¹	
217-KIT-SK02-01	Kitchen sink, north wall, right faucet	3.4	
217-KIT-SK03-01	Kitchen sink, east wall	2.5	
217-LR-DF01-01	Drinking fountain, cafeteria, southwest	9.6	
217-LR-DF02-01	Drinking fountain, cafeteria, southeast	3.8	
217-H120-DF01-01	Drinking fountain, hallway H120, next to room 106	<1.0	
217-H120-BF01-01	Bottle fill station, hallway H120, across from cafeteria	<1.0	
217-H120-DF02-01	Drinking fountain, hallway H120, across from gymnasium	21.3	Filter installed 2/2020
217-GYM-DF01-01	Drinking fountain, gymnasium, northeast corner	9.4	
217-H100-BF01-01	Bottle fill station, hallway H100, next to office	<1.0	
217-OFFCA-SK01-01	Nurse sink, room OFFCA	3.2	
217-GYMD-SK01-01	Lounge sink, room GYMD	5.5	
217-H110-BF01-01	Bottle fill station, hallway H110, next to door 12	<1.0	
217-123-DF01-01	Drinking fountain, classroom 123	2.2	
217-122-DF01-01	Drinking fountain, classroom 122	3.8	

Sample ID Key:

Building number – room number – fixture type count – long term bout count

1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/1/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
217-kit-sk-01	Kitchen sink, north wall, left	1.2		µg/L	
217-kit-sk-02	Kitchen sink, north wall, right	1.9		µg/L	
217-350-df-03	Drinking fountain, cafeteria, east side, left bubbler	2.2		µg/L	
217-350-df-04	Drinking fountain, cafeteria, east side, right bubbler	1.3		µg/L	
217-350-df-05	Drinking fountain, cafeteria, west side, left bubbler	5.4		µg/L	
217-350-df-06	Drinking fountain, cafeteria, west side, right bubbler	6.3		µg/L	
217-pta-sk-07	Sink, PTA room	6.1		µg/L	
217-h120-df-08	Drinking fountain, hallway H120, across from gym	6.1		µg/L	
217-h100-df-09	Drinking fountain hallway H100, next to main office	16.9	<1.0	µg/L	Fountain replaced 1/2018
217-h110-df-10	Drinking fountain, hallway H110, next to room 123	1.6		µg/L	
217-gym-df-11	Drinking fountain, gym	22.0	9.4	µg/L	Fountain replaced 1/2019
217-h120-df-12	Drinking fountain, hallway H120, across from cafeteria	2.3		µg/L	
217-h120-df-13	Drinking fountain, hallway H120, next to room 106, left bubbler	12.0	<1.0	µg/L	Bubbler replaced 1/2018, Filter installed 2/2019
217-h120-df-14	Drinking fountain, hallway H120, next to room 106, right bubbler	38.6	<1.0	µg/L	Bubbler replaced 1/2018, Filter installed 2/2019
217-h100-df-15	Drinking fountain, hallway H100, lobby, left bubbler	24.0	Pending	µg/L	Replaced 1/2018 – Pending Drain Repair
217-h100-df-16	Drinking fountain, hallway H100, lobby, right bubbler	19.0	Pending	µg/L	Replaced 1/2018 – Pending drain repair
217-122-df-17	Drinking fountain, room 122	10.2		µg/L	
217-123-df-18	Drinking fountain, room 123	2.6		µg/L	
Phase II Sampled on 2/8/2017					
217-106-SK-19	Classroom sink, room 106	4.0		µg/L	
217-107-SK-20	Classroom sink, room 107	7.0		µg/L	
217-105-SK-21	Classroom sink, room 105	6.0		µg/L	

217-108-SK-22	Classroom sink, room 108	3.0	µg/L
217-104-SK-23	Classroom sink, room 104	4.0	µg/L
217-109-SK-24	Classroom sink, room 109	5.0	µg/L
217-103B-SK-25	Classroom sink, room 103B	6.0	µg/L
217-110-SK-26	Classroom sink, room 110	3.0	µg/L
217-102B-SK-27	Classroom sink, room 102B	4.0	µg/L
217-111-SK-28	Classroom sink, room 111	4.0	µg/L
217-101B-SK-29	Classroom sink, room 101B	2.0	µg/L
217-112B-SK-30	LMC/IMC office sink, room 112B	5.0	µg/L
217-OFFCA-SK-31	Admin office sink, room OFFCA	4.0	µg/L
217-132-SK-32	Classroom sink, room 132	7.0	µg/L
217-GYMD-SK-33	Gymnasium office sink, room GYMD	5.0	µg/L
217-113-SK-34	Classroom sink, room 113	7.0	µg/L
217-130-SK-35	Classroom sink, room 130	12.0	µg/L
217-129-SK-36	Classroom sink, room 129	13.0	µg/L
217-114-SK-37	Classroom sink, room 114	9.0	µg/L
217-127-SK-38	Classroom sink, room 127	8.0	µg/L
217-117-SK-39	Classroom sink, room 117	5.0	µg/L
217-125-SK-40	Classroom sink, room 125	8.0	µg/L
217-119-SK-41	Classroom sink, room 119	8.0	µg/L
217-121-SK-42	Classroom sink, room 121	4.0	µg/L
217-123-SK-43	Classroom sink, room 123	5.0	µg/L
217-122-SK-44	Classroom sink, room 122	12.0	µg/L
217-H120-DF-45	Drinking fountain, hallway H120, across from cafeteria	<1.0*	µg/L
217-H120-DF-46	Bottle fill station, hallway H120, across from cafeteria	<1.0	µg/L

*Result less than 1.0 ppb which is the lowest level that can be reported by the lab.