

## Columbine Elementary (222) – 2540 E. 29<sup>th</sup> Ave.

*SY 2010/2020 Long Term Sampling – Action Level 10 µg/L*

*Sample Date: 02/14/2020*

Sample ID	Location Description	Lead Result (µg/L)
222-117-SK01-01	Kitchen sink, left faucet	5.4
222-117-SK02-01	Kitchen sink, center faucet	<1.0* <sup>1</sup>
222-117-SK03-01	Kitchen sink, right faucet	1.8
222-117-SK04-01	Kitchen prep sink, east wall	1.2
222-118-DF02-01	Drinking fountain, cafeteria, south wall next to kitchen	2.3
222-118-DF01-01	Drinking fountain, cafeteria, east wall	<1.0
222-116-DF01-01	Drinking fountain, gymnasium	<1.0
222-100-DF01-01	Drinking fountain, hallway 100, next to 115AA	<1.0
222-100-DF02-01	Drinking fountain, hallway 100, next to 100G	<1.0
222-110-SK01-01	Lounge sink, room 110	3.2
222-100-DF03-01	Drinking fountain, hallway 100, across from stair B	2.1
222-108-DF01-01	Drinking fountain, classroom 108	9.4
222-109-DF01-01	Drinking fountain, classroom 109	8.2
222-200-DF02-01	Drinking fountain, hallway 200, next to 200D	1.6
222-200-DF01-01	Drinking fountain, hallway 200, next to stair A	<1.0
222-213-SK01-01	Lounge sink, room 213	<1.0
222-101C-DF01-01	Nurse sink, room 101C	1.2

### Sample ID Key:

Building number – room number – fixture type count – long term bout count

1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.

## Phase I & II Sampling – Action Level 15 µg/L

**Sample ID Key:**

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

### Phase I Sampled on 9/21/2016

Sample ID	Sample Description	Lead Result	Flush Sample Result	Units	Action
222-117-sk-01	Kitchen sink, south wall, left faucet	9.9		µg/L	
222-117-SK-02	Kitchen sink, south wall, middle faucet	3.5		µg/L	
222-117-SK-03; 222-117-SK-22-FL	Kitchen sink, south wall, right faucet	16.1	4.0	µg/L	Faucet replaced 4/2018
222-118-DF-04	Drinking fountain, cafeteria, southwest wall, left bubbler	2.9		µg/L	
222-118-DF-05	Drinking fountain, cafeteria, southwest wall, right bubbler	1.3		µg/L	
222-118-DF-06	Drinking fountain, cafeteria, east wall, left bubbler	10.1		µg/L	
222-118-DF-07	Drinking fountain, cafeteria, east wall, right bubbler	2.3		µg/L	
222-116-DF-08	Drinking fountain, gym	<1.0* <sup>1</sup>		µg/L	
222-101C-SK-09	Sink, nurse office	<1.0		µg/L	
222-100-DF-10	Drinking fountain, hallway 100, across from school office, left bubbler	1.7		µg/L	
222-100-DF-11	Drinking fountain, hallway 100, across from school office, right bubbler	1.5		µg/L	
222-100-DF-12	Drinking fountain, hallway 100, across from room 102	<1.0		µg/L	
222-100-DF-13	Drinking fountain, hallway 100, next to 100B, left bubbler	2.1		µg/L	
222-100-DF-14	Drinking fountain, hallway 100, next to 100B, right bubbler	4.9		µg/L	
222-108-DF-15	Drinking fountain, room 108	9.7		µg/L	
222-108-DF-16	Drinking fountain, room 109	9.0		µg/L	
222-200-DF-17	Drinking fountain, hallway 200, next to 200C, left bubbler	2.0		µg/L	
222-200-DF-18	Drinking fountain, hallway 200, next to 200C, right bubbler	1.5		µg/L	
222-200-DF-19	Drinking fountain, hallway 200, across from room 201, left bubbler	1.5		µg/L	
222-200-DF-20	Drinking fountain, hallway 200, across from room 201, right bubbler	<1.0		µg/L	
222-213-SK-21	Sink, room 213	<1.0		µg/L	

### Phase II Sampled on 3/16/2017

222-101E-SK-23	Admin office sink, room 101E	7.0		µg/L	
222-114-SK-24	Classroom sink, room 114	<1.0		µg/L	
222-113-SK-25	Classroom sink, room 113	<1.0		µg/L	
222-112-SK-26	Classroom sink, room 112	7.0		µg/L	
222-111-SK-27	Classroom sink, room 111	3.0		µg/L	

<b>222-110-SK-28</b>	Office sink, room 110	5.0		µg/L	
<b>222-109-SK-29</b>	Classroom sink, room 109	>50.0	7.0	µg/L	Faucet replaced 1/2018
<b>222-108-SK-30</b>	Classroom sink, room 108	7.0		µg/L	
<b>222-107-SK-31</b>	Classroom sink, room 107	2.0		µg/L	
<b>222-106-SK-32</b>	Classroom sink, room 106	4.0		µg/L	
<b>222-105-SK-33</b>	Classroom sink, room 105	3.0		µg/L	
<b>222-104-SK-34</b>	Classroom sink, room 104	1.0		µg/L	
<b>222-103-SK-35</b>	Classroom sink, room 103	2.0		µg/L	
<b>222-102-SK-36</b>	Classroom sink, room 102	1.0		µg/L	
<b>222-212-SK-37</b>	Classroom sink, room 212	1.0		µg/L	
<b>222-211-SK-38</b>	Classroom sink, room 211	2.0		µg/L	
<b>222-210-SK-39</b>	Classroom sink, room 210	7.0		µg/L	
<b>222-209-SK-40</b>	Classroom sink, room 209	4.0		µg/L	
<b>222-206-SK-41</b>	Classroom sink, room 206	3.0		µg/L	
<b>222-205-SK-42</b>	Classroom sink, room 205	3.0		µg/L	
<b>222-204-SK-43</b>	Classroom sink, room 204	5.0		µg/L	
<b>222-203-SK-44</b>	Classroom sink, room 203	6.0		µg/L	
<b>222-208-SK-45</b>	Classroom sink, room 208	36.0	1.0	µg/L	Faucet replaced 1/2018

\*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.