

Force Elementary (240) – 1550 S. Wolff St.

SY 2019/2020 Long Term Sampling – Action Level 10 µg/L

Sample Date: 10/04/2019

Sample ID	Location Description	Lead Result (µg/L)	Action
240-103-SK01-01	Kitchen sink, room 103, east wall	4.0	
240-103-SK02-01	Kitchen prep sink, room 103, south wall	<1.0 ¹	
240-100-DF01-01	Drinking fountain, hallway 100, across from 106	<1.0	
240-113-DF01-01	Drinking fountain gym, northwest corner	2.8	
240-113-DF02-01	Drinking fountain, gym, south wall	1.0	
240-102-BF01-01	Bottle fill station, cafeteria, east wall	<1.0	
240-102-DF01-01	Drinking fountain, cafeteria, west wall	2.8	
240-101C-SK01-01	Nurse sink, room 101C	7.8	
240-101A-SK01-01	Sink, main office, room 101A	5.8	
240-115-BF01-01	Bottle fill station, hallway 115, main office lobby	<1.0	
240-115-DF01-01	Drinking fountain, hallway 115, lobby	2.2	
240-116-SK01-01	Sink, staff lounge, room 116	10.9	Flush notice, pending faucet replacement
240-115-BF02-01	Bottle fill station, hallway 115, across from 121	<1.0	
240-118-DF01-01	Drinking fountain, room 118	5.7	
240-119-DF01-01	Drinking fountain, room 119	8.7	
240-208-DF01-01	Drinking fountain, hallway 208, across from 217	1.9	
240-208-DF02-01	Drinking fountain, hallway 208, across from 214	2.6	
240-200-BF01-01	Bottle fill station, hallway 200, across from 202	<1.0	

Sample ID Key:

Building number – room number – fixture type count – long term count

1. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/15/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
240-100-DF-01	Drinking fountain, hallway 100, across from 106, left bubbler	1.9		µg/L	
240-100-DF-02	Drinking fountain, hallway 100, across from 106, right bubbler	2.6		µg/L	
240-103-SK-03	Kitchen prep sink, south wall	1.5		µg/L	
240-102-DF-04	Drinking fountain, cafeteria, east wall, left bubbler	14.4		µg/L	
240-102-DF-05	Drinking fountain, cafeteria, east wall, right bubbler	8.4		µg/L	
240-102-DF-06	Drinking fountain, cafeteria, west wall, left bubbler	<1.0* ¹		µg/L	
240-102-DF-07	Drinking fountain, cafeteria, west wall, right bubbler	4.4		µg/L	
240-115-DF-08	Drinking fountain, hallway 115, lobby, left bubbler	4.2		µg/L	
240-115-DF-09	Drinking fountain, hallway 115, lobby, right bubbler	8.0		µg/L	
240-101A-SK-10	Sink, main office, room 101A	6.7		µg/L	
240-115-DF-11	Drinking fountain, hallway 115, across from 124, left bubbler	3.5		µg/L	
240-115-DF-12	Drinking fountain, hallway 115, across from 124, right bubbler	4.6		µg/L	
240-115-DF-13	Drinking fountain, hallway 115, across from 121, left bubbler	6.6		µg/L	
240-115-DF-14	Drinking fountain, hallway 115, across from 121, right bubbler	4.1		µg/L	
240-208-DF-15	Drinking fountain, hallway 208, across from 217, left bubbler	7.8		µg/L	
240-208-DF-16	Drinking fountain, hallway 208, across from 217, right bubbler	2.9		µg/L	
240-218-SK-17	Sink, room 218, LMC	3.1		µg/L	
240-208-DF-18	Drinking fountain, hallway 208, across from 214, left bubbler	6.9		µg/L	
240-208-DF-19	Drinking fountain, hallway 208, across from 214, right bubbler	3.6		µg/L	
240-211-SK-20	Classroom sink, room 211	43.1	8.5	µg/L	Faucet replaced 11/2017
240-200-DF-21	Drinking fountain, hallway 200, across from 202, left bubbler	3.4		µg/L	
240-200-DF-22	Drinking fountain, hallway 200, across from 202, right bubbler	2.4		µg/L	
240-OUT-DF-23	Drinking fountain, outside, next to gym	6.6		µg/L	
240-113-DF-24	Drinking fountain gym, northwest corner	1.2		µg/L	
240-113-DF-25	Drinking fountain, gym, south wall	6.2		µg/L	
240-116-SK-26	Sink, staff lounge, room 116	3.7		µg/L	

Phase II Sampled on 3/2/2017

240-109-SK-27	Classroom sink, room 109	18.0	3.0	µg/L	Faucet replaced 11/2017
240-110-SK-28	Classroom sink, room 110	4.0		µg/L	
240-108-SK-29	Classroom sink, room 108	7.0		µg/L	
240-107-SK-31	Classroom sink, room 107	9.0		µg/L	
240-111-SK-32	Classroom sink, room 111	3.0		µg/L	
240-106-SK-33	Classroom sink, room 106	9.0		µg/L	
240-113AA-SK-34	Gymnasium office restroom, room 113AA	28.0	47.5	µg/L	Faucet replaced 11/2017, No drinking notice
240-102B-SK-35	PTA sink, room 102B	25.0	21.0 (2.0* ² Flush)	µg/L	Faucet replaced 11/2017, No drinking notice
240-101C-SK-36	Nurse sink, room 101C	8.0		µg/L	
240-124-SK-37	Classroom sink, room 124	5.0		µg/L	
240-123-SK-38	Classroom sink, room 123	5.0		µg/L	
240-122-SK-39	Classroom sink, room 122	5.0		µg/L	
240-121-SK-40	Classroom sink, room 121	4.0		µg/L	
240-120-SK-41	Classroom sink, room 120	12.0		µg/L	
240-119-SK-42	Classroom sink, room 119, right sink	2.0		µg/L	
240-118-SK-43	Classroom sink, room 118, right sink	2.0		µg/L	
240-118-SK-44	Classroom sink, room 118, left sink	2.0		µg/L	
240-118-DF-45	Drinking fountain, room 118	6.0		µg/L	
240-119-SK-46	Classroom sink, room 119, left sink	2.0		µg/L	
240-119-DF-47	Drinking fountain, room 119	9.0		µg/L	
240-117-SK-48	Classroom sink, room 117	3.0		µg/L	
240-207-SK-49	Classroom sink, room 207	9.0		µg/L	
240-206-SK-50	Staff lounge sink, room 206	5.0		µg/L	
240-205-SK-51	Classroom sink, room 205	13.0		µg/L	
240-204-SK-52	Classroom sink, room 204	6.0		µg/L	
240-203-SK-53	Classroom sink, room 203	11.0		µg/L	
240-201-SK-54	Workroom sink, room 201	35.0	23.0	µg/L	Faucet replaced 11/2017, No drinking notice
240-217-SK-55	Classroom sink, room 217	7.0		µg/L	
240-216-SK-56	Classroom sink, room 216	4.0		µg/L	
240-215-SK-57	Classroom sink, room 215	8.0		µg/L	
240-214-SK-58	Classroom sink, room 214	10.0		µg/L	
240-213-SK-59	Classroom sink, room 213	14.0		µg/L	
240-212-SK-60	Classroom sink, room 212	14.0		µg/L	
240-209-SK-61	Classroom sink, room 209	5.0		µg/L	
240-202-SK-62	Classroom sink, room 202	8.0		µg/L	
240-210-SK-63	Classroom sink, room 210	18.0	11.0	µg/L	Faucet replaced 11/2017

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.

*2. Follow-up samples field tested with a Palintest SA1100 scanning analyzer.