

Gilpin Elementary (242) – 2949 California St.

Long Term Sampling – Action Level 10 µg/L

Sample Date: 01/10/2020

Sample ID	Location Description	Lead Result (µg/L)	Action
242-004-SK01-01	Kitchen sink, east wall, room 004, left faucet	3.3	
242-004-SK02-01	Kitchen sink, east wall, room 004, right faucet	2.6	
242-001-DF01-01	Drinking fountain, cafeteria	30.7	Shut down, POU filter install pending
242-003-DF01-01	Drinking fountain, gym, left fountain	<1.0 ¹	
242-003-DF02-01	Drinking fountain, gym, right fountain	<1.0	
242-101-DF01-01	Drinking fountain, hallway 101, next to room 114	7.5	
242-121-BF01-01	Bottle fill, hallway 121, next to lobby	<1.0	
242-124B-SK01-01	Lounge sink, room 124B	2.4	
242-119-DF01-01	Drinking fountain, hallway 119, next to 119A	1.4	
242-118AA-SK01-01	Nurse restroom sink, room 118AA	3.3	
242-101-DF02-01	Drinking fountain, hallway 101, next to room 108	15.2	Shut down, POU filter install pending
242-106-DF01-01	Drinking fountain, room 106	11.4	Shut down, POU filter install pending
242-105-DF01-01	Drinking fountain, room 105	36.3	Shut down, POU filter install pending
242-201-DF02-01	Drinking fountain, hallway H220, next to room 210	1.2	
242-223-BF01-01	Bottle fill, hallway 223, next to 223A	6.5	

Sample ID Key:

Building number – room number – fixture type count – long term bout count

1. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/7/16					
Sample ID* ¹	Sample Description* ¹	Lead Result	Follow Up Result	Units	Action
242-003-DF-01	Drinking fountain, gym, left bubbler	<1.0* ²		µg/L	
242-003-DF-02	Drinking fountain, gym, right bubbler	<1.0		µg/L	
242-001-DF-03	Drinking fountain, cafeteria, left bubbler	7.0		µg/L	
242-001-DF-04	Drinking fountain, cafeteria, right bubbler	4.8		µg/L	
242-101-DF-05	Drinking fountain, hallway 101, next to room 114	2.2		µg/L	
242-101-DF-06	Drinking fountain, hallway 101, next to room 108	4.6		µg/L	
242-107-DF-07	Drinking fountain, room 107, left bubbler	7.4		µg/L	
242-107-DF-08	Drinking fountain, room 107, right bubbler	4.9		µg/L	
242-106-DF-09	Drinking fountain, room 106, left bubbler	6.3		µg/L	
242-106-DF-10	Drinking fountain, room 106, right bubbler	7.0		µg/L	
242-105-DF-11	Drinking fountain, room 105, left bubbler	6.8		µg/L	
242-105-DF-12	Drinking fountain, room 105, right bubbler	3.4		µg/L	
242-201-DF-13	Drinking fountain, hallway H220, next to room 210	4.7		µg/L	
242-201-DF-14	Drinking fountain, hallway 201, next to room 215	2.0		µg/L	
242-223-DF-15	Drinking fountain, hallway 223, next to 223A	20.4	<1.0	µg/L	Bottle fill install 11/2017
242-119-DF-16	Drinking fountain, hallway 119, next to 119A	1.6		µg/L	
242-004-SK-17	Kitchen sink, east wall, room 004	5.5		µg/L	
Phase II Sampled on 2/16/17					
242-105-SK-17	Classroom sink, room 105	12.0		µg/L	
242-106-SK-18	Classroom sink, room 106	6.0		µg/L	
242-107-SK-19	Classroom sink, room 107	3.3		µg/L	
242-104-SK-20	Classroom sink, room 104	5.1		µg/L	
242-103-SK-21	Classroom sink, room 103	>50.0	5.0	µg/L	Faucet replaced 11/2017
242-102-SK-22	Staff community sink, room 102	1.9		µg/L	
242-109-SK-23	Classroom sink, room 109A	40.0	4.0	µg/L	Faucet replaced 11/2017
242-108-SK-24	Classroom sink, room 108	16.0	6.0	µg/L	Faucet replaced 11/2017
242-111-SK-25	Classroom sink, room 111	17.0	10.0	µg/L	Faucet replaced 11/2017
242-112-SK-26	Classroom sink, room 112	8.3		µg/L	

242-114-SK-27	Classroom sink, room 114	12.0		µg/L	
242-115-SK-28	Classroom sink, room 115	11.0		µg/L	
242-116-SK-29	Classroom sink, room 116	11.0		µg/L	
242-121-DF-30	Drinking fountain, hallway 121, next to lobby, right bubbler	11.0		µg/L	
242-121-DF-31	Drinking fountain, hallway 121, next to lobby, left bubbler	17.0	<1.0	µg/L	Bottle fill install 2017
242-123B-SK-32	Workroom sink, room 123B	15.0	10.0	µg/L	Faucet replaced 11/2017
242-226A-SK-33	LMC/IMC office sink, room 226A	6.7		µg/L	
242-224-SK-34	Classroom sink, room 224	13.0		µg/L	
242-222-SK-35	Classroom sink, room 222	9.1		µg/L	
242-221B-SK-36	Admin office sink, room 221B	17.0	6.0	µg/L	Faucet replaced 7/2018
242-220-SK-37	Classroom sink, room 220	2.3		µg/L	
242-219-SK-38	Classroom sink, room 219	2.8		µg/L	
242-218-SK-39	Classroom sink, room 218	4.5		µg/L	
242-217-SK-40	Classroom sink, room 217	5.4		µg/L	
242-215-SK-41	Classroom sink, room 215	>50.0	10.0	µg/L	Faucet replaced 11/2017
242-214-SK-42	Classroom sink, room 214	4.2		µg/L	
242-213-SK-43	Classroom sink, room 213	6.8		µg/L	
242-211-SK-44	Classroom sink, room 211	3.3		µg/L	
242-210-SK-45	Classroom sink, room 210	4.0		µg/L	
242-209-SK-46	Classroom sink, room 209	13.0		µg/L	
242-208-SK-47	Classroom sink, room 208	17.0	13.0	µg/L	Faucet replaced 11/2017
242-207-SK-48	Classroom sink, room 207	2.5		µg/L	
242-204-SK-49	Classroom sink, room 204	2.8		µg/L	
242-203-SK-50	Classroom sink, room 203	8.2		µg/L	
242-202-SK-51	Classroom sink, room 202	>50.0	5.0	µg/L	Faucet replaced 11/2017

*1. Rooms were renumbered between the time of sampling and the receipt of results. Sample ID's and descriptions have been edited to match the current floor plan.

*2. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.