

Schmitt Elementary (271) – 1820 S. Vallejo St.

Sample ID	Description	Post Mitigation Lead Result (µg/L)	Action
271-103B-SK01-01	Sink, PTA kitchen, room 103B	1.7 (flush)	Flush Notice, faucet previously replaced
271-105-DF02-01	Drinking fountain, gymnasium, west wall	3.2	POU filter installed 10/2019
271-H100-DF01-01	Drinking fountain, hallway H100, across from room 122	Pending	POU filter installed 1/2020
271-110-DF01-01	Drinking fountain, room 110	Pending	POU filter installed 10/2019
271-210A-SK01-01	Lounge sink, room 210A	3.0 (flush)	Flush notice, faucet previously replaced

Schmitt Elementary (271) – 1820 S. Vallejo St.

SY 2019/2020 Long Term Sampling – Action Level 10 µg/L
Sample Date: 09/13/2020

Sample ID	Description	Lead Result (µg/L)	Action
271-104-SK03-01	Kitchen sink, south wall, left faucet	2.4	
271-104-SK01-01	Kitchen sink, east wall, left faucet	6.2	
271-104-SK02-01	Kitchen sink, east wall, right faucet	3.7	
271-103-BF01-01	Bottle fill station, cafeteria, east wall	<1.0* ¹	
271-103-DF01-01	Drinking fountain, cafeteria, west wall	<1.0	
271-103B-SK01-01	Sink, PTA kitchen, room 103B	37.7	Flush notice, faucet previously replaced
271-105-DF01-01	Drinking fountain, gymnasium, south wall	2.8	
271-105-DF02-01	Drinking fountain, gymnasium, west wall	16.4	Shut down, POU filter to be installed
271-101C-SK01-01	Sink, nurse office, room 101C	8.2	
271-101A-SK01-01	Sink, room 101A	2.9	
271-H100A-BF01-01	Bottle fill station, lobby H100A	<1.0	
271-H100-DF01-01	Drinking fountain, hallway H100, across from room 122	19.7	Shut down, POU filter to be installed
271-H100-DF02-01	Drinking fountain, hallway H100, next to room 110	6.6	
271-110-DF01-01	Drinking fountain, room 110	15.6	Shut down, POU filter to be installed
271-111-DF01-01	Drinking fountain, room 111	5.7	
271-H100-DF03-01	Drinking fountain, hallway H100, next to room 113	4.4	
271-H200-DF02-01	Drinking fountain, hallway H200, next to room 204	1.8	
271-H200-DF01-01	Drinking fountain, hallway H200, next to room 201	8.8	
271-210A-SK01-01	Lounge sink, room 210A	22.6	Flush notice, faucet previously replaced

Sample ID Key:

Building number – room number – fixture type count – long term count

1. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L Lead**Sample ID Key:**

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled On 9/20/2016

Sample ID* ¹	Sample Description* ¹	Lead Result	Follow Up Result	Units	Action
271-001-SK-01	Sink, room 001	10.4		µg/L	
271-Playground-DF-02	Drinking fountain, outside, playground by gym	3.8		µg/L	
271-104-SK-03	Kitchen sink, south wall, left faucet	1.9		µg/L	
271-104-SK-04	Kitchen sink, south wall, right faucet	<1.0* ²		µg/L	
271-104-SK-05	Kitchen sink, east wall, left faucet	5.6		µg/L	
271-104-SK-06	Kitchen sink, east wall, right faucet	8.6		µg/L	
271-105-DF-07	Drinking fountain, gymnasium, south wall	3.2		µg/L	
271-105-DF-08	Drinking fountain, gymnasium, west wall	10.7		µg/L	
271-103-DF-09	Drinking fountain, cafeteria, east wall, right bubbler	3.8		µg/L	
271-103-DF-10	Drinking fountain, cafeteria, east wall, left bubbler	22.9	<0.1	µg/L	New bottle fill install 11/2017
271-103B-SK-11; 271-103B-33-FL	Sink, PTA kitchen, room 103B	26.5	14	µg/L	Faucet replaced 12/2017
271-103-DF-12	Drinking fountain, cafeteria, west wall, left bubbler	20.6	<1.0	µg/L	Bubblers replaced 11/2017, Filter install 7/2019
271-103-DF-13	Drinking fountain, cafeteria, west wall, right bubbler	10.5		µg/L	
271-101A-SK-14	Sink, room 101A	3.3		µg/L	
271-101C-SK-15	Sink, nurse office, room 101C	8.5		µg/L	
271-H100-DF-16	Drinking fountain, hallway H100, next to room 113, left bubbler	3.0		µg/L	
271-H100-DF-17	Drinking fountain, hallway H100, next to room 113, right bubbler	5.2		µg/L	
271-112-SK-18	Lounge sink, room 112	6.1		µg/L	
271-111-SK-19	Classroom sink, room 111	41.4	21.0	µg/L	Replaced 11/2017; Failed follow up - No drinking notice
271-111-DF-20	Drinking fountain, room 111	14.7		µg/L	
271-110-DF-21	Drinking fountain, room 110	12.1		µg/L	
271-110-SK-22	Classroom sink, room 110	<1.0		µg/L	

271-H100-DF-23	Drinking fountain, hallway H100, across from room 122	7.9		µg/L	
271-210A-SK-24; 271-210A-34-RT	Lounge sink, room 210A	23.6	11.0	µg/L	Faucet replaced 11/10/16
271-H200-DF-25	Drinking fountain, hallway H200, next to room 201, left bubbler	6.9		µg/L	
271-H200-DF-26	Drinking fountain, hallway H200, next to room 201, right bubbler	4.5		µg/L	
271-H200-DF-27	Drinking fountain, hallway H200, next to room 204, left bubbler	13.1		µg/L	
271-H200-DF-28	Drinking fountain, hallway H200, next to room 204, right bubbler	5.8		µg/L	
271-H100-DF-29	Drinking fountain, hallway H100, next to room 110, left bubbler	5.6		µg/L	
271-H100-DF-30	Drinking fountain, hallway H100, next to room 110, right bubbler	7.9		µg/L	
271-H100A-DF-31	Drinking fountain, lobby 100A, left bubbler	16.0	<0.1	µg/L	New bottle fill install 11/2017
271-H100A-DF-32	Drinking fountain, lobby 100A, right bubbler	5.2		µg/L	
Phase II Sampled On 3/10/2017					
271-122-SK-33	Classroom sink, room 122	20.0	15.0	µg/L	Replaced 11/2017; Failed follow up - No drinking notice
271-121-SK-34	Classroom sink, room 121	11.0		µg/L	
271-120-SK-36	Classroom sink, room 120	5.0		µg/L	
271-119-SK-37	Classroom sink, room 119	8.0		µg/L	
271-118-SK-38	Classroom sink, room 118	11.0		µg/L	
271-116-SK-39	Classroom sink, room 116	7.0		µg/L	
271-115-SK-40	Classroom sink, room 115	5.0		µg/L	
271-114-SK-41	Classroom sink, room 114	5.0		µg/L	
271-113-SK-42	Classroom sink, room 113	3.0		µg/L	
271-111-SK-43	Classroom sink, room 111, left sink	10.0		µg/L	
271-111-SK-44	Classroom sink, room 111, right sink	31.0	21.0	µg/L	Replaced 11/2017; Failed follow up - No drinking notice
271-110-SK-45	Classroom sink, room 110, left sink	8.0		µg/L	
271-110-SK-46	Classroom sink, room 110, right sink	8.0		µg/L	
271-109-SK-47	Classroom sink, room 109	8.0		µg/L	
271-209-SK-48	Classroom sink, room 209	18.0	3.0	µg/L	Faucet replaced 11/2017
271-208-SK-49	Classroom sink, room 208	22.0	13.0	µg/L	Faucet replaced 11/2017
271-207-SK-50	Classroom sink, room 207	11.0		µg/L	
271-206-SK-51	Classroom sink, room 206	16.0	39.0	µg/L	Replaced 11/2017; Failed follow up - No drinking notice
271-205-SK-52	Classroom sink, room 205	15.0	12.5	µg/L	Faucet replaced 11/2017
271-204-SK-53	Classroom sink, room 204	23.0	16.0	µg/L	Replaced 11/2017; Failed follow up - No drinking notice

271-203-SK-54	Classroom sink, room 203	14.0	µg/L
271-202-SK-55	Classroom sink, room 202	4.0	µg/L
271-201-SK-56	Classroom sink, room 201	7.0	µg/L

*1. Room renumbering occurred between phases I and II, phase I sample ID's and location descriptions have been updated to match current floor plan.

*2. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.