

Hilltop Service Center (891) – Sampled 11/11/2016

All results <15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Sample ID	Sample Description	Lead Result	Units	Action
891-101-SK-01	Admin office sink, room 101, north wall next to room 101C	1.0	µg/L	
891-100-DF-02	Drinking fountain, hallway 100, next to shop 117	<1.0*	µg/L	
891-117-SK-03	Break area sink, shop 117	4.0	µg/L	
891-116C-SK-04	Break area sink, shop room 116C	1.0	µg/L	
891-118-DF-05	Bottle fill, hallway 118, across from shop 111	<1.0	µg/L	
891-118-DF-06	Drinking fountain, hallway 118, across from shop 111	<1.0	µg/L	
891-114-SK-07	Break area sink, shop 114	<1.0	µg/L	
891-113-SK-08	Break area sink, shop 113	4.0	µg/L	
891-111-SK-09	Break area sink, shop 111	4.0	µg/L	
891-115-SK-10	Food prep sink, Hilltop café room 115	1.0	µg/L	
891-109-SK-11	Break area sink, shop 109	<1.0	µg/L	
891-109-DF-12	Drinking fountain, shop 109	3.0	µg/L	
891-110-SK-13	Break area sink, shop 110	<1.0	µg/L	
891-105-SK-14	Break area sink, shop 105	2.0	µg/L	
891-103-SK-15	Break area sink, shop 103	2.0	µg/L	
891-001-DF-16	Drinking fountain, warehouse 001, next to office 002A	3.0	µg/L	
891-001-DF-17	Bottle fill, warehouse 001, next to office 002A	2.0	µg/L	
891A-H110-DF-18	Hilltop training center, drinking fountain, hallway H110	<1.0	µg/L	
891A-H120A-SK-19	Hilltop training center, break room sink, room H120A	11.0	µg/L	

*Result less than 1.0 ppb which is the lowest level that can be reported by the lab.