

Morey Middle School (413)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Sample ID	Sample Description	Lead Result	Follow Up Sample Result	Units	Action
Phase I Sampled on 10/19/2016					
413-H100-DF-01	Drinking fountain, hallway H001, across from room 003	<1.0*		µg/L	
413-005-DF-02	Drinking fountain, boys locker room 005	<1.0		µg/L	
413-H006-DF-03	Drinking fountain, hallway H006, next to girls locker room and pool entrance	<1.0		µg/L	
413-013-SK-04	Sink, custodial office, room 013	1.5		µg/L	
413-H164-DF-05	Drinking fountain, hallway H164, next to main office, left bubbler	<1.0		µg/L	
413-H164-DF-06	Drinking fountain, hallway H164, next to main office, right bubbler	<1.0		µg/L	
413-138B-SK-07	Staff lounge sink, room 138B	2.8		µg/L	
413-141A-SK-08	Nurse sink, room 141A	16.1	8.0	µg/L	Faucet replaced 4/9/2018
413-H169-DF-09	Drinking fountain, hallway H169, across from room 122, left bubbler	1.2		µg/L	
413-H169-DF-10	Drinking fountain, hallway H169, across from room 122, right bubbler	<1.0		µg/L	
413-H169-DF-11	Drinking fountain, hallway H169, across from room 118	<1.0		µg/L	
413-107-DF-12	Drinking fountain, cafeteria, west wall	1.4		µg/L	
413-107-DF-13	Drinking fountain, cafeteria, east wall	11.3		µg/L	
413-107B-SK-14	Kitchen prep sink, room 107B, south wall	3.5		µg/L	
413-107B-SK-15	Kitchen prep sprayer, room 107B, south wall	1.6		µg/L	
413-107B-SK-16	Kitchen kettle fill, room 107B, south wall	10.7		µg/L	
413-H168-DF-17	Drinking fountain, hallway H168, across from room 114, left bubbler	3.8		µg/L	
413-H168-DF-18	Drinking fountain, hallway H168, across from room 114, right bubbler	5.7		µg/L	
413-110-SK-19	Staff lounge sink, room 110	<1.0		µg/L	
413-H165-DF-20	Drinking fountain, hallway H165, across from room 108, left bubbler	<1.0		µg/L	
413-H165-DF-21	Drinking fountain, hallway H165, across from room 108, right bubbler	<1.0		µg/L	
413-H164-DF-22	Drinking fountain, hallway H164, across from room 105	<1.0		µg/L	
413-H240-DF-23	Drinking fountain, hallway H240, across from room 204	1.2		µg/L	
413-H239-DF-24	Drinking fountain, hallway H239, across from room 208, left bubbler	<1.0		µg/L	

413-H239-DF-25	Drinking fountain, hallway H239, across from room 208, right bubbler	<1.0		µg/L	
413-H242-DF-26	Drinking fountain, hallway H242, across from room 215, left bubbler	3.2		µg/L	
413-H242-DF-27	Drinking fountain, hallway H242, across from room 215, right bubbler	3.2		µg/L	
413-H243-DF-28	Drinking fountain, hallway H243, across from room H243	<1.0		µg/L	
Phase II Sampled on 9/13/2017					
413-017-SK-29	Office sink, room 017	1.0		µg/L	
413-124-SK-30	Faculty workroom sink, room 124	24.0	9.0	µg/L	Faucet replaced 4/9/2018
413-126-SK-31	Faculty lounge sink, room 126	9.0		µg/L	
413-117C-SK-32	Office storage, room 117C	19.0	9.0	µg/L	Faucet replaced 4/9/2018
413-113-SK-33	Classroom sink, room 133, left faucet	>50.0	3.0	µg/L	Faucet replaced 4/9/2018
413-113-SK-34	Classroom sink, room 133, right faucet	3.0		µg/L	
413-112-SK-35	Classroom sink, room 112	12.0		µg/L	
413-111-SK-36	Classroom sink, room 111, left faucet	16.0	4.0	µg/L	Faucet replaced 4/9/2018
413-111-SK-37	Classroom sink, room 111, right faucet	23.0	3.0	µg/L	Faucet replaced 4/9/2018
413-208A-SK-38	Prep room sink, room 208A	2.0		µg/L	
413-211-SK-39	Classroom sink, room 211	16.0	9.0	µg/L	Faucet replaced 4/9/2018

*Result less than 1.0 ppb which is the lowest level that can be reported by the lab.