

Emily Griffith Technical College (1001) – Sampled 11/3/2016

All results <15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Sample ID	Sample Description	Lead Result	Units	Action
1001-203-SK-01	Lounge sink, room 203, south wall	0.1	µg/L	
1001-203-DF-02	Bottle fill, room 203, east wall	<0.1*	µg/L	
1001-203-DF-03	Drinking fountain, room 203, east wall, left bubbler	<0.1	µg/L	
1001-203-DF-04	Drinking fountain, room 203, east wall, right bubbler	<0.1	µg/L	
1001-208CA-SK-05	Sink, resource room 208CA, south wall	1.5	µg/L	
1001-213-DF-06	Drinking fountain, shop 213, left bubbler	<0.1	µg/L	
1001-213-DF-07	Drinking fountain, shop 213, right bubbler	<0.1	µg/L	
1001-209-DF-08	Drinking fountain, hallway 209, across from 214, left bubbler	<0.1	µg/L	
1001-209-DF-09	Drinking fountain, hallway 209, across from 214, right bubbler	<0.1	µg/L	
1001-103C-DF-10	Drinking fountain, welding shop 103C, left bubbler	<0.1	µg/L	
1001-103C-DF-11	Drinking fountain, welding shop 103C, right bubbler	0.1	µg/L	
1001-104-DF-12	Drinking fountain, hallway 104, left bubbler	<0.1	µg/L	
1001-104-DF-13	Drinking fountain, hallway 104, right bubbler	<0.1	µg/L	
1001-110-DF-14	Drinking fountain, collision shop 110, left bubbler	<0.1	µg/L	
1001-110-DF-15	Drinking fountain, collision shop 110, right bubbler	<0.1	µg/L	
1001-109-DF-16	Drinking fountain, auto tech shop 109, left bubbler	<0.1	µg/L	
1001-109-DF-17	Drinking fountain, auto tech shop 109, right bubbler	<0.1	µg/L	

*Result less than 0.1 ppb which is the lowest level that can be reported by the lab.