

Clayton Early Learning @ Evie Dennis Campus Bldg. #5 (160)

All results <15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 10/12-13/2016				
Sample ID	Sample Description	Lead Result	Units	Action
160-152-SK-01	Staff lounge sink, room 152	0.3	µg/L	
160-170-DF-02	Drinking fountain, hallway 170, next to restrooms, left bubbler	0.2	µg/L	
160-170-DF-03	Drinking fountain, hallway 170, next to restrooms, right bubbler	0.3	µg/L	
160-183-DF-04	Drinking fountain, in first floor lobby, across from elevator, left bubbler	<0.1* ¹	µg/L	
160-183-DF-05	Drinking fountain, in first floor lobby, across from elevator, right bubbler	0.3	µg/L	
160-106-SK-06	Staff lounge sink, room 106	0.7	µg/L	
160-107-SK-07	Nurse sink, room 107	3.0	µg/L	
160-138-DF-08	Drinking fountain, next to stairs 5-1S2, across from room 138, left bubbler	0.2	µg/L	
160-138-DF-09	Drinking fountain, next to stairs 5-1S2, across from room 138, right bubbler	0.3	µg/L	
160-139-SK-10	Kitchen prep sink, room 139, center wall	0.7	µg/L	
160-139-SK-11	Kitchen sink, room 139, south wall, left faucet	1.1	µg/L	
160-117-BF-12	Bottle fill, room 117, west wall	<1.0* ²	µg/L	
160-121-BF-13	Bottle fill, room 121, east wall	<1.0	µg/L	
160-122-BF-14	Bottle fill, room 122, west wall	<1.0	µg/L	
160-126-BF-15	Bottle fill, room 126, east wall	<1.0	µg/L	
160-127-BF-16	Bottle fill, room 127, east wall	<1.0	µg/L	
160-131-BF-17	Bottle fill, room 131, west wall	<1.0	µg/L	
160-132-SK-18	Sink, room 132	<1.0	µg/L	
160-241-DF-19	Drinking fountain, lobby 241, southeast wall, left bubbler	<1.0	µg/L	
160-241-DF-20	Drinking fountain, lobby 241, southeast wall, right bubbler	<1.0	µg/L	
160-240-SK-21	Staff workroom sink, room 240	<1.0	µg/L	
160-208-SK-22	Admin office sink, room 208	<1.0	µg/L	
160-212-SK-23	Nurse sink, room 212	<1.0	µg/L	
160-213-SK-24	Staff workroom sink, room 213	<1.0	µg/L	
160-242-DF-25	Drinking fountain, hallway 242, next to restrooms, left bubbler	<1.0	µg/L	
160-242-DF-26	Drinking fountain, hallway 242, next to restrooms, right bubbler	<1.0	µg/L	
160-230-SK-27	Staff workroom sink, room 230	<1.0	µg/L	
160-242-DF-28	Drinking fountain, hallway 242, next to room 222, left bubbler	<1.0	µg/L	
160-242-DF-29	Drinking fountain, hallway 242, next to room 222, right bubbler	<1.0	µg/L	
Phase II Sampled on 5/11-12/2017				
160-126-SK-30	Classroom sink, room 126, south wall	<1.0	µg/L	
160-122-SK-31	Classroom sink, room 122, south wall	<1.0	µg/L	
160-127-SK-32	Classroom sink, room 127, north wall, left sink	<1.0	µg/L	

160-131-SK-33	Classroom sink, room 131, west wall	<1.0	µg/L
160-121-SK-34	Classroom sink, room 121, south wall	<1.0	µg/L
160-132-SK-35	Classroom sink, room 132, east wall, left sink	<1.0	µg/L
160-132-SK-36	Classroom sink, room 132, east wall, right sink	<1.0	µg/L
160-132-SK-37	Classroom sink, room 132, southeast corner	<1.0	µg/L
160-117-SK-38	Classroom sink, room 117, south wall	<1.0	µg/L
160-116-SK-39	Classroom sink, room 116, left sink	<1.0	µg/L
160-116-SK-40	Classroom sink, room 116, right sink	<1.0	µg/L
160-127-SK-41	Classroom sink, room 127, counter sink, on right	<1.0	µg/L
160-127-SK-42	Classroom sink, room 127, hand sink next to restrooms, on left	<1.0	µg/L
160-127-SK-43	Classroom sink, room 127, hand sink next to restrooms, on right	<1.0	µg/L
160-126-SK-44	Classroom sink, room 126, hand sink next to restrooms, on right	<1.0	µg/L
160-122-SK-45	Classroom sink, room 122, hand sink next to restrooms, on left	<1.0	µg/L
160-131-SK-46	Classroom sink, room 131, hand sink next to restrooms, on left	<1.0	µg/L
160-131-SK-47	Classroom sink, room 131, hand sink next to restrooms, on right	<1.0	µg/L
160-131-SK-48	Classroom sink, room 131, upper counter, hand sink	<1.0	µg/L
160-131-SK-49	Classroom sink, room 131, hand sink, south wall between rooms 127 and 131	<1.0	µg/L
160-126-SK-50	Classroom sink, room 126, hand sink next to restrooms, on left	<1.0	µg/L
160-122-SK-51	Classroom sink, room 122, hand sink next to restrooms, on right	<1.0	µg/L
160-121-SK-52	Classroom sink, room 121, hand sink next to restrooms, on left	<1.0	µg/L
160-121-SK-53	Classroom sink, room 121, hand sink next to restrooms, on right	<1.0	µg/L
160-117-SK-54	Classroom sink, room 117, hand sink next to restrooms, on left	<1.0	µg/L
160-117-SK-55	Classroom sink, room 117, hand sink next to restrooms, on right	<1.0	µg/L

*1. Result less than 0.1 ppb which is the lowest level that can be reported by the external lab.

*2. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.