

Lowry Elementary (210)

All results <15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/29/2016

Sample ID	Sample Description	Lead Result	Units	Action
210-124A-SK-01	Kitchen prep sink, west wall	<1.0* ¹	µg/L	
210-124A-SK-02	Kitchen kettle fill	<1.0	µg/L	
210-100-DF-03	Drinking fountain, hallway 100, across from cafeteria, left bubbler	<1.0	µg/L	
210-100-DF-04	Drinking fountain, hallway 100, across from cafeteria, right bubbler	<1.0	µg/L	
210-125-DF-05	Drinking fountain, gymnasium, southwest corner	<1.0	µg/L	
210-116-DF-06	Drinking fountain, room 116	<1.0	µg/L	
210-115-DF-07	Drinking fountain, room 115	<1.0	µg/L	
210-11-DF-08	Drinking fountain, hallway 111, across from room 113, left bubbler	<1.0	µg/L	
210-111-DF-09	Drinking fountain, hallway 111, across from room 113, right bubbler	<1.0	µg/L	
210-112-DF-10	Drinking fountain, room 112	<1.0	µg/L	
210-108-DF-11	Drinking fountain, room 108	<1.0	µg/L	
210-108-SK-12	Classroom sink, room 108, tall counter	<1.0	µg/L	
210-107-DF-13	Drinking fountain, room 107	<1.0	µg/L	
210-107-SK-14	Classroom sink, room 107, tall counter	<1.0	µg/L	
210-103-SK-15	Drinking fountain, hallway 103, across from room 105, left bubbler	<1.0	µg/L	
210-103-DF-16	Drinking fountain, hallway 103, across from room 105, right bubbler	<1.0	µg/L	
210-101E-SK-17	Staff lounge sink, room 101D	<1.0	µg/L	
210-101F-SK-18	Nurse sink, room 101F	<1.0	µg/L	
210-127-DF-19	Drinking fountain, hallway 127, across from room 146, left bubbler (right side INOP)	<1.0	µg/L	
210-136-DF-20	Drinking fountain, hallway 136, across from room 140, left bubbler	<1.0	µg/L	
210-136-DF-21	Drinking fountain, hallway 136, across from room 140, right bubbler	<1.0	µg/L	
210-128-DF-22	Drinking fountain, hallway 128, across from room 132, left bubbler	<1.0	µg/L	
210-128-DF-23	Drinking fountain, hallway 128, across from room 132, right bubbler	<1.0	µg/L	
210-120-SK-24	Classroom sink, room 120	<1.0	µg/L	

Phase II Sampled on 4/26/2017

210-115-SK-25	Classroom sink, room 115, counter	<1.0	µg/L	
210-115-SK-26	Classroom sink, room 115, wall mounted next to drinking fountain	<1.0	µg/L	
210-111G-SK-27	Faculty workroom sink, room 111G	<1.0	µg/L	
210-116-SK-28	Classroom sink, room 116, next to drinking fountain	<1.0	µg/L	
210-116-SK-29	Classroom sink, room 116, counter	<1.0	µg/L	
210-117-SK-30	Classroom sink, room 117	<1.0	µg/L	

210-118-SK-31	Classroom sink, room 118	<1.0	µg/L
210-119-SK-32	Classroom sink, room 119	<1.0	µg/L
210-114-SK-33	Classroom sink room 114	<1.0	µg/L
210-113-SK-34	Classroom sink, room 113	<1.0	µg/L
210-112-SK-35	Classroom sink, room 112, sink on left	<1.0	µg/L
210-112-SK-36	Classroom sink, room 112, sink on right, lower counter	<1.0	µg/L
210-103C-SK-37	Faculty workroom sink, room 103C	2.0	µg/L
210-108-SK-38	Classroom sink, room 108, lower counter, sink on left	<1.0	µg/L
210-107-SK-39	Classroom sink, room 107, lower counter, sink on right	<1.0	µg/L
210-106-SK-40	Classroom sink, room 106	<1.0	µg/L
210-105-SK-41	Classroom sink, room 105	<1.0	µg/L
210-104-SK-42	Classroom sink, room 104	<1.0	µg/L
210-126B-SK-43	Faculty workroom sink, room 126B	<1.0	µg/L
210-148-SK-44	Classroom sink, room 148	<1.0	µg/L
210-147-SK-45	Classroom sink, room 147	<1.0	µg/L
210-136B-SK-46	Classroom sink, room 136B	<1.0	µg/L
210-146-SK-47	Classroom sink, room 146	<1.0	µg/L
210-145-SK-48	Classroom sink, room 145	<1.0	µg/L
210-144-SK-49	Classroom sink, room 144	<1.0	µg/L
210-136E-SK-50	Faculty workroom sink, room 136E	<1.0	µg/L
210-143-SK-51	Classroom sink, room 143	<1.0	µg/L
210-142-SK-52	Classroom sink, room 142	<1.0	µg/L
210-141-SK-53	Classroom sink, room 141	<1.0	µg/L
210-140-SK-54	Classroom sink, room 140	<1.0	µg/L
210-139-SK-55	Classroom sink, room 139	<1.0	µg/L
210-138-SK-56	Classroom sink, room 138	<1.0	µg/L
210-137-SK-57	Classroom sink, room 137	<1.0	µg/L
210-128C-SK-58	Faculty workroom sink, room 128C	<1.0	µg/L
210-133-SK-59	Classroom sink, room 133	<1.0	µg/L
210-132-SK-60	Classroom sink, room 132	<1.0	µg/L
210-131-SK-61	Classroom sink, room 131, south wall, left sink	<1.0	µg/L
210-131-SK-62	Classroom sink, room 131, south wall, center sink	<1.0	µg/L
210-131-SK-63	Classroom sink, room 131, south wall, right sink	<1.0	µg/L
210-130-SK-64	Classroom sink, room 130	<1.0	µg/L
210-129-SK-65	Classroom sink, room 129, drinking fountain/sink combo	2.0	µg/L
210-129-DF-66	Drinking fountain, room 129, drinking fountain/sink combo	1.0	µg/L

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.