

Cory Elementary (223) – 1550 S. Steele St.

Long Term Sampling – Action Level 10 µg/L

Sample Date: 11/06/2019

Sample ID	Location Description	Lead Result (µg/L)	Action
223-002-DF01-01	Drinking fountain, hallway 002, across from room 003	<1.0* ¹	
223-102-BF01-01	Bottle fill station, cafeteria	<1.0	
223-100-DF01-01	Drinking fountain, hallway 100, next to 101A	<1.0	
223-101C-SK01-01	Sink, office 101C	2.8	
223-100-BF01-01	Bottle fill station, hallway 100, next to 107B	<1.0	
223-108-DF01-01	Drinking fountain, room 108	12.7	Shut down, POU Filter installed 2/2020
223-109-DF01-01	Drinking fountain, room 109	13.6	Shut down, POU Filter installed 2/2020
223-110-BF01-01	Bottle fill station, hallway 110, next to room 111	<1.0	
223-110-DF01-01	Drinking fountain, hallway 110, next to room 115	<1.0	
223-200-BF01-01	Drinking fountain, hallway 200, across from room 211	<1.0	
223-207-SK01-01	Lounge sink, room 207	5.1	
223-200-DF01-01	Drinking fountain, hallway 200, across from room 205	<1.0	
223-103-SK01-01	Kitchen sink, left faucet	6.7	
223-103-SK02-01	Kitchen sink, center faucet	2.6	
223-103-SK03-01	Kitchen sink, right faucet	1.5	

Sample ID Key:

Building number – room number – fixture type count – long term bout count

1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

July 2017: All issues addressed, results below action level, no further actions at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/1/2016					
Sample ID	Sample Description	Lead Result	Follow Up Results	Units	Action
223-002-df-01	Drinking fountain, hallway 002, across from room 003	6.1		µg/L	
223-102-df-02	Drinking fountain, cafeteria, left bubbler	16.9	<2.0* ¹	µg/L	Fountain replaced July 2017
223-102-df-03	Drinking fountain, cafeteria, right bubbler	13.1	<2.0* ¹	µg/L	Fountain replaced July 2017
223-100-df-04	Drinking fountain, hallway 100, next to 101A, left bubbler	4.7		µg/L	
223-100-df-05	Drinking fountain, hallway 100, next to 101A, right bubbler	3.0		µg/L	
223-101a-sk-06	Sink, office 101A	3.0		µg/L	
223-100-df-07	Drinking fountain, hallway 100, next to 107B, left bubbler	11.5		µg/L	
223-100-df-08	Drinking fountain, hallway 100, next to 107B, right bubbler	3.6		µg/L	
223-108-df-09	Drinking fountain, room 108, left bubbler	8.2		µg/L	
223-108-df-10	Drinking fountain, room 108, right bubbler	2.7		µg/L	
223-109-df-11	Drinking fountain, room 109, left bubbler	9.0		µg/L	
223-110-df-13	Drinking fountain, hallway 110, next to room 111, left bubbler	1.9		µg/L	
223-110-df-14	Drinking fountain, hallway 110, next to room 111, right bubbler	4.2		µg/L	
223-110-df-16	Drinking fountain, hallway 110, next to room 115, right bubbler	6.4		µg/L	
223-103-sk-17	Kitchen sink, left	6.4		µg/L	
223-103-sk-18	Kitchen sink, center	1.5		µg/L	
223-103-sk-19	Kitchen sink, right	3.1		µg/L	
223-200-df-20	Drinking fountain, hallway 200, across from room 211, left bubbler	3.5		µg/L	
223-200-df-21	Drinking fountain, hallway 200, across from room 211, right bubbler	3.6		µg/L	
223-207-sk-22	Lounge sink, room 207	13.0		µg/L	
223-200-df-23	Drinking fountain, hallway 200, across from room 205, left bubbler	6.0		µg/L	

223-200-df-24	Drinking fountain, hallway 200, across from room 205, right bubbler	3.9		µg/L	
223-211b-sk-25	Sink, room 211B	7.5		µg/L	
Phase II Sampled on 2/15/2017					
223-109-SK-26	Classroom sink, room 109	19.0	5.0* ¹	µg/L	Faucet replaced 7/15/2017
223-108-SK-27	Classroom sink, room 108	7.0		µg/L	
223-119-SK-28	Classroom sink, room 119	7.0		µg/L	
223-111-SK-29	Classroom sink, room 111	7.0		µg/L	
223-118-SK-30	Classroom sink, room 112	13.0		µg/L	
223-117-SK-31	Classroom sink, room 117	6.0		µg/L	
223-112-SK-32	Classroom sink, room 112	6.0		µg/L	
223-116-SK-33	Classroom sink, room 116	19.0	5.0* ¹	µg/L	Faucet replaced 7/15/2017
223-113-SK-34	Classroom sink, room 113	8.0		µg/L	
223-115-SK-35	Classroom sink, room 115	7.0		µg/L	
223-205-SK-36	Classroom sink, room 205	6.0		µg/L	
223-204-SK-37	Classroom sink, room 204	6.0		µg/L	
223-206-SK-38	Classroom sink, room 206	6.0		µg/L	
223-203-SK-39	Classroom sink, room 203	8.0		µg/L	
223-202-SK-40	Classroom sink, 202	24.0	2.0* ¹	µg/L	Faucet replaced 7/15/2017
223-209-SK-41	Classroom sink, room 209	11.0		µg/L	
223-201-SK-42	Classroom sink, room 201	8.0		µg/L	
223-210-SK-43	Classroom sink, room 210	4.0		µg/L	
223-211B-SK-44	Office sink, room 211B	11.0		µg/L	
223-003-SK-45	Classroom sink, room 003	7.0		µg/L	

*1. Follow up samples collected on 8/31/17 and processed with a Palintest SA1100 scanning analyzer.