

Denison Montessori (226)

All results below 15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/22/16				
Sample ID	Sample Description	Lead Result	Units	Action
226-116-SK-01	Kitchen sink, next to dishwasher	2.8	µg/L	
226-116-SK-02	Main kitchen sink, left faucet	<1.0* ¹	µg/L	
226-116-SK-03	Main kitchen sink, right faucet	2.7	µg/L	
226-H110-DF-04	Drinking fountain, hallway H110, next to kitchen, left bubbler	5.8	µg/L	
226-H110-DF-05	Drinking fountain, hallway H110, next to kitchen, right bubbler	1.4	µg/L	
226-115-DF-06	Drinking fountain, gymnasium, west end	<1.0	µg/L	
226-115-DF-07	Drinking fountain, gymnasium, east end	<1.0	µg/L	
226-H110-DF-08	Drinking fountain, hallway H110, across from 118, left bubbler	1.8	µg/L	
226-H110-DF-09	Drinking fountain, hallway H110, across from 118, right bubbler	1.4	µg/L	
226-120C-SK-10	Admin office sink, room 120C	4.2	µg/L	
226-H100-DF-11	Drinking fountain, hallway 100, across from room 101, left bubbler	1.3	µg/L	
226-H100-DF-12	Drinking fountain, hallway 100, across from room 101, right bubbler	2.0	µg/L	
226-H100-DF-13	Drinking fountain, hallway 100, between 100A and 100B	<1.0	µg/L	
226-111-DF-14	Drinking fountain, room 111	3.2	µg/L	
226-110-DF-15	Drinking fountain, room 110	3.5	µg/L	
226-110-SK-16	Classroom sink, room 110	<1.0	µg/L	
226-106-SK-17	Classroom sink, room 106	5.6	µg/L	
226-107-SK-18	Classroom sink, room 107	11.1	µg/L	
226-159-SK-19	LMC sink, room 159	<1.0	µg/L	
226-105-SK-20	Classroom sink, room 105	<1.0	µg/L	
226-111-SK-21	Classroom sink, room 111	1.3	µg/L	
226-104-SK-22	Classroom sink, room 104	<1.0	µg/L	
226-103-SK-23	Classroom sink, room 103	1.1	µg/L	
226-102-SK-24	Classroom sink, room 102	1.2	µg/L	
226-101-SK-25	Classroom sink, room 101	1.6	µg/L	
226-OUT-DF-26	Drinking fountain, outside, on west gym wall	8.8	µg/L	
226-H200-DF-27	Drinking fountain, north end of hallway H200, left bubbler	<1.0	µg/L	
226-H200-DF-28	Drinking fountain, north end of hallway H200, right bubbler	<1.0	µg/L	
226-201A-SK-29	Workroom sink, room 201A	1.4	µg/L	
226-H200-DF-30	Drinking fountain, hallway H200, between restrooms, left bubbler	1.5	µg/L	
226-H200-DF-31	Drinking fountain, hallway H200, between restrooms, right bubbler	<1.0	µg/L	
226-202-SK-32	Classroom sink, room 202	2.5	µg/L	
226-203-SK-33	Classroom sink, room 203	1.5	µg/L	

226-207-SK-34	Classroom sink, room 207	2.9	µg/L
226-204-SK-35	Classroom sink, room 204	1.2	µg/L
226-206-SK-36	Classroom sink, room 206	1.2	µg/L
226-205-SK-37	Classroom sink, room 205	3.8	µg/L
226-109-SK-38	Classroom sink, room 109	8.0	µg/L
226-108-SK-39	Classroom sink, room 108	10.9	µg/L
226-112-SK-40	Classroom sink, room 112	4.4	µg/L
Phase II Sampled on 3/17/17			
226-201A-SK-41	Faculty workroom sink, room 201A	2.0	µg/L

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.