

Eagleton Elementary (228)

All results below 15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/23/2016				
Sample ID	Sample Description	Lead Result	Units	Action
228-103-SK-01	Staff lounge sink, room 103	<1.0* ¹	µg/L	
228-105-SK-02	Kitchen sink, west wall, left faucet	4.2	µg/L	
228-105-SK-03	Kitchen sink, west wall, right faucet	1.2	µg/L	
228-105A-SK-04	Kitchen sink, east wall, room 105A	<1.0	µg/L	
228-107-DF-05	Drinking fountain, all purpose room 107, west wall	<1.0	µg/L	
228-107-DF-06	Drinking fountain, all purpose room 107, northeast corner	2.7	µg/L	
228-106-DF-07	Drinking fountain, hallway 106, across from room 108	1.2	µg/L	
228-108-SK-08	Classroom sink, room 108	<1.0	µg/L	
228-109-DF-09	Drinking fountain, gymnasium	<1.0	µg/L	
228-111-SK-10	Classroom sink, room 111	<1.0	µg/L	
228-112-SK-11	Classroom sink, room 112	1.9	µg/L	
228-113-SK-12	Classroom sink, room 113	<1.0	µg/L	
228-114-SK-13	Classroom sink, room 114	<1.0	µg/L	
228-110-DF-14	Drinking fountain, hallway 110, next to room 113	<1.0	µg/L	
228-110-DF-15	Drinking fountain, hallway 110, next to room 116	<1.0	µg/L	
228-118-SK-16	Classroom sink, room 118	<1.0	µg/L	
228-117-SK-17	Classroom sink, room 117	<1.0	µg/L	
228-119-DF-18	Drinking fountain, classroom 119	1.3	µg/L	
228-121-DF-19	Drinking fountain, classroom 121	<1.0	µg/L	
228-122-SK-20	Classroom sink, room 122	1.5	µg/L	
228-123-SK-21	Classroom sink, room 123	<1.0	µg/L	
228-127-SK-22	Classroom sink, room 127	1.5	µg/L	
228-128-SK-23	Classroom sink, room 128, by door	3.8	µg/L	
228-100-DF-24	Drinking fountain, hallway 100, next to room 130	<1.0	µg/L	
228-100-DF-25	Drinking fountain, hallway 100, next to room 131	<1.0	µg/L	
228-131-SK-26	Classroom sink, room 131	<1.0	µg/L	
228-132-SK-27	Classroom sink, room 132	<1.0	µg/L	
228-101G-SK-28	Nurse sink, room 101G	<1.0	µg/L	
228-128-SK-29	Classroom sink, room 128	9.7	µg/L	
228-101GA-SK-30	Sink, main office, room 101GA	<1.0	µg/L	
228-130-SK-31	Classroom sink, room 130	<1.0	µg/L	
228-129-SK-32	Classroom sink, room 129	<1.0	µg/L	
228-125-SK-33	Classroom sink, room 125	1.9	µg/L	

228-124-SK-34	Classroom sink, room 124	1.1	µg/L
228-116-SK-35	Classroom sink, room 116	<1.0	µg/L
228-140-DF-36	Drinking fountain, west modular, room 140	<1.0	µg/L
228-141-DF-37	Drinking fountain, east modular, room 141	<1.0	µg/L
Phase II Sampled on 3/9/2017			
228-127-SK-38	Classroom sink, room 127, sink on south wall	9.0	µg/L
228-126-SK-39	Classroom sink, room 126	3.0	µg/L
228-121-SK-40	Classroom sink, room 121	<1.0	µg/L
228-119-SK-41	Classroom sink, room 119	<1.0	µg/L
228-140-SK-42	Classroom sink, room 140	<1.0	µg/L
228-141-SK-43	Classroom sink, room 141	<1.0	µg/L

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.