

Goldrick Elementary (244)

SY 2019/2020 Long Term Sampling – Action Level 10 µg/L

Sample Date: 10/11/2019

| Sample ID | Location Description | Lead Result* ¹ (µg/L) |
|------------------|--|-------------------------------------|
| 244-132-SK03-01 | Kitchen sink, near dishwasher | <1.0 ² |
| 244-132-SK01-01 | Kitchen sink, left | 2.1 |
| 244-132-SK02-01 | Kitchen sink, right | 1.4 |
| 244-131-DF01-01 | Drinking fountain, cafeteria, east | <1.0 |
| 244-131-DF02-01 | Drinking fountain, cafeteria, west | <1.0 |
| 244-H120-DF01-01 | Drinking fountain, hall H120, next to stair B | <1.0 |
| 244-H120-DF02-01 | Drinking fountain, hall H120, next to stair A | <1.0 |
| 244-136-DF01-01 | Drinking fountain, gym | <1.0 |
| 244-136C-SK01-01 | Lounge sink, room 136C | <1.0 |
| 244-130A-SK01-01 | PTA Kitchen sink, room 130A | <1.0 |
| 244-H120-DF03-01 | Drinking fountain, hallway H120, next to 133B | <1.0 |
| 244-H129-DF01-01 | Drinking fountain, hallway H129, next to auditorium | <1.0 |
| 244-H129-DF02-01 | Drinking fountain, hallway H129, next to school office | <1.0 |
| 244-128D-SK01-01 | Nurse sink, room 128D | <1.0 |
| 244-120-DF01-01 | Drinking fountain, room 120 | <1.0 |
| 244-H124-DF01-01 | Drinking fountain, east end of hall H124 | <1.0 |
| 244-H124-DF02-01 | Drinking fountain, hall H124, next to 121 | <1.0 |
| 244-118-DF01-01 | Drinking fountain, room 118 | <1.0 |
| 244-115-DF01-01 | Drinking fountain, room 115 | <1.0 |
| 244-H220-DF01-01 | Drinking fountain, east end of hall H220 | <1.0 |
| 244-H220-DF02-01 | Drinking fountain, west end of hall H220 | <1.0 |

Sample ID Key:

Building number – room number – fixture type count – long term bout count

Notes:

1. Galvanized piping replacement project summer 2019.
2. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

| Phase I Sampled on 9/14/16 | | | | | |
|----------------------------|--|-------------|------------------|-------|-------------------------|
| Sample ID | Sample Description | Lead Result | Follow Up Result | Units | Action |
| 244-H120-DF-01 | Drinking fountain, hall H120, next to stair B, left bubbler | 11.8 | | µg/L | |
| 244-H120-DF-02 | Drinking fountain, hall H120, next to stair B, right bubbler | 7.1 | | µg/L | |
| 244-H120-DF-03 | Drinking fountain, hall H120, next to stair A, left bubbler | 3.0 | | µg/L | |
| 244-H120-DF-04 | Drinking fountain, hall H120, next to stair A, right bubbler | 1.5 | | µg/L | |
| 244-131-DF-05 | Drinking fountain, cafeteria, east, left bubbler | 7.3 | | µg/L | |
| 244-131-DF-06 | Drinking fountain, cafeteria, east, right bubbler | 4.0 | | µg/L | |
| 244-131-DF-07 | Drinking fountain, cafeteria, west, left bubbler | 17.1 | 4.0 | µg/L | Bubbler replaced 2/2018 |
| 244-131-DF-08 | Drinking fountain, cafeteria, west, right bubbler | 6.4 | 2.0 | µg/L | Bubbler replaced 2/2018 |
| 244-132-SK-09 | Kitchen sink, right | 4.3 | | µg/L | |
| 244-132-SK-10 | Kitchen sink, left | 2.0 | | µg/L | |
| 244-132-SK-11 | Kitchen sink, near dishwasher | 13.0 | | µg/L | |
| 244-136-DF-12 | Drinking fountain, gym, right bubbler | 7.3 | | µg/L | |
| 244-H120-DF-13 | Drinking fountain, hallway H120, next to 133B | 5.6 | | µg/L | |
| 244-H120-DF-14 | Drinking fountain, hallway H129, next to auditorium, left bubbler | 13.9 | | µg/L | |
| 244-H129-DF-15 | Drinking fountain, hallway H129, next to auditorium, right bubbler | 9.3 | | µg/L | |
| 244-128D-DF-16 | Drinking fountain, hallway H129, next to school office | 9.9 | | µg/L | |
| 244-128D-SK-17 | Nurse sink, room 128D | 6.1 | | µg/L | |
| 244-136-DF-18 | Drinking fountain, gym, left bubbler | 33.4 | 5.0 | µg/L | Bubbler replaced 2/2018 |
| 244-136E-SK-19 | Lounge sink, room 136C | 2.0 | | µg/L | |
| 244-H124-DF-20 | Drinking fountain, hall H124, next to 121 | 2.0 | | µg/L | |
| 244-H124-DF-21 | Drinking fountain, hall H124, next to 120 | 2.0 | | µg/L | |
| 244-120-DF-22 | Drinking fountain, room 120 | 5.6 | | µg/L | |
| 244-118-DF-23 | Drinking fountain, room 123 | 4.8 | | µg/L | |
| 244-115-DF-24 | Drinking fountain, room 115 | 2.0 | | µg/L | |
| 244-H124-DF-25 | Drinking fountain, east end of hall H124 | 6.4 | | µg/L | |
| 244-H220-DF-26 | Drinking fountain, west end of hall H220 | 1.7 | | µg/L | |
| 244-H220-DF-27 | Drinking fountain, east end of hall H220, left bubbler | 7.4 | | µg/L | |

| | | | | | |
|------------------------------------|---|--------------------|------|------|---------------------------|
| 244-H220-DF-28 | Drinking fountain, east end of hall H220, right bubbler | 4.6 | | µg/L | |
| Phase II Sampled on 2/24/17 | | | | | |
| 244-104-SK-29 | LMC/IMC sink, room 104 | 5.0 | | µg/L | |
| 244-106-SK-30 | Classroom sink, room 106 | 6.0 | | µg/L | |
| 244-103-SK-31 | Classroom sink, room 103 | 16.0 | <1.0 | µg/L | Faucet replaced 6/2018 |
| 244-107-SK-32 | Classroom sink, room 107 | 8.0 | | µg/L | |
| 244-102-SK-33 | Classroom sink, room 102 | 6.0 | | µg/L | |
| 244-108-SK-34 | Classroom sink, room 108 | 3.0 | | µg/L | |
| 244-101-SK-35 | Classroom sink, room 101 | 9.0 | | µg/L | |
| 244-124-SK-36 | Classroom sink, room 124 | 6.0 | | µg/L | |
| 244-123-SK-37 | Classroom sink, room 123 | 5.0 | | µg/L | |
| 244-109-SK-38 | Classroom sink, room 109 | 4.0 | | µg/L | |
| 244-122-SK-39 | Classroom sink, room 122 | 5.0 | | µg/L | |
| 244-110-SK-40 | Classroom sink, room 110 | 8.0 | | µg/L | |
| 244-121-SK-41 | Classroom sink, room 121 | 3.0 | | µg/L | |
| 244-120-SK-42 | Classroom sink, room 120 | 35.0 | 3.0 | µg/L | Faucet replaced 6/2018 |
| 244-119-SK-43 | Classroom sink, room 119 | 4.0 | | µg/L | |
| 244-118-SK-44 | Classroom sink, room 118 | 7.0 | | µg/L | |
| 244-111-SK-45 | Classroom sink, room 111 | 6.0 | | µg/L | |
| 244-116-SK-46 | Classroom sink, room 116, sink on right | <1.0* ¹ | | µg/L | |
| 244-116-SK-47 | Classroom sink, room 116, sink on left | 1.0 | | µg/L | |
| 244-112-SK-48 | Classroom sink, room 112 | 5.0 | | µg/L | |
| 244-115-SK-49 | Classroom sink, room 115, sink on right | <1.0 | | µg/L | |
| 244-115-SK-50 | Classroom sink, room 115, sink on left | <1.0 | | µg/L | |
| 244-113-SK-51 | Classroom sink, room 113 | 7.0 | | µg/L | |
| 244-114-SK-52 | Classroom sink, room 114 | 12.0 | | µg/L | |
| 244-201-SK-53 | Classroom sink, room 201 | 10.0 | | µg/L | |
| 244-208-SK-54 | Classroom sink, room 208 | 9.0 | | µg/L | |
| 244-202-SK-55 | Classroom sink, room 202 | 4.0 | | µg/L | |
| 244-207-SK-56 | Classroom sink, room 207 | 5.0 | | µg/L | |
| 244-203-SK-57 | Classroom sink, room 203 | 5.0 | | µg/L | |
| 244-206-SK-58 | Classroom sink, room 206 | 5.0 | | µg/L | |
| 244-204-SK-59 | Classroom sink, room 204 | 5.0 | | µg/L | |

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.