

Greenlee Elementary (245) – 1150 N. Lipan St.

SY 2019/2020 Long Term Sampling – Action Level 10 µg/L

Sample Date: 09/20/2019

Sample ID	Location Description	Lead Result (µg/L)	Action
245-H010A-SK01-01	Sink, room H010A	1.3	
245-KIT-SK01-01	Kitchen sink, left faucet	2.7	
245-KIT-SK02-01	Kitchen sink, right faucet	5.8	
245-LR-DF01-01	Drinking fountain, cafeteria	13.7	POU filter installed 1/2020
245-H120D-DF01-01	Drinking fountain, hallway H120D, next to gymnasium	<1.0 ¹	
245-GYM-DF01-01	Drinking fountain, gym, south	5.1	
245-102B-SK01-01	Faculty lounge sink, room 102B	3.5	
245-H100-DF01-01	Drinking fountain, hallway 100, outside of room 102	6.3	
245-H100-DF02-01	Drinking fountain, hallway 100, next to room 105	<1.0	
245-106A-SK01-01	Faculty lounge sink, room 106A	10.1	Flush notice, faucet replacement pending
245-H100-BF01-01	Bottle fill station, hallway 100, near H100E	<1.0	
245-OFFF-SK01-01	Sink, admin office, room OFFF	11.6	Flush notice, faucet replacement pending
245-H160-DF01-01	Drinking fountain, between rooms 117 and 116	1.0	
245-H130-DF01-01	Drinking fountain, between rooms 108 and 109	1.4	
245-H140-DF01-01	Drinking fountain, between rooms 110 and 111	<1.0	
245-H100-DF04-01	Drinking fountain, hallway 100, next to room 111	<1.0	
245-112-DF01-01	Drinking fountain, room 112	<1.0	
245-113-DF01-01	Drinking fountain, room 113	<1.0	
245-H200-DF04-01	Drinking fountain, hallway 200, by room 211	<1.0	
245-H220-DF01-01	Drinking fountain, between rooms 210 and 211	<1.0	
245-H230-DF01-01	Drinking fountain, between rooms 212 and 213	15.2	POU filter installed 1/2020
245-H210-DF01-01	Drinking fountain, between 208 and 209	<1.0	
245-H240-DF01	Drinking fountain, between rooms 215 and 214	<1.0	
245-H200-BF01-01	Bottle fill station, hallway 200, south of IMC	<1.0	
245-H200-DF02-01	Drinking fountain, hallway 200, south of 201	18	POU filter installed 1/2020
245-H200-DF01-01	Drinking fountain, hallway 200, north of 202	<1.0	
245-204-SK01-01	Lounge sink, room 204	11.1	Flush notice, faucet replacement pending

Sample ID Key:

Building number – room number – fixture type count – long term count

1. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/2/16 & 9/8/16					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
245-KIT-SK-01	Kitchen sink, left faucet	3.7		µg/L	
245-KIT-SK-02	Kitchen sink, right faucet	3.7		µg/L	
245-H010A-SK-03	Sink, room H010A	1.4		µg/L	
245-LR-DF-04	Drinking fountain, cafeteria, left bubbler	5.9		µg/L	
245-LR-DF-05	Drinking fountain, cafeteria, right bubbler	5.4		µg/L	
245-H100-DF-06	Drinking fountain, hallway 100, outside of room 102	5.0		µg/L	
245-H100-DF-07	Drinking fountain, hallway 100, next to 105, left bubbler	16.9	<1.0	µg/L	Bubbler replaced 11/2018, POU Filter
245-H100-DF-08	Drinking fountain, hallway 100, next to 105, right bubbler	4.8		µg/L	
245-106A-SK-09	Lounge sink, room 106A	10.8		µg/L	
245-OFFF-SK-10	Sink, admin office, room OFFF	10.6		µg/L	
245-H100-DF-11	Drinking fountain, hallway 100, near H100E	6.1		µg/L	
245-H130-DF-12	Drinking fountain, between rooms 108 and 109, left bubbler	7.4		µg/L	
245-H130-DF-13	Drinking fountain, between rooms 108 and 109, right bubbler	3.1		µg/L	
245-H160-DF-14	Drinking fountain, between rooms 117 and 116, left bubbler	11.0		µg/L	
245-H160-DF-15	Drinking fountain, between rooms 117 and 116, right bubbler	6.9		µg/L	
245-117-SK-16	Sink, room 117	3.6		µg/L	
245-H100-DF-17	Drinking fountain, hallway 100, next to room 111, left bubbler	11.8		µg/L	
245-H100-DF-18	Drinking fountain, hallway 100, next to room 111, right bubbler	8.6		µg/L	
245-113-DF-19	Drinking fountain, room 113, left bubbler	14.4		µg/L	
245-113-DF-20	Drinking fountain, room 113, right bubbler	3.8		µg/L	
245-112-DF-21	Drinking fountain, room 112, left bubbler	10.8		µg/L	
245-112-DF-22	Drinking fountain, room 112, right bubbler	8.3		µg/L	
245-GYM-DF-23	Drinking fountain, gym, south	2.7		µg/L	
245-GYM-DF-24	Drinking fountain, gym, north	15.1	14.0	µg/L	Replaced 11/2017
245-H200-DF-25	Drinking fountain, hallway 200, north of 202, left bubbler	10.7		µg/L	
245-H200-DF-26	Drinking fountain, hallway 200, north of 202, right bubbler	9.2		µg/L	
245-H200-DF-27	Drinking fountain, hallway 200, south of 201	7.2		µg/L	
245-H200-DF-28	Drinking fountain, hallway 200, south of IMC	4.2		µg/L	
245-H210-DF-29	Drinking fountain, between 208 and 209, left bubbler	11.1		µg/L	
245-H210-DF-30	Drinking fountain, between 208 and 209, right bubbler	8.6		µg/L	
245-H240-DF-31	Drinking fountain, between rooms 215 and 214, left bubbler	13.4		µg/L	

245-H240-DF-32	Drinking fountain, between rooms 215 and 214, right bubbler	11.3		µg/L	
245-H200-DF-33	Drinking fountain, hallway 200, by room 211, left bubbler	10.2		µg/L	
245-H200-DF-34	Drinking fountain, hallway 200, by room 211, right bubbler	9.1		µg/L	
245-H220-DF-35	Drinking fountain, between rooms 210 and 211, left bubbler	10.3		µg/L	
245-H220-DF-36	Drinking fountain, between rooms 210 and 211, right bubbler	5.7		µg/L	
245-H230-DF-37	Drinking fountain, between rooms 212 and 213, left bubbler	9.8		µg/L	
245-H230-DF-38	Drinking fountain, between rooms 212 and 213, right bubbler	3.9		µg/L	
245-H140-DF-39	Drinking fountain, between rooms 110 and 111, left bubbler	>50.0	7.0	µg/L	Replaced 11/2017
245-H140-DF-40	Drinking fountain, between rooms 110 and 111, right bubbler	10.8		µg/L	
245-H150-DF-41	Drinking fountain, between rooms 114 and 115, left bubbler	18.8	14.0	µg/L	Replaced 11/2017
245-H150-DF-42	Drinking fountain, between rooms 114 and 115, right bubbler	9.9		µg/L	
Phase II Sampled on 2/17/17					
245-103-SK-43	Classroom sink, room 103	13.0		µg/L	
245-104-SK-44	Classroom sink, room 104	18.0	9.0	µg/L	Replaced 11/2017
245-102B-SK-45	Faculty lounge sink, room 102B	17.0	4.0	µg/L	Replaced 11/2017
245-105-SK-46	Classroom sink, room 105	10.0		µg/L	
245-101-SK-47	Classroom sink, room 101	7.0		µg/L	
245-108-SK-48	Classroom sink, room 108	11.0		µg/L	
245-116-SK-49	Classroom sink, room 116	9.0		µg/L	
245-109-SK-50	Classroom sink, room 109	7.0		µg/L	
245-115-SK-51	Classroom sink, room 115	10.0		µg/L	
245-110-SK-52	Classroom sink, room 110	11.0		µg/L	
245-114-SK-53	Classroom sink, room 114	8.0		µg/L	
245-111-SK-54	Classroom sink, room 111	4.0		µg/L	
245-113-SK-55	Classroom sink, room 113	6.0		µg/L	
245-112-SK-56	Classroom sink, room 112	5.0		µg/L	
245-203-SK-57	Classroom sink, room 203	19.0	6.0	µg/L	Replaced 11/2017
245-204-SK-58	Classroom sink, room 204	6.0		µg/L	
245-202-SK-59	Classroom sink, room 202	15.0	2.0	µg/L	Replaced 11/2017
245-205-SK-60	Classroom sink, room 205	9.0		µg/L	
245-201-SK-61	Classroom sink, room 201	7.0		µg/L	
245-215-SK-62	Classroom sink, room 215	8.0		µg/L	
245-208-SK-63	Classroom sink, room 208	16.0	9.0	µg/L	Replaced 11/2017
245-214-SK-64	Classroom sink, room 214	9.0		µg/L	
245-209-SK-65	Classroom sink, room 209	11.0		µg/L	
245-213-SK-66	Classroom sink, room 213	5.0		µg/L	

245-210-SK-67	Classroom sink, room 210	5.0	µg/L
245-212-SK-68	Classroom sink, room 212	3.0	µg/L
245-211-SK-69	Classroom sink, room 211	9.0	µg/L
245-IMCAA-SK-70	LMC/IMC office sink, room IMCAA	2.0	µg/L
245-206-SK-71	Classroom sink, room 206	10.0	µg/L
245-106A-SK-72	Faculty lounge sink, room 106A	7.0	µg/L

*1. Flush samples are field tested with a Palintest SA1100 scanning analyzer.