

Newlon Elementary (261) – 361 N. Vrain St.

Sample ID	Location Description	Post Mitigation Lead Result (µg/L)	Action
261-H150-DF02-01	Drinking fountain, hall H150, next to 105	<1.0*	POU filter installed 2/2020

*Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Newlon Elementary (261) – 361 N. Vrain St.

SY 2019/2020 Long Term Sampling – Action Level 10 µg/L

Sample Date: 12/06/2019

Sample ID	Location Description	Lead Result (µg/L)	Action
261-06A-SK01-01	Kitchen prep sink, room 06A	1.5	
261-06-SK01-01	Kitchen sink, left faucet	2.8	
261-06-SK02-01	Kitchen sink, right faucet	<1.0 ¹	
261-05-DF01-01	Drinking fountain, cafeteria	7.0	
261-04-SK01-01	Lounge sink, room 04	<1.0	
261-H000-DF01-01	Drinking fountain, hallway H000	9.2	
261-127-SK01-01	Staff workroom, room 127	<1.0	
261-H100-DF01-01	Drinking fountain, hallway H100, next to elevator	<1.0	
261-H150-DF01-01	Drinking fountain, hall H150, across from room 101	<1.0	
261-H150-DF02-01	Drinking fountain, hall H150, next to 105	14.1	Shut down, filter install
261-H105A-DF01-01	Drinking fountain, hall 105A, between 105 and 103	7.4	
261-H240-DF02-01	Drinking fountain, hall H240, across from room 208	4.0	
261-H240-DF01-01	Drinking fountain, hall H240, across from room 203	3.3	
261-H160-DF01-01	Drinking fountain, hall H160, across from 109	<1.0	
261-113A-SK01-01	Lounge sink, room 113A	3.5	
261-H160-DF02-01	Drinking fountain, hall H160, across from 113, left fountain	<1.0	
261-H160-DF03-01	Drinking fountain, hall H160, across from 113, right fountain	<1.0	
261-H170-DF01-01	Drinking fountain, hall H170, next to room 115, left fountain	<1.0	
261-H170-DF02-01	Drinking fountain, hall H170, next to room 115, right fountain	<1.0	
261-H170-DF03-01	Drinking fountain, hall H170, next to H160K, left fountain	<1.0	
261-H170-DF04-01	Drinking fountain, hall H170, next to H160K, right fountain	<1.0	
261-119-DF01-01	Drinking fountain, room 119	<1.0	
261-123A-DF01-01	Drinking fountain, 123A, between rooms 123 and 121	<1.0	
261-122A-DF01-01	Drinking fountain, 122A, between rooms 122 and 120	<1.0	
261-H150-DF02-01RT	Drinking fountain, hall H150, next to 105	<1.0	

Sample ID Key:

Building number – room number – fixture type count – long term count

1. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/8/16					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
261-06-SK-01	Kitchen sink, left	4.5		µg/L	
261-06-SK-02	kitchen sink, right	3.7		µg/L	
261-05-DF-03	Drinking fountain, cafeteria, left	6.6		µg/L	
261-05-DF-04	Drinking fountain, cafeteria, right	4.3		µg/L	
261-03A-SK-05	Lounge sink, room 03A	1.3		µg/L	
261-H000-DF-06	Drinking fountain, hallway H000, left bubbler	19.2	8.0	µg/L	Bubbler replaced 2/2018
261-H000-DF-07	Drinking fountain, hallway H000, right bubbler	8.6		µg/L	
261-100E-SK-08	Nurse sink, room 100E	7.5		µg/L	
261-H100-DF-09	Drinking fountain, hallway H100, next to elevator, left bubbler	10.1		µg/L	
261-H100-DF-10	Drinking fountain, hallway H100, next to elevator, right bubbler	4.3		µg/L	
261-125L-SK-11	Sink, gymnasium room 125C	5.6		µg/L	
261-122A-DF-12	Drinking fountain, 122A, between rooms 122 and 120	<1.0* ¹		µg/L	
261-122-SK-13	Classroom sink, room 122	1.2		µg/L	
261-123A-DF-14	Drinking fountain, 123A, between rooms 123 and 121	<1.0		µg/L	
261-119-DF-15	Drinking fountain, room 119	<1.0		µg/L	
261-119-SK-16	Classroom sink, room 119	<1.0		µg/L	
261-116-SK-17	Classroom sink, room 116	<1.0		µg/L	
261-H170-DF-18	Drinking fountain, hall H170, west exit, left bubbler	<1.0		µg/L	
261-H170-DF-19	Drinking fountain, hall H170, west exit, right bubbler	<1.0		µg/L	
261-H170-DF-20	Drinking fountain, hall H170, next to room 115, left bubbler	<1.0		µg/L	
261-H170-DF-21	Drinking fountain, hall H170, next to room 115, right bubbler	<1.0		µg/L	
261-H160-DF-22	Drinking fountain, hall H160, across from 113, left bubbler	<1.0		µg/L	
261-H160-DF-23	Drinking fountain, hall H160, across from 113, right bubbler	<1.0		µg/L	
261-113A-SK-24	Lounge sink, room 113A	5.6		µg/L	
261-H160-DF-25	Drinking fountain, hall H160, across from 109	<1.0		µg/L	
261-107-SK-26	Classroom sink, room 107	4.6		µg/L	
261-105A-DF-27	Drinking fountain, hall 105A, between 105 and 103	9.4		µg/L	
261-H150-DF-28	Drinking fountain, hall H150, next to 105, left bubbler	19.6	8.0	µg/L	Bubbler replaced 2/2018
261-104-SK-29	Classroom sink, room 104	6.2		µg/L	
261-101-DF-30	Drinking fountain, room 101	3.7		µg/L	
261-102-SK-31	Classroom sink, room 102	13.3		µg/L	
261-H150-DF-32	Drinking fountain, hall H150, across from room 101, left bubbler	10.0		µg/L	
261-H150-DF-33	Drinking fountain, hall H150, across from room 101, right bubbler	2.3		µg/L	

261-201-SK-34	Classroom sink, room 201	8.2	µg/L
261-H240-DF-35	Drinking fountain, hall H240, across from room 203, left bubbler	4.8	µg/L
261-H240-DF-36	Drinking fountain, hall H240, across from room 203, right bubbler	4.3	µg/L
261-H240-DF-37	Drinking fountain, hall H240, across from room 208, left bubbler	5.8	µg/L
261-H240-DF-38	Drinking fountain, hall H240, across from room 208, right bubbler	5.2	µg/L
Phase II Sampled on 2/22/17			
261-02-SK-39	Classroom sink, room 02	3.1	µg/L
261-101-SK-40	Classroom sink, room 101	6.5	µg/L
261-103-SK-41	Classroom sink, room 103	9.7	µg/L
261-105-SK-42	Classroom sink, room 105	19.1	18.0
			µg/L Failed – no drinking notice, Faucet replaced 9/2018
261-106-SK-43	Classroom sink, room 106	5.3	µg/L
261-108-SK-44	Classroom sink, room 108	3.6	µg/L
261-109-SK-45	Classroom sink, room 109	2.5	µg/L
261-110-SK-46	Classroom sink, room 110	2.8	µg/L
261-111-SK-47	Classroom sink, room 111	1.5	µg/L
261-112-SK-48	Classroom sink, room 112	2.7	µg/L
261-114-SK-49	Classroom sink, room 114	2.2	µg/L
261-117-SK-50	Classroom sink, room 117	0.4	µg/L
261-118-SK-51	Classroom sink, room 118	0.4	µg/L
261-119-SK-52	Classroom sink, room 119	0.5	µg/L
261-121-SK-53	Classroom sink, room 121	0.3	µg/L
261-120-SK-54	Classroom sink, room 120	1.8	µg/L
261-123-SK-55	Classroom sink, room 123	0.4	µg/L
261-127-SK-56	Staff workroom, room 127	1.7	µg/L
261-204-SK-57	Classroom sink, room 204	5.2	µg/L
261-203-SK-58	Classroom sink, room 203	14.3	µg/L
261-206-SK-59	Classroom sink, room 206	4.9	µg/L
261-205-SK-60	Classroom sink, room 205	8.4	µg/L
261-208-SK-61	Classroom sink, room 208	4.9	µg/L
261-207-SK-62	Classroom sink, room 207	7.2	µg/L

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.