

McKinley-Thatcher (264) – 1230 S. Grant St.

SY 2019/2020 Long Term Sampling – Action Level 10 µg/L

Sample Date: 03/06/2020

Sample ID	Location Description	Lead Result (µg/L)
264-119-SK01-01	Kitchen sink, left faucet	5.2
264-119-SK02-01	Kitchen sink, right faucet	4.1
264-115-DF01-01	Drinking fountain, hallway 115	<1.0 ¹
264-124-BF01-01	Bottle fill station, hallway 124, high-low station	<1.0
264-124-BF02-01	Bottle fill station, hallway 124, single station	<1.0
264-101B-SK01-01	Lounge sink, room 101B	<1.0
264-101D-SK01-01	Nurse sink, room 101D	2.2
264-113-DF01-01	Drinking fountain, room 113	5.8
264-112-DF01-01	Drinking fountain, room 112	2.2
264-107-DF01-01	Drinking fountain, hallway 107	5.7
264-109-SK01-01	Lounge sink, room 109	<1.0
264-111-DF01-01	Drinking fountain, room 111	1.2
264-110-DF01-01	Drinking fountain, room 110	7.1
264-106-DF01-01	Drinking fountain, room 106	1.5
264-105-DF01-01	Drinking fountain, room 105	2.6
264-104-DF01-01	Drinking fountain, room 104	1.2
264-100-DF01-01	Drinking fountain, hallway 100	1.3
264-204-DF01-01	Drinking fountain, room 204	2.6
264-205-DF01-01	Drinking fountain, room 205	<1.0
264-206-DF01-01	Drinking fountain, room 206	3.3
264-207-DF01-01	Drinking fountain, room 207	2.3
264-200-DF01-01	Drinking fountain, hallway 200	1.8

Sample ID Key:

Building number – room number – fixture type count – long term bout count

1. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Phase I & II Sampled 9/28/2016

Action Level 15 µg/L

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
264-119-SK-01	Kitchen sink, west wall, left faucet	5.1		µg/L	
264-119-SK-02	Kitchen sink, west wall, right faucet	2.5		µg/L	
264-116-DF-03	Drinking fountain, gymnasium, north wall	<1.0* ¹		µg/L	
264-115-DF-04	Drinking fountain, hallway 115, outside of gymnasium	<1.0		µg/L	
264-101D-SK-05	Nurse sink, room 101D	7.3		µg/L	
264-102-SK-06	Staff lounge sink, room 102	1.8		µg/L	
264-104-DF-07	Drinking fountain, room 104	<1.0		µg/L	
264-104-SK-08	Classroom sink, room 104	7.1		µg/L	
264-105-DF-09	Drinking fountain, room 105	2.1		µg/L	
264-105-SK-10	Classroom sink, room 105	1.4		µg/L	
264-106-DF-11	Drinking fountain, room 106	20.2	13.0	µg/L	Replaced 2/2018
264-106-SK-12	Classroom sink, room 106	<1.0		µg/L	
264-OUT-DF-13	Drinking fountain, outside on south west corner, by room 106	5.5		µg/L	
264-100-DF-14	Drinking fountain, hallway 100, across from room 109	1.8		µg/L	
264-200-DF-15	Drinking fountain, hallway 200, across from room 207	1		µg/L	
264-207-DF-16	Drinking fountain, room 207	<1.0		µg/L	
264-207-SK-17	Classroom sink, room 207	1.3		µg/L	
264-206-DF-18	Drinking fountain, room 206	1.4		µg/L	
264-206-SK-19	Classroom sink, room 206	2.9		µg/L	
264-205-DF-20	Drinking fountain, room 205	<1.0		µg/L	
264-205-SK-21	Classroom sink, room 205	2.6		µg/L	
264-204-DF-22	Drinking fountain, room 204	3.7		µg/L	
264-204-SK-23	Classroom sink, room 204	<1.0		µg/L	
264-110-DF-24	Drinking fountain, room 110	4.0		µg/L	
264-110-SK-25	Classroom sink, room 110	9.9		µg/L	
264-111-DF-26	Drinking fountain, room 111	1.2		µg/L	
264-111-SK-27	Classroom sink, room 111	2.8		µg/L	
264-107-DF-28	Drinking fountain, hallway 107, across from room 112	4.5		µg/L	
264-112-DF-29	Drinking fountain, room 112	1.8		µg/L	
264-112-SK-30	Classroom sink, room 112	4.7		µg/L	
264-113-DF-31	Drinking fountain, room 113	6.1		µg/L	
264-113-SK-32	Classroom sink, room 113	7.3		µg/L	
264-114A-SK-33	LMC sink, room 114A	3.0		µg/L	
264-OUT-DF-34	Drinking fountain, outside, south east corner by gymnasium	5.7		µg/L	

1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.