

**Pioneer Building (266) – 3230 E. 38th St.
University Prep – Steel St.**

***SY 2019/2020 Long Term Sampling – Action Level 10 µg/L
Sample Date: 02/06/2020***

Sample ID	Location Description	Lead Result (µg/L)
266-H010-DF01-01	Drinking fountain, hallway H010, across from stair D	5.5
266-H010-DF02-01	Drinking fountain, hallway H010, next to room 009	9.5
266-007-SK01-01	Lounge sink, room 007	1.9
266-H100-DF03-01	Drinking fountain, hallway H100, next to stair C	<1.0 ¹
266-104B-SK01-01	Admin office sink, room 104B	4.3
266-H100-DF02-01	Drinking fountain, hallway H100, next to room 102	<1.0
266-H100-DF01-01	Drinking fountain, hallway H100, next to H100A	<1.0
266-112-DF01-01	Drinking fountain, all purpose room, west wall	<1.0
266-112A-SK01-01	Kitchen prep sink, left of 3 compartment sink	<1.0
266-112A-SK02-01	Kitchen sink, 3 compartment, left faucet	<1.0
266-112A-SK03-01	Kitchen sink, 3 compartment, right faucet	<1.0
266-H200-DF01-01	Drinking fountain, hallway H200, across from stair B	<1.0
266-H200-DF02-01	Drinking fountain, hallway H200, across from stair A	<1.0
266-203-SK01-01	Lounge sink, room 203	<1.0

Sample ID Key:

Building number – room number – fixture type count – long term count

1. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

All results at 15 ppb or below – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 8/26/2016

Sample ID	Sample Description	Lead Result	Units	Action
266-112-DF-01	Drinking fountain, gym, right bubbler	<1.0* ¹	µg/L	
266-112-DF-02	Drinking fountain, gym, left bubbler	<1.0	µg/L	
266-H100-DF-03	Drinking fountain, hallway H100, next to gym, right bubbler	<1.0	µg/L	
266-H100-DF-04	Drinking fountain, hallway H100, next to gym, left bubbler	<1.0	µg/L	
266-H100-DF-05	Drinking fountain, hallway H100, next to room 102	<1.0	µg/L	
266-H100-DF-06	Drinking fountain, hallway H100, next to room 104	<1.0	µg/L	
266-H200-DF-07	Drinking fountain, hallway H200, across from room 209	<1.0	µg/L	
266-H200-DF-08	Drinking fountain, hallway H200, next to room 202, right bubbler	<1.0	µg/L	
266-H200-DF-09	Drinking fountain, hallway H200, next to room 202, left bubbler	<1.0	µg/L	
266-H010-DF-10	Drinking fountain, hallway H010, next to room 009	3.2	µg/L	
266-H010-DF-11	Drinking fountain, hallway, H010, next to room 007, right bubbler	5.9	µg/L	
266-H010-DF-12	Drinking fountain, hallway, H010, next to room 007, left bubbler	12.3	µg/L	
266-112A-SK-13	Kitchen sink, room 112A	10.2	µg/L	

Phase II Sampled on 2/2/2017

266-002-SK-14	Custodial office sink, room 002	2.3	µg/L	
266-007-SK-15	Admin office sink, room 007	3.7	µg/L	
266-008-SK-16	Admin office sink, room 008	4.5	µg/L	
266-009-SK-17	Faculty workroom sink, room 009	12.0	µg/L	
266-107-SK-18	Classroom sink, room 107	1.3	µg/L	
266-106-SK-19	Classroom sink, room 106	0.6	µg/L	
266-108-SK-20	Classroom sink, room 108	4.4	µg/L	
266-105-SK-21	Classroom sink, room 105	4.2	µg/L	
266-109-SK-22	Classroom sink, room 109	0.6	µg/L	
266-104B-SK-23	Admin office sink, room 104B	4.2	µg/L	
266-110-SK-24	Classroom sink, room 110	4.9	µg/L	
266-103-SK-25	Classroom sink, room 103	1.6	µg/L	
266-206-SK-26	Classroom sink, room 206	1.4	µg/L	
266-207-SK-27	Classroom sink, room 207	4.3	µg/L	
266-208-SK-28	Classroom sink, room 208	1.1	µg/L	
266-209-SK-29	Classroom sink, room 209	4.6	µg/L	
266-205-SK-30	Classroom sink, room 205	3.1	µg/L	
266-203-SK-31	Faculty lounge sink, room 203	3.4	µg/L	
266-210-SK-32	Classroom sink, room 210	10.0	µg/L	

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.