

**Stedman Elementary (277) – 2940 N. Dexter St.**

***SY 2019/2020 Long Term Sampling – Action Level 10 µg/L***

***Sample Date: 02/20/2020***

<b>Sample ID</b>	<b>Location Description</b>	<b>Lead Result<sup>1</sup> (µg/L)</b>
<b>277-108-SK01-01</b>	Kitchen sink, 3 compartment sink, left faucet	<1.0 <sup>2</sup>
<b>277-108-SK02-01</b>	Kitchen sink, 3 compartment sink, right faucet	1.5
<b>277-108-SK03-01</b>	Kitchen prep sink	4.3
<b>277-105-DF02-01</b>	Drinking fountain, hallway 105, next to kitchen	4.4
<b>277-107-DF01-01</b>	Drinking fountain, cafeteria	<1.0
<b>277-105-DF01-01</b>	Drinking fountain, hallway 105, next to 104B	<1.0
<b>277-100-DF01-01</b>	Drinking fountain, hallway 100, across from room 102	<1.0
<b>277-100-DF02-01</b>	Drinking fountain, hallway 100, across from room 121	<1.0
<b>277-121CC-SK01-01</b>	Nurse restroom sink, room 121CC	<1.0
<b>277-100-DF03-01</b>	Drinking fountain, hallway 100, next to room 113	<1.0
<b>277-114-SK01-01</b>	Lounge sink, room 114G	<1.0
<b>277-119-DF01-01</b>	Drinking fountain, room 119	<1.0
<b>277-116-DF01-01</b>	Drinking fountain, hallway 116, next to room 119	1.5
<b>277-117A-DF01-01</b>	Drinking fountain, hallway 117A	<1.0
<b>277-200-DF02-01</b>	Drinking fountain, hallway 200, next to stair B	<1.0
<b>277-200-DF01-01</b>	Drinking fountain, hallway 200, next to room 209	<1.0
<b>277-215-DF01-01</b>	Drinking fountain, hallway 215, next to room 214	<1.0
<b>277-205-DF01-01</b>	Drinking fountain/sink combo, room 205	<1.0
<b>277-206-DF01-01</b>	Drinking fountain/sink combo, room 206	<1.0
<b>277-215-DF02-01</b>	Drinking fountain, hallway 215, next to room 207	2.0

**Sample ID Key:**

Building number – room number – fixture type count – long term count

**Notes:**

1. Piping replacement project summer 2018.
2. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

## Phase I & II Sampling – Action Level 15 µg/L

**Sample ID Key:**

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 8/25/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
277-116DF-02	Drinking fountain, hallway 116, next to room 119	5.4		µg/L	
277-114-SK-03	Lounge sink, room 114	3.6		µg/L	
277-100-DF-04	Drinking fountain, hallway 100, next to gym, right bubbler	3.1		µg/L	
277-100-DF-05	Drinking fountain, hallway 100, next to gym, left bubbler	<1.0* <sup>1</sup>		µg/L	
277-100-DF-06	Drinking fountain, hallway 100, across from admin office	5.9		µg/L	
277-100-DF-07	Drinking fountain, hallway 100, across from room 102	1.9		µg/L	
277-103-SK-08	Sink, room 103	5.1		µg/L	
277-105-DF-09	Drinking fountain, hallway 105, next to room 104B	3.7		µg/L	
277-105-DF-10	Drinking fountain, east end of hallway 105, right bubbler	1.9		µg/L	
277-105-DF-11	Drinking fountain, east end of hallway 105, left bubbler	6.7		µg/L	
277-119-DF-12	Drinking fountain, room 119	14.1		µg/L	
277-200-DF-13	Drinking fountain, hallway 200, next to room 210	4.2		µg/L	
277-200-DF-14	Drinking fountain, hallway 200, next to room 209	2.4		µg/L	
277-215-DF-15	Drinking fountain, hallway 215, next to room 204, right bubbler	<1.0		µg/L	
277-215-DF-16	Drinking fountain, hallway 215, next to room 204, left bubbler	1.8		µg/L	
277-215-DF-17	Drinking fountain, hallway 215, next to room 207, right bubbler	3.2		µg/L	
277-215-DF-18	Drinking fountain, hallway 215, next to room 207, left bubbler	1.2		µg/L	
Phase II Sampled on 1/26/2017					
277-108-SK-19	Kitchen prep sink, room 108, south wall	2.8		µg/L	
277-108-SK-20	Kitchen kettle fill, room 108	4.2		µg/L	
277-107-DF-21	Drinking fountain, cafeteria 107, left bubbler	<0.1* <sup>2</sup>		µg/L	
277-107-DF-22	Drinking fountain, cafeteria 107, right bubbler	6.9		µg/L	
277-106-SK-23	Classroom sink, room 106	4.6		µg/L	
277-102-SK-24	Classroom sink, room 102	6.6		µg/L	
277-121CC-SK-25	Admin office sink, room 121CC	5.9		µg/L	
277-112-SK-26	Staff office sink, room 112	2.8		µg/L	
277-113-SK-27	Staff office sink, room 113	4.4		µg/L	
277-117-SK-28	Classroom sink, room 117	3.2		µg/L	
277-119-SK-29	Classroom sink, room 119	4.1		µg/L	
277-118-SK-30	Classroom sink, room 118	1.6		µg/L	
277-214-SK-31	Classroom sink, room 214	9.7		µg/L	
277-210-SK-32	Classroom sink, room 210	<0.1		µg/L	
277-201-SK-33	Classroom sink, room 201	2.9		µg/L	
277-202-SK-34	Classroom sink, room 202	7.1		µg/L	

<b>277-203-SK-35</b>	Classroom sink, room 203	8.0		µg/L	
<b>277-215B-SK-36</b>	Staff workroom sink, room 215B	1.9		µg/L	
<b>277-204-SK-37</b>	Classroom sink, room 204	8.2		µg/L	
<b>277-205-DF-38</b>	Drinking fountain, room 205	1.8		µg/L	
<b>277-206-SK-39</b>	Classroom sink, room 206, sink/fountain combination	2.0		µg/L	
<b>277-206-DF-40</b>	Drinking fountain, room 206, sink/fountain combination	1.0		µg/L	
<b>277-207-SK-41</b>	Classroom sink, room 207	1.2		µg/L	
<b>277-215-DF-42</b>	Drinking fountain, hallway 215, next to room 207, left bubbler	2.6		µg/L	
<b>277-215-DF-43</b>	Drinking fountain, hallway 215, next to room 207, right bubbler	3.7		µg/L	
<b>277-104A-DF-44</b>	Drinking fountain, south auditorium entrance 104A	22.7	N/A	µg/L	Removed

\*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.

\*2. Result less than 0.1 ppb which is the lowest level that can be reported by the external lab.