

Slavens Elementary (279) – 3000 S. Clayton St.

SY 2019/2020 Long Term Sampling – Action Level 10 µg/L

Sample Date: 02/13/2020

| Sample ID | Location Description | Lead Result (µg/L) |
|-------------------|---|--------------------|
| 279-123-SK01-01 | Kitchen prep sink, north wall | 1.3 |
| 279-123-SK02-01 | Kitchen sink, 3 compartment, left faucet | <1.0 ¹ |
| 279-123-SK03-01 | Kitchen sink, 3 compartment, right faucet | <1.0 |
| 279-124-DF01-01 | Drinking fountain, cafeteria, west wall | <1.0 |
| 279-115-DF01-01 | Drinking fountain, hallway 115, next to room 129 | <1.0 |
| 279-127-DF01-01 | Drinking fountain, hallway 127, next to gymnasium | <1.0 |
| 279-114E-SK01-01 | Nurse sink, room 114E | 1.7 |
| 279-114G-SK01-01 | Lounge sink, room 114G | 1.3 |
| 279-H100-DF01-01 | Drinking fountain, hallway H100, next to auditorium | 4.0 |
| 279-H100-BF01-01 | Bottle fill station, hallway H100, across from room 112 | <1.0 |
| 279-101-DF01-01 | Drinking fountain, classroom 101 | 2.8 |
| 279-102-DF01-01 | Drinking fountain, classroom 102 | 2.7 |
| 279-H100-DF02-01 | Drinking fountain, hallway H100, next to stair B | 3.7 |
| 279-108-DF01-01 | Drinking fountain/sink combo, classroom 108 | 4.5 |
| 279-103-DF01-01 | Drinking fountain/sink combo, classroom 103 | 3.3 |
| 279-H120-DF01-01 | Drinking fountain, hallway H120, across from H120A | 4.6 |
| 279-H200-BF02-01 | Bottle fill station, hallway H200, next to H200N | <1.0 |
| 279-H200-BF01-01 | Bottle fill station, hallway H200, next to stair B | <1.0 |
| 279-H200-DF01-01 | Drinking fountain, hallway H200, across from room 214 | 1.8 |
| 279-H100H-SK01-01 | Lounge sink, room H100H | <1.0 |

Sample ID Key:

Building number – room number – fixture type count – long term count

1. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

| Phase I Sampled on 9/20-21/2016 | | | | | |
|---------------------------------|--|-------------|------------------|-------|------------------------|
| Sample ID | Sample Description | Lead Result | Follow Up Result | Units | Action |
| 279-123-SK-01 | Kitchen sink, north wall | 1.5 | | µg/L | |
| 279-123-SK-02 | Kitchen sink, east wall | 1.8 | | µg/L | |
| 279-124-DF-03 | Drinking fountain, cafeteria, left bubbler | <1.0*1 | | µg/L | |
| 279-124-DF-04 | Drinking fountain, cafeteria, right bubbler | <1.0 | | µg/L | |
| 279-127-DF-05 | Drinking fountain, hallway 127, next to gym, left bubbler | <1.0 | | µg/L | |
| 279-127-DF-06 | Drinking fountain, hallway 127, next to gym, right bubbler | <1.0 | | µg/L | |
| 279-115-DF-07 | Drinking fountain, hallway 115, next to room 129, left bubbler | <1.0 | | µg/L | |
| 279-115-DF-08 | Drinking fountain, hallway 115, next to room 129, right bubbler | <1.0 | | µg/L | |
| 279-114E-SK-09 | Nurse sink, room 114E | 2.8 | | µg/L | |
| 279-H100-DF-10 | Drinking fountain, hallway H100, next to lobby, left bubbler | 2.4 | | µg/L | |
| 279-H100-DF-11 | Drinking fountain, hallway H100, next to lobby, right bubbler | 2.0 | | µg/L | |
| 279-H100H-SK-12 | Classroom sink, room H100H | 4.3 | | µg/L | |
| 279-H100-DF-13 | Drinking fountain, hallway H100, next to room 112, left bubbler | 8.6 | | µg/L | |
| 279-H100-DF-14 | Drinking fountain, hallway H100, next to room 112, right bubbler | 14.1 | | µg/L | |
| 279-101-DF-15 | Drinking fountain, room 101 | 2.6 | | µg/L | |
| 279-102-DF-16 | Drinking fountain, room 102 | 4.6 | | µg/L | |
| 279-H100-DF-17 | Drinking fountain, hallway H100, next to room 102, left bubbler | 4.1 | | µg/L | |
| 279-H100-DF-18 | Drinking fountain, hallway H100, next to room 102, right bubbler | 2.4 | | µg/L | |
| 279-108-DF-19 | Drinking fountain, room 108 | 5.3 | | µg/L | |
| 279-103-DF-20 | Drinking fountain, room 103 | 3.6 | | µg/L | |
| 279-H120-DF-21 | Drinking fountain, hallway H120, next to 120D, left bubbler | 4.2 | | µg/L | |
| 279-H120-DF-22 | Drinking fountain, hallway H120, next to 120D, right bubbler | 2.7 | | µg/L | |
| 279-104-DF-23 | Drinking fountain, room 104 | 8.3 | | µg/L | |
| 279-107-SK-24 | Classroom sink, room 107 | 33.2 | 11.5 | µg/L | Faucet replaced 3/2019 |
| 279-106-DF-25 | Drinking fountain, room 106 | 15.2 | N/A | µg/L | Removed |

| | | | | | |
|---------------------------------------|--|------|------|------|---|
| 279-105-DF-26 | Drinking fountain, room 105 | 9.3 | | µg/L | |
| 279-H200-DF-27 | Drinking fountain, hallway H200, next to room 203, right bubbler | 3.7 | | µg/L | |
| 279-H200-DF-28 | Drinking fountain, hallway H200, next to room 208, left bubbler | 2.0 | | µg/L | |
| Phase II Sampled on 12/13/2016 | | | | | |
| 279-113-SK-29 | Classroom sink, room 113 | 3.0 | | µg/L | |
| 279-112-SK-30 | Classroom sink, room 112 | 5.0 | | µg/L | |
| 279-111-SK-31 | Classroom sink, room 111 | 4.0 | | µg/L | |
| 279-110-SK-32 | Classroom sink, room 110 | 3.0 | | µg/L | |
| 279-109-SK-33 | Classroom sink, room 109 | 8.0 | | µg/L | |
| 279-108-SK-34 | Classroom sink, room 108 | 6.0 | | µg/L | |
| 279-106-SK-35 | Classroom sink, room 106 | 10.0 | | µg/L | |
| 279-105-SK-36 | Classroom sink, room 105 | 4.0 | | µg/L | |
| 279-104-SK-37 | Classroom sink, room 104 | 8.0 | | µg/L | |
| 279-103-SK-38 | Classroom sink, room 103 | 2.0 | | µg/L | |
| 279-102-SK-39 | Classroom sink, room 102 | 3.0 | | µg/L | |
| 279-101-SK-40 | Classroom sink, room 101 | 3.0 | | µg/L | |
| 279-116-SK-41 | Classroom sink, room 116 | <1.0 | | µg/L | |
| 279-134-SK-42 | Classroom sink, room 134 | <1.0 | | µg/L | |
| 279-117-SK-43 | Classroom sink, room 117 | <1.0 | | µg/L | |
| 279-118-SK-44 | Classroom sink, room 118 | 2.0 | | µg/L | |
| 279-120-SK-45 | Classroom sink, room 120 | <1.0 | | µg/L | |
| 279-121-SK-46 | Classroom sink, room 121 | <1.0 | | µg/L | |
| 279-126-SK-47 | Classroom sink, room 126 | <1.0 | | µg/L | |
| 279-128OA-SK-48 | Gym office sink, room 128DA | <1.0 | | µg/L | |
| 279-124A-SK-49 | Office sink, room 124A | <1.0 | | µg/L | |
| 279-204-SK-50 | Classroom sink, room 204 | 5.0 | | µg/L | |
| 279-205-SK-51 | Classroom sink, room 205 | 7.0 | | µg/L | |
| 279-203-SK-52 | Classroom sink, room 203 | 3.0 | | µg/L | |
| 279-206-SK-53 | Classroom sink, room 206 | 4.0 | | µg/L | |
| 279-202-SK-54 | Classroom sink, room 202 | 17.0 | 22.8 | µg/L | Faucet replaced 11/2018, Cleaning only notice |
| 279-201-SK-55 | Classroom sink, room 201 | 3.0 | | µg/L | |
| 279-H200C-SK-56 | Office sink, room H200C | 4.0 | | µg/L | |
| 279-209-SK-57 | Classroom sink, room 209 | 9.0 | | µg/L | |
| 279-210-SK-58 | Classroom sink, room 210 | <1.0 | | µg/L | |

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.