

Swansea Elementary (280) – 4650 N. Columbine St.

SY 2019/2020 Long Term Sampling – Action Level 10 µg/L

Sample Date: 02/28/2020

Sample ID	Description	Lead Result (µg/L)
280-122-SK01-01	Kitchen sink, 3 compartment, left faucet	<1.0 ¹
280-122-SK02-01	Kitchen sink, 3 compartment, right faucet	1.4
280-122-SK03-01	Kitchen prep sink, west wall	<1.0
280-117-BF01-01	Bottle fill station, hallway 117, across from auditorium	<1.0
280-120-DF01-01	Drinking fountain, gymnasium	1.3
280-123-DF01-01	Drinking fountain, hallway 123, across from room 136	7.9
280-147-DF01-01	Drinking fountain, hallway 147, across from room 157	4.8
280-149-DF01-01	Drinking fountain, room 149	<1.0
280-150-DF01-01	Drinking fountain, room 150	<1.0
280-151-BF01-01	Bottle fill station, hallway 151, across from room 155	<1.0
280-159-DF01-01	Drinking fountain, hallway 159	1.4
280-101G-SK01-01	Nurse sink, room 101G	<1.0
280-102-SK01-01	Lounge sink, room 102	1.8
280-105-DF01-01	Drinking fountain, hallway 105, left fountain	<1.0
280-105-DF02-01	Drinking fountain, hallway 105, right fountain	3.4
280-110-SK01-01	Lounge sink, room 110	1.1

Sample ID Key:

Building number – room number – fixture type count – long term count

1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/20/2016

Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
280-lr-df-01	Drinking fountain, cafeteria, north end	>50.0	2.0	µg/L	Bubbler replaced 5/2018, Filter installed 2/2019
280-lra-SK-02	Sink, PTA kitchen	2.0		µg/L	
280-GYM-DF-03	Drinking fountain, gym	3.4		µg/L	
280-H130-DF-04	Drinking fountain, hallway H130, next to auditorium, left bubbler	2.8		µg/L	
280-H130-DF-05	Drinking fountain, hallway H130, next to auditorium, right bubbler	<1.0*1		µg/L	
280-H140A-SK-06	Lounge sink, room H140-A	<1.0		µg/L	
280-H120-DF-07	Drinking fountain, hallway H120, next to room 108, left bubbler	<1.0		µg/L	
280-H120-DF-08	Drinking fountain, hallway H120, next to room 108, left bubbler	<1.0		µg/L	
280-111B-DF-09	Drinking fountain, hallway 111B, next to room 111	12.1		µg/L	
280-H110-DF-10	Drinking fountain, hallway H110, next to room 112, left bubbler	3.4		µg/L	
280-130-DF-11	Drinking fountain, room 130	<1.0		µg/L	
280-131-DF-12	Drinking fountain, room 131	<1.0		µg/L	
280H100-DF-13	Drinking fountain, hallway H100, next to room 125, left bubbler	4.0		µg/L	
280-H100-DF-14	Drinking fountain, hallway H100, next to room 125, right bubbler	5.7		µg/L	
280-OFFB-SK-15	Sink, admin office B	2.4		µg/L	
280-KITA-SK-16	Kitchen sink, room KITA	2.1		µg/L	
280-KIT-SK-17	Kitchen sink, south wall, left	6.6		µg/L	
280-KIT-SK-18	Kitchen sink, south wall, right	1.3		µg/L	

Phase II Sampled on 3/8/2017

280-H150F-SK-19	Admin office sink, room H150F	3.0		µg/L	
280-126-SK-20	Classroom sink, room 126	2.0		µg/L	
280-127-SK-21	Classroom sink, room 127	2.0		µg/L	
280-125-SK-22	Classroom sink, room 125	1.0		µg/L	
280-124-SK-23	Classroom sink, room 124	<1.0		µg/L	
280-123-SK-24	Classroom sink, room 123	<1.0		µg/L	
280-122-SK-25	Classroom sink, room 122	1.0		µg/L	

280-121-SK-26	Classroom sink, room 121	1.0		µg/L	
280-120-SK-27	Classroom sink, room 120	2.0		µg/L	
280-119-SK-28	Classroom sink, room 119	2.0		µg/L	
280-118-SK-29	Classroom sink, room 118	3.0		µg/L	
280-117-SK-30	Classroom sink, room 117	<1.0		µg/L	
280-116-SK-31	Classroom sink, room 116	<1.0		µg/L	
280-130-SK-32	Classroom sink, room 130, southwest corner	3.0		µg/L	
280-130-SK-33	Classroom sink, room 130, southeast corner	<1.0		µg/L	
280-131-SK-34	Classroom sink, room 131, southwest corner	1.0		µg/L	
280-131-SK-35	Classroom sink, room 131, southeast corner	<1.0		µg/L	
280-100-SK-36	Conference room sink, room 100	22.0	N/A	µg/L	Fixed kitchenette unit; no drinking notice
280-112-SK-37	Classroom sink, room 112	5.0		µg/L	
280-115-SK-38	Classroom sink, room 115	6.0		µg/L	
280-114-SK-39	Classroom sink, room 114	12.0		µg/L	
280-113-SK-40	Classroom sink, room 113	8.0		µg/L	
280-110-SK-41	Classroom sink, room 110	15.0	N/A	µg/L	Sink removed 2017 with remodel
280-109-SK-42	Classroom sink, room 109	11.0		µg/L	
280-111-SK-43	Classroom sink, room 111	6.0		µg/L	
280-108-SK-44	Classroom sink room 108	<1.0		µg/L	
280-107-SK-45	Classroom sink, room 107	<1.0		µg/L	
280-106-SK-46	Classroom sink, room 106	<1.0		µg/L	
280-105-SK-47	Classroom sink, room 105	<1.0		µg/L	
280-104-SK-48	Classroom sink, room 104	<1.0		µg/L	
280-103-SK-49	Classroom sink, room 103	3.0		µg/L	
280-102-SK-50	Classroom sink, room 102	<1.0		µg/L	
280-101-SK-51	Classroom sink, room 101	<1.0		µg/L	
280-TL-SK-52	Faculty lounge sink, room TL	7.0		µg/L	
280-LMCA-SK-53	LMC/IMC office sink, room LMCA	7.0		µg/L	
280-LMCB-SK-54	LMC/IMC office sink, room LMCB	15.0	1.0	µg/L	Faucet replaced 10/2018

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.