

Kunsmiller (409) – 2250 S. Quitman Way

SY 2019/2020 Long Term Sampling – Action Level 10 µg/L

Sample Date: 01/29/2020

Sample ID	Location Description	Lead Result (µg/L)	Action
409-107-SK01-01	Kitchen sink, south wall, left faucet	6.5	
409-107-SK02-01	Kitchen sink, south wall, right faucet	2.3	
409-107-SK03-01	Kitchen prep sink, room 107, southwest corner	<1.0 ¹	
409-001-DF01-01	Drinking fountain, hallway 001, next to room 009	<1.0	
409-006-DF01-01	Drinking fountain, hallway 006, next to stair K	<1.0	
409-01-DF01-01	Drinking fountain, hallway 01, next to room 06	3.8	
409-05-DF01-01	Drinking fountain, room 05	<1.0	
409-03-DF01-01	Drinking fountain, room 03	<1.0	
409-100-DF02-01	Drinking fountain, hallway 100, next to room 123	1.0	
409-100-DF01-01	Drinking fountain, hallway 100, across from room 131	12.5	Shut down, POU filter pending
409-101G-SK01-01	Nurse sink, room 101G	7.0	
409-103-DF02-01	Drinking fountain, hallway 103, next to room 103H	<1.0	
409-108-DF01-01	Drinking fountain, cafeteria, northwest corner	4.4	
409-103-DF03-01	Drinking fountain, hallway 103, across from elevator	<1.0	
409-110-DF01-01	North gymnasium fountain, south wall	<1.0	
409-203-DF02-01	Drinking fountain, hallway 203, across from room 205	7.9	
409-203-DF01-01	Drinking fountain, hallway 203, next to room 203C	<1.0	
409-200-DF01-01	Drinking fountain, hallway 200, across from room 229	13.0	Shut down, Bottle fill station pending
409-200-DF02-01	Drinking fountain, hallway 200, next to room 222A	1.9	
409-101F-SK01-01	Nurse restroom sink, room 101F	11.0	Flush notice, Faucet replacement pending

Sample ID Key:

Building number – room number – fixture type count – long term count

1. Result less than 1.0 µg/L, which is the lowest level that can be reported by the lab.

Phase I & II Sampling – Action Level 15 µg/L

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 10/28/2016

Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
409-19-DF-01	Drinking fountain, hallway 19, next to room 8	0.4		µg/L	
409-01-DF-02	Drinking fountain, hallway 01, next to room 06, left bubbler	1.9		µg/L	
409-01-DF-03	Drinking fountain, hallway 01, next to room 06, right bubbler	1.7		µg/L	
409-03-DF-04	Drinking fountain, room 03	0.6		µg/L	
409-100-DF-05	Drinking fountain, hallway 100, next to room 123, left bubbler	1.7		µg/L	
409-100-DF-06	Drinking fountain, hallway 100, next to room 123, right bubbler	1.6		µg/L	
409-100-DF-07	Drinking fountain, hallway 100, across from room 131, left bubbler	9.3		µg/L	
409-100-DF-08	Drinking fountain, hallway 100, across from room 131, right bubbler	9.4		µg/L	
409-101F-SK-09	Nurse sink, room 101F	6.8		µg/L	
409-103-DF-10	Drinking fountain, hallway 103, next to room 104, left bubbler	2.6		µg/L	
409-103-DF-11	Drinking fountain, hallway 103, next to room 104, right bubbler	2.0		µg/L	
409-103-DF-12	Drinking fountain, hallway 103, next to room 103H, left bubbler	>50.0	10.0	µg/L	Bubbler replaced 11/2018
409-103-DF-13	Drinking fountain, hallway 103, next to room 103H, right bubbler	>50.0	5.0	µg/L	Bubbler replaced 11/2018
409-107-SK-14	Kitchen prep sink, room 107, southwest corner	0.7		µg/L	
409-107-SK-15	Kitchen kettle fill, room 107, center of room	5.3		µg/L	
409-108-DF-16	Drinking fountain, cafeteria room 108, northwest corner, left bubbler	15.0	4.0	µg/L	Bubbler replaced 2/2018
409-108-DF-17	Drinking fountain, cafeteria room 108, northwest corner, right bubbler	5.4		µg/L	
409-108-DF-18	Drinking fountain, cafeteria room 108, northeast corner, left bubbler	6.7		µg/L	
409-108-DF-19	Drinking fountain, cafeteria room 108, northeast corner, right bubbler	1.9		µg/L	
409-103-DF-20	Drinking fountain, hallway 103, across from elevator/cafeteria, left bubbler	13.3		µg/L	
409-103-DF-21	Drinking fountain, hallway 103, across from elevator/cafeteria, right bubbler	40.7	2.0	µg/L	Bubbler replaced 2/2018

409-200-DF-22	Drinking fountain, hallway 200, next to room 222A, left bubbler	0.1*	µg/L
409-200-DF-23	Drinking fountain, hallway 200, next to room 222A, right bubbler	0.1	µg/L
409-200-DF-24	Drinking fountain, hallway 200, across from room 229, left bubbler	7.2	µg/L
409-200-DF-25	Drinking fountain, hallway 200, across from room 229, right bubbler	3.9	µg/L
409-203-DF-26	Drinking fountain, hallway 203, next to room 203C, left bubbler	10.9	µg/L
409-203-DF-27	Drinking fountain, hallway 203, next to room 203C, right bubbler	10.5	µg/L
409-203-DF-28	Drinking fountain, hallway 203, across from room 205, left bubbler	3.3	µg/L
409-203-DF-29	Drinking fountain, hallway 203, across from room 205, right bubbler	3.1	µg/L

Phase II Sampled on 9/19 & 20/2017

409-009-SK-30	Classroom sink, room 009	0.8	µg/L	
409-009-DF-31	Drinking fountain, hallway 001, next to room 009	0.2	µg/L	
409-02-SK-32	Classroom sink, room 02	2.0	µg/L	
409-03-SK-33	Classroom sink, room 03	1.9	µg/L	
409-09-SK-34	Classroom sink, room 09	1.4	µg/L	
409-07-SK-35	Classroom sink, room 07	1.1	µg/L	
409-06-SK-36	Classroom sink, room 06	1.0	µg/L	
409-05-SK-37	Classroom sink, room 05	8.5	µg/L	
409-04B-SK-38	Hand sink, room 04B	1.1	µg/L	
409-129-SK-39	Classroom sink, room 129	4.2	µg/L	
409-128-SK-40	Classroom sink, room 128	26.2	12.0 µg/L	Faucet replaced 2/2018
409-115-SK-41	Classroom sink, room 115	28.5	6.0 µg/L	Faucet replaced 2/2018
409-112-SK-42	Faculty lounge sink, room 112	5.9	µg/L	
409-007-SK-43	Art room sink, room 007, left sink	1.8	µg/L	
409-007-SK-44	Art room sink, room 007, center sink	1.1	µg/L	
409-007-SK-45	Art room sink, room 007, right sink	1.0	µg/L	
409-08-SK-46	Classroom sink, room 08	0.9	µg/L	
409-104-SK-47	Classroom sink, room 104	0.2	µg/L	
409-217-SK-48	Science lab sink, room 217, demonstration sink	0.3	µg/L	
409-217-SK-49	Science lab sink, room 217, first row from front, west island	1.5	µg/L	
409-217-SK-50	Science lab sink, room 217, second row from front, west island	1.3	µg/L	
409-217-SK-51	Science lab sink, room 217, third row from front, west island	1.0	µg/L	

409-217-SK-52	Science lab sink, room 217, fourth row from front, west island	5.5		µg/L	
409-217-SK-53	Science lab sink, room 217, fifth row from front, west island	1.1		µg/L	
409-217-SK-54	Science lab sink, room 217, second row from front, east island	0.6		µg/L	
409-217-SK-55	Science lab sink, room 217, third row from front, east island	1.3		µg/L	
409-217-SK-56	Science lab sink, room 217, fourth row from front, east island	1.7		µg/L	
409-217-SK-57	Science lab sink, room 217, fifth row from front, east island	0.9		µg/L	
409-230-SK-58	LMC/IMC sink, room 230	5.3		µg/L	
409-205-SK-59	Classroom sink, room 205, north wall, left sink	8.5		µg/L	
409-205-SK-60	Classroom sink, room 205, north wall, right sink	19.4	8.0	µg/L	Faucet replaced 2/2018
409-207-SK-61	Classroom sink, room 207	3.2		µg/L	
409-212-SK-62	Classroom sink, room 212, south wall	3.1		µg/L	
409-212-SK-63	Classroom sink, room 212, west wall	2.0		µg/L	
409-212-SK-64	Classroom sink, room 212, north wall, left sink	11.4		µg/L	
409-212-SK-65	Classroom sink, room 212, north wall, center sink	5.5		µg/L	
409-212-SK-66	Classroom sink, room 212, north wall, right sink	13.3		µg/L	
409-211-SK-67	Classroom sink, room 211	6.0		µg/L	
409-210-SK-68	Classroom sink, room 210	19.3	21.0	µg/L	Failed – no drinking notice; Faucet replaced 2/2018
409-23-SK-69	Classroom sink, room 23, north wall, far left sink, left faucet	1.5		µg/L	
409-23-SK-70	Classroom sink, room 23, north wall, far left sink, right faucet	1.3		µg/L	
409-23-SK-71	Classroom sink, room 23, north wall, center left sink	0.4		µg/L	
409-23-SK-72	Classroom sink, room 23, north wall, center right sink	0.3		µg/L	
409-23-SK-73	Classroom sink, room 23, north wall, far right sink	0.8		µg/L	
409-26-SK-74	Classroom sink, room 26, south wall, left sink	0.4		µg/L	
409-26-SK-75	Classroom sink, room 26, south wall, center sink	0.5		µg/L	
409-26-SK-76	Classroom sink, room 26, south wall, right sink, right faucet	1.4		µg/L	
409-26-SK-77	Classroom sink, room 26, south wall, right sink, left faucet	1.3		µg/L	

*Result less than 0.1 ppb which is the lowest level that can be reported by the lab.