

## DSST – GVR Middle School @ Evie Dennis Campus Bldg. #3 (443)

All results <15 ppb – No further action at this time.

### Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

| Phase I Sampled on 10/11/2016 |  |             |       |        |
|-------------------------------|--|-------------|-------|--------|
| Sample ID                     | Sample Description   | Lead Result | Units | Action |
| 443-110-SK-01                 | Faculty workroom sink, room 3-110                                  | 1.4         | µg/L  |        |
| 443-135-DF-04                 | Drinking fountain, hallway 3-135, next to restrooms, left bubbler  | 1.6         | µg/L  |        |
| 443-135-DF-05                 | Drinking fountain, hallway 3-135, next to restrooms, right bubbler | 1.7         | µg/L  |        |
| 443-222-DF-06                 | Drinking fountain, hallway 3-222, next to restrooms, left bubbler  | 1.2         | µg/L  |        |
| 443-222-DF-07                 | Drinking fountain, hallway 3-222, next to restrooms, right bubbler | 1.2         | µg/L  |        |
| 443-201-DF-08                 | Drinking fountain, lobby 3-201, next to room 3-202, left bubbler   | 1.1         | µg/L  |        |
| 443-201-DF-09                 | Drinking fountain, lobby 3-201, next to room 3-202, right bubbler  | 1.1         | µg/L  |        |
| Phase II Sampled on 5/12/2017 |  |             |       |        |
| 443-3-114-SK-10               | Classroom sink, room 114, left sink                                | 1.0         | µg/L  |        |
| 443-3-114-SK-11               | Classroom sink, room 114, right sink                               | 1.0         | µg/L  |        |

Sample number 02 & 03 not collected due to inoperable fixtures at the time of sampling.