

Northfield High School Bldg. #2 at Paul Sandoval Campus (519)

All results <15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 11/9/2016				
Sample ID	Sample Description	Lead Result	Units	Action
519-125-DF-01	Drinking fountain, hallway 125, next to room 134, left bubbler	<1.0*	µg/L	
519-125-DF-02	Drinking fountain, hallway 125, next to room 134, right bubbler	<1.0	µg/L	
519-125-BF-03	Bottle fill, hallway 125, next to room 134	<1.0	µg/L	
519-138-SK-04	Classroom room sink, room 138	<1.0	µg/L	
519-125-DF-05	Drinking fountain, hallway 125, next to room 130, left bubbler	<1.0	µg/L	
519-125-DF-06	Drinking fountain, hallway 125, next to room 130, right bubbler	<1.0	µg/L	
519-125-BF-07	Bottle fill, hallway 125, next to room 130	<1.0	µg/L	
519-139-DF-08	Drinking fountain, room 139, west wall	<1.0	µg/L	
519-100-DF-09	Drinking fountain, hallway 100, next to room 124, left bubbler	<1.0	µg/L	
519-100-DF-10	Drinking fountain, hallway 100, next to room 124, right bubbler	<1.0	µg/L	
519-100-BF-11	Bottle fill, hallway 100, next to room 124	<1.0	µg/L	
519-103-SK-12	Nurse sink, room 103	<1.0	µg/L	
519-105-DF-13	Drinking fountain, hallway 105, next to room 118, left bubbler	<1.0	µg/L	
519-105-DF-14	Drinking fountain, hallway 105, next to room 118, right bubbler	<1.0	µg/L	
519-105-BF-15	Bottle fill, hallway 105, next to room 118	<1.0	µg/L	
519-107-DF-16	Drinking fountain, room 107 east wall	<1.0	µg/L	
519-105-DF-17	Drinking fountain, hallway 105, next to room 110, left bubbler	<1.0	µg/L	
519-105-DF-18	Drinking fountain, hallway 105, next to room 110, right bubbler	<1.0	µg/L	
519-105-BF-19	Bottle fill, hallway 105, next to room 110	<1.0	µg/L	
519-202-DF-20	Drinking fountain, hallway 202, next to room 207, left bubbler	<1.0	µg/L	
519-202-DF-21	Drinking fountain, hallway 202, next to room 207, right bubbler	<1.0	µg/L	
519-202-BF-22	Bottle fill, hallway 202, next to room 207	<1.0	µg/L	
519-202-DF-23	Drinking fountain, hallway 202, next to room 214, left bubbler	<1.0	µg/L	
519-202-DF-24	Drinking fountain, hallway 202, next to room 214, right bubbler	<1.0	µg/L	
519-202-BF-25	Bottle fill, hallway 202, next to room 214	<1.0	µg/L	
519-215-SK-26	Workroom sink, room 215	<1.0	µg/L	
519-200-DF-27	Drinking fountain, hallway 200, next to room 218, left bubbler	<1.0	µg/L	
519-200-DF-28	Drinking fountain, hallway 200, next to room 218, right bubbler	<1.0	µg/L	
519-200-BF-29	Bottle fill, hallway 200, next to room 218	<1.0	µg/L	
519-224-SK-30	Workroom sink, room 224	<1.0	µg/L	
519-221-DF-31	Drinking fountain, hallway 221, next to room 226, left bubbler	<1.0	µg/L	
519-221-DF-32	Drinking fountain, hallway 221, next to room 226, right bubbler	<1.0	µg/L	
519-221-BF-33	Bottle fill, hallway 221, next to room 226	<1.0	µg/L	

519-221-DF-34	Drinking fountain, hallway 221, next to room 230, left bubbler	<1.0	µg/L
519-221-DF-35	Drinking fountain, hallway 221, next to room 230, right bubbler	<1.0	µg/L
519-221-BF-36	Bottle fill, hallway 221, next to room 230	<1.0	µg/L
Phase II Sampled on 10/11/2017			
519-139-SK-37	Classroom sink, room 139, left sink	3.2	µg/L
519-139-SK-38	Classroom sink, room 139, right sink	0.2	µg/L
519-107-SK-39	Art room sink, room 107, west wall, left sink	0.2	µg/L
519-107-SK-40	Art room sink, room 107, west wall, right sink	0.2	µg/L
519-204-SK-41	Science lab sink, room 204, east wall	0.3	µg/L
519-204-SK-42	Science lab sink, room 204, south wall, left sink	0.2	µg/L
519-204-SK-43	Science lab sink, room 204, south wall, right sink	0.3	µg/L
519-204-SK-44	Science lab sink, room 204, west wall	0.3	µg/L
519-203-SK-45	Science prep room sink, room 203	1.1	µg/L
519-201-SK-46	Science lab sink, room 201, north wall, left sink	0.4	µg/L
519-201-SK-47	Science lab sink, room 201, north wall, right sink	0.3	µg/L
519-201-SK-48	Science lab sink, room 201, west wall, left sink	0.4	µg/L
519-201-SK-49	Science lab sink, room 201, west wall, center sink	0.3	µg/L
519-201-SK-50	Science lab sink, room 201, west wall, right sink	0.6	µg/L
519-201-SK-51	Science lab sink, room 201, south wall, left sink	0.3	µg/L
519-201-SK-52	Science lab sink, room 201, south wall, center sink	0.2	µg/L
519-201-SK-53	Science lab sink, room 201, south wall, right sink	0.2	µg/L
519-237-SK-54	Science lab sink, room 237, north wall, left sink	0.3	µg/L
519-237-SK-55	Science lab sink, room 237, north wall, center sink	0.3	µg/L
519-237-SK-56	Science lab sink, room 237, north wall, right sink	0.4	µg/L
519-237-SK-57	Science lab sink, room 237, west wall, left sink	0.2	µg/L
519-237-SK-58	Science lab sink, room 237, west wall, center sink	0.4	µg/L
519-237-SK-59	Science lab sink, room 237, west wall, right sink	0.2	µg/L
519-237-SK-60	Science lab sink, room 237, south wall, left sink	0.2	µg/L
519-237-SK-61	Science lab sink, room 237, south wall, right sink	0.2	µg/L
519-236-SK-62	Science prep room sink, room 236	0.5	µg/L
519-235-SK-63	Science lab sink, room 235, west wall	0.8	µg/L
519-235-SK-64	Science lab sink, room 235, west wall, left sink	0.4	µg/L
519-235-SK-65	Science lab sink, room 235, west wall, right sink	0.6	µg/L
519-235-SK-66	Science lab sink, room 235, east wall	0.6	µg/L

*Result less than 1.0 ppb which is the lowest level that can be reported by the lab.