

Hilltop Transportation Building (893) – Sampled 11/10/2016

All results <15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Sample ID	Sample Description	Lead Result	Units	Action
893E-111A-SK-01	Building E, breakroom sink, room 111A	<1.0*	µg/L	
893E-111-SK-02	Building E, breakroom sink, room 111	<1.0	µg/L	
893E-H119-DF-03	Building E, drinking fountain, hallway H119, across from room 114, left bubbler	<1.0	µg/L	
893E-H119-DF-04	Building E, drinking fountain, hallway H119, across from room 114, right bubbler	<1.0	µg/L	
893C-111-DF-05	Building C, drinking fountain, hallway 111, across from room B104	3.0	µg/L	
893B-105-DF-06	Building B, drinking fountain, hallway 105, across from room 109, left bubbler	<1.0	µg/L	
893B-105-DF-07	Building B, drinking fountain, hallway 105, across from room 109, right bubbler	<1.0	µg/L	
893B-104-SK-08	Building B, breakroom sink, room 104	<1.0	µg/L	
893D-101-DF-09	Building D, drinking fountain, room 101	1.0	µg/L	

*Result less than 1.0 ppb which is the lowest level that can be reported by the lab.