

## Evie Dennis Campus Bldg. #1 (981)

All results <15 ppb – No further action at this time.

**Sample ID Key:**

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 10/7/2016				
Sample ID	Sample Description	Lead Result	Units	Action
981-1-135-SK-01	Kitchen prep sink, west wall	0.6	µg/L	
981-1-135-SK-02	Kitchen sink, east wall	0.6	µg/L	
981-1-131-DF-03	Drinking fountain, west all-purpose area room 1-131, next to 1-128, left bubbler	0.2	µg/L	
981-1-131-DF-04	Drinking fountain, west all-purpose area room 1-131, next to 1-128, right bubbler	0.2	µg/L	
981-1-128-SK-05	PTA kitchen sink, room 1-128	0.3	µg/L	
981-1-149-DF-06	Drinking fountain, east all-purpose area room 1-149, next to 1-128, left bubbler	0.4	µg/L	
981-1-149-DF-07	Drinking fountain, east all-purpose area room 1-149, next to 1-128, right bubbler	<0.1*	µg/L	
981-1-104-DF-08	Drinking fountain, hallway 1-104, next to east restrooms, left bubbler	1.5	µg/L	
981-1-104-DF-09	Drinking fountain, hallway 1-104, next to east restrooms, right bubbler	1.0	µg/L	
981-1-104-DF-10	Drinking fountain, hallway 1-104, next to west restrooms, left bubbler	1.3	µg/L	
981-1-104-DF-11	Drinking fountain, hallway 1-104, next to west restrooms, right bubbler	1.8	µg/L	
981-1-157-SK-12	Nurse sink, room 1-157, south wall	2.9	µg/L	
981-1-122-SK-13	Nurse sink, room 1-122, south wall	0.9	µg/L	
981-1-123-SK-14	Nurse sink, room 1-123, north wall	0.8	µg/L	
981-1-124-SK-15	Nurse sink, room 1-124, south wall	0.6	µg/L	
981-1-125-SK-16	Nurse sink, room 1-125, north wall	0.8	µg/L	
981-1-212-DF-21	Drinking fountain, hallway 1-212, next to room 1-210, left bubbler	<0.1	µg/L	
981-1-212-DF-22	Drinking fountain, hallway 1-212, next to room 1-210, right bubbler	0.1	µg/L	
Phase II Sampled on 5/12/2017				
981-1-022-DF-23	Drinking fountain, hallway 1-022, next to room 1-013, left bubbler	<1.0	µg/L	
981-1-022-DF-24	Drinking fountain, hallway 1-022, next to room 1-013, right bubbler	<1.0	µg/L	
981-1-119-SK-25	Nurse sink, room 1-119	<1.0	µg/L	
981-1-156A-SK-26	Nurse sink, room 1-156A	<1.0	µg/L	
981-1-154A-SK-27	Nurse sink, room 1-154A	1.0	µg/L	

\*1. Result less than 0.1 ppb which is the lowest level that can be reported by the external lab.

\*2. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.

Sample numbers 17-20 not collected during phase I to inoperable fixtures at the time of sampling.