

Lalo Delgado (982)

All results <15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 10/26/2016				
Sample ID	Sample Description	Lead Result	Units	Action
982-02B-SK-01	Nurse sink, room 02B	<1.0*	µg/L	
982-02-SK-02	Admin office sink, room 02	<1.0	µg/L	
982-02-DF-03	Bottle fill, admin office, room 02	<1.0	µg/L	
982-01-DF-04	Drinking fountain, hallway 01, across from room 12, left bubbler	<1.0	µg/L	
982-01-DF-05	Drinking fountain, hallway 01, across from room 12, right bubbler	<1.0	µg/L	
982-14-DF-06	Drinking fountain, hallway 14, next to room 16, left bubbler	<1.0	µg/L	
982-14-DF-07	Drinking fountain, hallway 14, next to room 16, right bubbler	<1.0	µg/L	
982-116A-SK-08	Kitchen sink, room 116A, south side of center wall	<1.0	µg/L	
982-116A-SK-09	Kitchen sink, room 116A, north side of center wall	<1.0	µg/L	
982-118-DF-10	Drinking fountain, hallway 118, across from room 124	2.0	µg/L	
982-101J-SK-11	Faculty lounge sink, room 101J	<1.0	µg/L	
982-101-SK-12	Admin office sink, room 101, across from room 101C	1.0	µg/L	
982-101-DF-13	Bottle fill, admin office, room 101, across from room 101C	<1.0	µg/L	
982-101H-SK-14	Nurse sink, room 101H	<1.0	µg/L	
982-100-DF-15	Drinking fountain, hallway 100, next to room 103, left bubbler	<1.0	µg/L	
982-100-DF-16	Drinking fountain, hallway 100, next to room 103, right bubbler	<1.0	µg/L	
982-118-DF-17	Drinking fountain, hallway 118, next to room 121, left bubbler	4.0	µg/L	
982-118-DF-18	Drinking fountain, hallway 118, next to room 121, right bubbler	4.0	µg/L	
982-115-SK-19	Faculty lounge sink, room 115	6.0	µg/L	
982-115-DF-20	Drinking fountain, room 115	<1.0	µg/L	
982-200-DF-21	Drinking fountain, hallway 200, next to room 216, left bubbler	<1.0	µg/L	
982-200-DF-22	Drinking fountain, hallway 200, next to room 216, right bubbler	<1.0	µg/L	
982-201-DF-23	Drinking fountain, hallway 201, across from room 211, left bubbler	<1.0	µg/L	
982-201-DF-24	Drinking fountain, hallway 201, across from room 211, right bubbler	<1.0	µg/L	
Phase II Sampled on 9/20/2017				
982-11-SK-25	Classroom sink, room 11	0.4	µg/L	
982-117-SK-26	Science lab sink, room 117, north wall, right sink	1.4	µg/L	
982-117-SK-27	Science lab sink, room 117, north wall, left sink	0.5	µg/L	
982-117-SK-28	Science lab sink, room 117, west wall	0.4	µg/L	
982-117-SK-29	Science lab sink, room 117, south wall	0.3	µg/L	
982-119-SK-30	Science lab sink, room 119, south island sink	1.9	µg/L	
982-119-SK-31	Science lab sink, room 119, north island sink	5.7	µg/L	

982-119-SK-32	Science lab sink, room 119, west wall, right sink	0.4	µg/L
982-119-SK-33	Science lab sink, room 119, west wall, left sink	0.3	µg/L
982-119A-SK-34	Science prep room sink, room 119A, south wall	0.4	µg/L
982-119A-SK-35	Science prep room sink, room 119A, west wall	2.5	µg/L
982-120-SK-36	Science lab sink, room 120, southeast island sink	3.2	µg/L
982-120-SK-37	Science lab sink, room 120, south center island sink	0.4	µg/L
982-120-SK-38	Science lab sink, room 120, southwest island sink	12	µg/L
982-120-SK-39	Science lab sink, room 120, northeast island sink	5.1	µg/L
982-120-SK-40	Science lab sink, room 120, north center island sink	1.7	µg/L
982-120-SK-41	Science lab sink, room 120, northwest island sink	1.9	µg/L
982-120-SK-42	Science lab sink, room 120, north wall, right sink	1.7	µg/L
982-120-SK-43	Science lab sink, room 120, north wall, left sink	1.2	µg/L
982-126-SK-44	Science lab sink, room 126, east wall	1.1	µg/L
982-126-SK-45	Science lab sink, room 126, north wall	1.2	µg/L
982-126-SK-46	Science lab sink, south wall, right sink	0.2	µg/L
982-126-SK-47	Science lab sink, south wall, left sink	0.3	µg/L
982-210-SK-48	Classroom sink, room 210	0.2	µg/L

*Result less than 1.0 ppb which is the lowest level that can be reported by the lab.