

## Amesse Elementary (292)

**Sample ID Key:**

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/23/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
292-105-sk-01	Kitchen sink, west wall, left faucet	13.0		µg/L	
292-105-SK-02	Kitchen sink, west wall, center faucet	1.6		µg/L	
292-105-SK-03	Kitchen sink, west wall, right faucet	<1.0* <sup>1</sup>		µg/L	
292-106-DF-04	Drinking fountain, cafeteria, west wall, left bubbler	2.4		µg/L	
292-106-DF-05	Drinking fountain, cafeteria, west wall, right bubbler	1.3		µg/L	
292-106-DF-06	Drinking fountain, cafeteria, east wall, left bubbler	2.8		µg/L	
292-106-DF-07	Drinking fountain, cafeteria, east wall, right bubbler	4.1		µg/L	
292-109-DF-08	Drinking fountain, gymnasium, east wall, left fixture	4.3		µg/L	
292-109-DF-09	Drinking fountain, gymnasium, east wall, right fixture	3.3		µg/L	
292-101B-SK-10	Admin office sink, room 101B	<1.0		µg/L	
292-107-SK-11	Staff lounge sink, room 107	1.0		µg/L	
292-100-DF-12	Drinking fountain, hallway 100, next to room 101B	<1.0		µg/L	
292-114-DF-13	Drinking fountain, hallway 114, outside of auditorium	1.5		µg/L	
292-117-DF-14	Drinking fountain, hallway 117, next to room 142, left bubbler	1.0		µg/L	
292-117-DF-15	Drinking fountain, hallway 117, next to room 142, right bubbler	<1.0		µg/L	
292-146-DF-16	Drinking fountain, room 146, next to restrooms	<1.0		µg/L	
292-131-DF-17	Drinking fountain, hallway 131, next to room 137	<1.0		µg/L	
292-131-DF-18	Drinking fountain, hallway 131, next to room 132	<1.0		µg/L	
292-117-DF-19	Drinking fountain, hallway 117, next to room 121, left bubbler	1.5		µg/L	
292-117-DF-20	Drinking fountain, hallway 117, next to room 121, right bubbler	1.4		µg/L	
292-110-DF-21	Drinking fountain, hallway 110, next to room 114, left bubbler	<1.0		µg/L	
292-110-DF-22	Drinking fountain, hallway 110, next to room 114, right bubbler	<1.0		µg/L	
Phase II Sampled on 4/5/2017					
292-146-SK-23	Classroom sink, room 146	<1.0		µg/L	
292-145-SK-24	Classroom sink, room 145	<1.0		µg/L	
292-143-SK-25	Classroom sink, room 143	4.0		µg/L	

292-141-SK-26	Classroom sink, room 141, west wall	1.0		µg/L	
292-141-SK-27	Classroom sink, room 141, southwest corner	7.0		µg/L	
292-139-SK-28	Classroom sink, room 139	5.0		µg/L	
292-137-SK-29	Classroom sink, room 137	10.0		µg/L	
292-135-SK-30	Classroom sink, room 135	17.0	2.0	µg/L	Faucet replaced 7/2017
292-134-SK-31	Classroom sink, room 134	3.0		µg/L	
292-132-SK-32	Classroom sink, room 132	13.0		µg/L	
292-130-SK-33	Classroom sink, room 130, west wall	5.0		µg/L	
292-130-SK-34	Classroom sink, room 130, southeast corner	<1.0		µg/L	
292-129-SK-35	Classroom sink, room 129, southeast corner	2.0		µg/L	
292-129-SK-36	Classroom sink, room 129, north wall	3.0		µg/L	
292-127-SK-37	Classroom sink, room 127	3.0		µg/L	
292-125-SK-38	Classroom sink, room 125, sink on left	4.0		µg/L	
292-125-SK-39	Classroom sink, room 125, center sink	1.0		µg/L	
292-125-SK-40	Classroom sink, room 125, right sink	15.0	2.0	µg/L	Faucet replaced 11/2018
292-123-SK-41	Classroom sink, room 123	2.0		µg/L	
292-124-SK-42	Classroom sink, room 124	5.0		µg/L	
292-126-SK-43	Classroom sink, room 126	9.0		µg/L	
292-133-SK-44	Classroom sink, room 133, sink on left	8.0		µg/L	
292-133-SK-45	Classroom sink, room 133, sink on right	3.0		µg/L	
292-136-SK-46	Classroom sink, room 136	11.0		µg/L	
292-140-SK-47	Classroom sink, room 140	8.0		µg/L	
292-142-SK-48	Classroom sink, room 142	4.0		µg/L	
292-118-SK-49	Classroom sink, room 118	3.0		µg/L	
292-120-SK-50	Classroom sink, room 120	2.0		µg/L	
292-121-SK-51	Classroom sink, room 121	4.0		µg/L	
292-115-SK-52	Classroom sink, room 115, west wall	5.0		µg/L	
292-115-SK-53	Classroom sink, room 115, northeast corner	4.0		µg/L	
292-113-SK-54	Classroom sink, room 113, west wall	5.0		µg/L	
292-113-SK-55	Classroom sink, room 113, southwest corner	2.0		µg/L	
292-111-SK-56	Classroom sink, room 111	2.0		µg/L	
292-112-SK-57	Classroom sink, room 112	2.0		µg/L	
292-114-SK-58	Classroom sink, room 114, west wall	6.0		µg/L	
292-114-SK-59	Classroom sink, room 114, east wall	2.0		µg/L	
292-116-SK-60	Classroom sink, room 116, west wall	18.0	3.0	µg/L	Faucet replaced 7/2017
292-116-SK-61	Classroom sink, room 116, north wall left sink	3.0		µg/L	
292-116-SK-62	Classroom sink, room 116, north wall center sink	1.0		µg/L	
292-116-SK-63	Classroom sink, room 116, north wall right sink	2.0		µg/L	
292-101C-SK-64	Faculty workroom sink, room 101C	<1.0		µg/L	
292-109A-SK-65	Gymnasium office sink, room 109A	12.0		µg/L	
292-119C-SK-66	LMC/IMC office sink, room 119C	8.0		µg/L	
292-119B-SK-67	LMC/IMC office sink, room 119B	>50.0	8.0	µg/L	Faucet replaced 7/2017

\*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.