

## Archuleta Elementary (199)

**Sample ID Key:**

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 10/7/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
199-151-DF-01	Drinking fountain, all purpose room 151, left bubbler	1.5		µg/L	
199-151-DF-02	Drinking fountain, all purpose room 151, right bubbler	0.2		µg/L	
199-190-SK-03	Kitchen sink, north wall	1.2		µg/L	
199-190-SK-04	Kitchen kettle fill	2.4		µg/L	
199-165-SK-05	Nurse office sink, room 165	0.4		µg/L	
199-H160-DF-06	Drinking fountain, hallway H160, across from main office, left bubbler	0.1		µg/L	
199-H160-DF-07	Drinking fountain, hallway H160, across from main office, right bubbler	<0.1*1		µg/L	
199-150-DF-08	Drinking fountain, gymnasium, south east corner	0.2		µg/L	
199-H100M-SK-09	Staff lounge sink, room H100M	0.4		µg/L	
199-H125-DF-10	Drinking fountain, hallway H125, across from room 119, left bubbler	<0.1		µg/L	
199-H125-DF-11	Drinking fountain, hallway H125, across from room 119, right bubbler	<0.1		µg/L	
199-H145-DF-12	Drinking fountain, hallway H145, across from room 113, right bubbler (left side INOP)	<0.1		µg/L	
199-107-DF-13	Drinking fountain, room 107	0.2		µg/L	
199-106-DF-14	Drinking fountain, room 106	0.1		µg/L	
199-H155-DF-15	Drinking fountain, hallway H155, across from room 105, left bubbler	0.2		µg/L	
199-H155-DF-16	Drinking fountain, hallway H155, across from room 105, right bubbler	0.1		µg/L	
199-105-DF-17	Drinking fountain, room 105	0.1		µg/L	
199-104B-DF-18	Drinking fountain, hallway 104B, between rooms 104 and 105	0.3		µg/L	
199-104-DF-19	Drinking fountain, room 104	0.1		µg/L	
199-101-DF-20	Drinking fountain, room 101	<0.1		µg/L	
199-102-DF-21	Drinking fountain, room 102	0.1		µg/L	
199-103-DF-22	Drinking fountain, room 103	0.1		µg/L	
199-110-DF-23	Drinking fountain, room 110	0.2		µg/L	
199-111-DF-24	Drinking fountain, room 111	0.3		µg/L	
199-112-DF-25	Drinking fountain, room 112	0.1		µg/L	
Phase II Sampled on 4/28/2017					
199-125-SK-26	Classroom sink, room 125	<1.0		µg/L	

199-124-SK-27	Classroom sink, room 124	<1.0		µg/L	
199-123-SK-28	Classroom sink, room 123	<1.0		µg/L	
199-122-SK-29	Classroom sink, room 122	<1.0		µg/L	
199-121-SK-30	Classroom sink, room 121	<1.0		µg/L	
199-120-SK-31	Classroom sink, room 120	<1.0		µg/L	
199-119-SK-32	Classroom sink, room 119	1.0		µg/L	
199-118-SK-33	Classroom sink, room 118	<1.0		µg/L	
199-117-SK-34	Classroom sink, room 117	2.0		µg/L	
199-116-SK-35	Classroom sink, room 116	<1.0		µg/L	
199-115-SK-36	Classroom sink, room 115	<1.0		µg/L	
199-114-SK-37	Classroom sink, room 114	2.0		µg/L	
199-113-SK-38	Classroom sink, room 113	<1.0		µg/L	
199-112-SK-39	Classroom sink, room 112, sink on left	<1.0		µg/L	
199-111-SK-40	Classroom sink, room 111, sink on right	<1.0		µg/L	
199-112-SK-41	Classroom sink, room 112, sink on right	<1.0		µg/L	
199-111-SK-42	Classroom sink, room 111, sink on left	2.0		µg/L	
199-110-SK-43	Classroom sink, room 110, sink on left	<1.0		µg/L	
199-110-SK-44	Classroom sink, room 110, sink on right	<1.0		µg/L	
199-109-SK-45	Classroom sink, room 109	<1.0		µg/L	
199-108-SK-46	Classroom sink, room 108, sink on left	<1.0		µg/L	
199-108-SK-47	Classroom sink, room 108, sink on right	<1.0		µg/L	
199-107-SK-48	Classroom sink, room 107, sink on left	1.0		µg/L	
199-107-SK-49	Classroom sink, room 107, sink on right	<1.0		µg/L	
199-106-SK-50	Classroom sink, room 106, sink on right	10.0		µg/L	
199-106-SK-51	Classroom sink, room 106, sink on left	2.0		µg/L	
199-106B-DF-52	Drinking fountain, hallway 106B, between rooms 106 and 107	<1.0		µg/L	
199-105-SK-53	Classroom sink, room 105, sink on left	<1.0		µg/L	
199-105-SK-54	Classroom sink, room 105, sink on right	1.0		µg/L	
199-104-SK-55	Classroom sink, room 104, sink on right	<1.0		µg/L	
199-104-SK-56	Classroom sink, room 104, sink on left	<1.0		µg/L	
199-103-SK-57	Classroom sink, room 103, sink on left	<1.0		µg/L	
199-103-SK-58	Classroom sink, room 103, sink on right	1.0		µg/L	
199-102-SK-59	Classroom sink, room 102, sink on right	<1.0		µg/L	
199-102-SK-60	Classroom sink, room 102, sink on left	15.0	<1.0	µg/L	Faucet Replaced 10/29/2018
199-101-SK-61	Classroom sink, room 101, sink on left	<1.0		µg/L	
199-101-SK-62	Classroom sink, room 101, sink on right	3.0		µg/L	
199-141-SK-63	Faculty workroom sink, room 141	<1.0		µg/L	

\*Result less than 0.1 ppb which is the lowest level that can be reported by the lab.