

## Bryant Webster Elementary (216)

All results at 15 ppb or below – No further action at this time.

**Sample ID Key:**

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/2/2016			
Sample ID	Sample Description	Lead Result	Units
216-005-sk-01	Lounge sink, room 005	<1.0* <sup>1</sup>	µg/L
216-009-df-02	Drinking fountain, cafeteria	1.5	µg/L
216-009a-sk-03	Kitchen, kettle faucet	11.7	µg/L
216-009s-sk-04	Kitchen sink, south wall	<1.0	µg/L
216-100-df-05	Drinking fountain, hallway 100, next to auditorium	<1.0	µg/L
216-101-sk-06	Sink, office room 101	1.1	µg/L
216-100-df-07	Drinking fountain, hallway 100, next to room 103	<1.0	µg/L
216-100-df-08	Bottle fill, hallway 100, across from room 117	<1.0	µg/L
216-100-df-09	Drinking fountain, hallway 100, across from room 117	<1.0	µg/L
216-100-df-10	Drinking fountain, hallway 100, across from room 106	<1.0	µg/L
216-109-df-11	Drinking fountain, hallway 109, next to room 109A	<1.0	µg/L
216-200-df-12	Bottle filler, hallway 200, near room 206	<1.0	µg/L
216-200-df-13	Drinking fountain, hallway 200, near room 206	<1.0	µg/L
216-200-df-14	Drinking fountain, hallway 200, near room 202	<1.0	µg/L
216-200-df-15	Drinking fountain, hallway 200, near room 212	<1.0	µg/L
Phase II Sampled on 2/10/2017			
216-121-SK-16	Admin office sink, room 121	0.6	µg/L
216-115-SK-17	Classroom sink, room 115	<0.5* <sup>2</sup>	µg/L
216-114-SK-18	Classroom sink, room 114	0.5	µg/L
216-113-SK-19	Classroom sink, room 113	0.9	µg/L
216-108-SK-20	Classroom sink, room 108	6.1	µg/L
216-107-SK-21	Classroom sink, room 107	3.8	µg/L
216-106-SK-22	Classroom sink, room 106	2.9	µg/L
216-105-SK-23	Classroom sink, room 105	1.3	µg/L
216-101-SK-24	Admin office sink, room 101	0.7	µg/L
216-208-SK-25	Faculty lounge sink, room 208	<0.5	µg/L

\*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.

\*2 Result less than 0.50 ppb which is the lowest level that can be reported by the external lab.