

Contemporary Learning Academy @ 200 East 9th Ave. (1003)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 10/27/2016

Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
1003-009-SK-01	Kitchen sink, room 009, west wall, by double doors	<1.0		µg/L	
1003-009-SK-02	Kitchen island sink, room 009, center of room	1.7		µg/L	
1003-009-SK-03	Kitchen kettle fill, room 009, south wall	0.8		µg/L	
1003-009-SK-04	Kitchen sink, room 009, southeast corner	1.1		µg/L	
1003-009-SK-05	Kitchen sink, room 009, west wall, next to cooler 009F	1.1		µg/L	
1003-008-DF-06	Drinking fountain, hallway 008, next to cafeteria, left bubbler	0.4		µg/L	
1003-008-DF-07	Drinking fountain, hallway 008, next to cafeteria, right bubbler	0.5		µg/L	
1003-008-DF-08	Bottle filler, hallway 008, next to cafeteria	0.4		µg/L	
1003-105-DF-09	Drinking fountain, hallway 105, across from room 109, left bubbler	0.2		µg/L	
1003-105-DF-10	Drinking fountain, hallway 105, across from room 109, right bubbler	0.2		µg/L	
1003-105-DF-11	Bottle filler, hallway 105, across from room 109	0.2		µg/L	
1003-115-DF-12	Drinking fountain, hallway 115, next to room 116, left bubbler	0.3		µg/L	
1003-115-DF-13	Drinking fountain, hallway 115, next to room 116, right bubbler	0.3		µg/L	
1003-115-DF-14	Bottle filler, hallway 115, next to room 116	0.3		µg/L	
1003-119-SK-15	Faculty lounge sink, room 119	0.7		µg/L	
1003-145-SK-16	Faculty work room sink, room 145	0.3		µg/L	
1003-220-DF-17	Drinking fountain, hallway 220, across from room 219, left bubbler	0.3		µg/L	
1003-220-DF-18	Drinking fountain, hallway 220, across from room 219, right bubbler	0.3		µg/L	
1003-220-DF-19	Bottle filler, hallway 220, across from room 219	0.4		µg/L	
1003-214-SK-20	Reading room sink, room 214, next to room 227	0.3		µg/L	
1003-205-DF-21	Drinking fountain, hallway 205, across from room 208, left bubbler	0.2		µg/L	
1003-205-DF-22	Drinking fountain, hallway 205, across from room 208, right bubbler	0.3		µg/L	
1003-205-DF-23	Bottle filler, hallway 205, across from room 208	0.2		µg/L	
Phase II Sampled on 9/27/2017					
1003-216-SK-24	Science lab sink, room 216, left faucet	1.1		µg/L	

1003-216-SK-25	Science lab sink, room 216, right faucet	0.5		µg/L	
1003-226-SK-26	Science lab sink, room 226, west wall, right sink	0.7		µg/L	
1003-226-SK-27	Science lab sink, room 226, west wall, center sink	2.2		µg/L	
1003-226-SK-28	Science lab sink, room 226, west wall, left sink	0.5		µg/L	
1003-226-SK-29	Science lab sink, room 226, east wall, right sink	1.1		µg/L	
1003-226-SK-30	Science lab sink, room 226, east wall, left sink	1.5		µg/L	
1003-226A-SK-31	Science lab sink, prep room 226A	0.6		µg/L	
1003-204-SK-32	Art room sink, room 204, left sink	0.9		µg/L	
1003-204-SK-33	Art room sink, room 204, right sink	0.8		µg/L	
1003-206-SK-34	Science lab sink, room 206, left sink	1.0		µg/L	
1003-206-SK-35	Science lab sink, room 206, center sink	0.9		µg/L	
1003-206-SK-36	Science lab sink, room 206, right sink	0.9		µg/L	
1003-140A-SK-37	Storage room utility sink, room 140A	>50.0	2.0	µg/L	Faucet replaced 4/2018
1003-146-SK-38	Nurse sink, room 146	0.5		µg/L	