

Centennial Elementary (297)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/27/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
297-KIT-SK-01	Kitchen sink, east wall, left faucet, hot water line for sanitation compartment	>50.0 (5.0 flush ^{*1})	<1.0	µg/L	Flush notice, Faucet replaced 12/2018
297-KIT-SK-02	Kitchen sink, east wall, middle faucet	21.2 (<2.0 flush ^{*1})	6.0	µg/L	Flush notice, Faucet replaced 12/2018
297-KIT-SK-03	Kitchen sink, east wall, right faucet	3.6		µg/L	
297-KITC-SK-04	Kitchen sink, room KITC	1.7		µg/L	
297-H150-DF-05	Drinking fountain, hallway H150, across from cafeteria	6.1		µg/L	
297-GYM-DF-06	Drinking fountain, gymnasium, north wall	5.4		µg/L	
297-H190-DF-07	Drinking fountain, hallway H190, next to room 130	<1.0 ^{*2}		µg/L	
297-H140-DF-08	Drinking fountain, hallway H140, next to room 122, left bubbler	<1.0		µg/L	
297-H140-DF-09	Drinking fountain, hallway H140, next to room 122, right bubbler	<1.0		µg/L	
297-WR-SK-10	Workroom sink, room WR	3.7		µg/L	
297-H140-DF-11	Drinking fountain, hallway H140, next to room 118, left bubbler	1.3		µg/L	
297-H140-DF-12	Drinking fountain, hallway H140, next to room 118, right bubbler	<1.0		µg/L	
297-H160-DF-13	Drinking fountain, hallway H160, next to room 113, left bubbler	<1.0		µg/L	
297-H160-DF-14	Drinking fountain, hallway H160, next to room 113, right bubbler	<1.0		µg/L	
297-H100-DF-15	Drinking fountain, hallway H100, next to room 108, left bubbler	<1.0		µg/L	
297-H100-DF-16	Drinking fountain, hallway H100, next to room 108, right bubbler	<1.0		µg/L	
297-128-SK-17	Classroom sink, room 128	<1.0		µg/L	
297-H100-DF-18	Drinking fountain, hallway H100, next to room 104, left bubbler	<1.0		µg/L	
297-H100-DF-19	Drinking fountain, hallway H100, next to room 104, right bubbler	<1.0		µg/L	
297-127-SK-20	Classroom sink, room 127	1.8		µg/L	
297-H170-DF-21	Drinking fountain, hallway H170, in main office	3.7		µg/L	
297-H170E-SK-22	Main office sink, room H170E	<1.0		µg/L	
297-OFFB-SK-23	Main office sink, room OFFB	2.0		µg/L	

297-102-DF-24	Drinking fountain, room 102	5.5	µg/L
297-101-DF-25	Drinking fountain, room 101	2.3	µg/L
Phase II Sampled on 4/12/2017			
297-169-SK-26	Classroom sink, room 169	3.0	µg/L
297-168-SK-27	Classroom sink, room 168	4.0	µg/L
297-105-SK-28	Classroom sink, room 105	<1.0	µg/L
297-107-SK-29	Classroom sink, room 107	<1.0	µg/L
297-112-SK-30	Classroom sink, room 112	<1.0	µg/L
297-114-SK-31	Classroom sink, room 114	<1.0	µg/L
297-118-SK-32	Classroom sink, room 118	<1.0	µg/L
297-121-SK-33	Classroom sink, room 121	<1.0	µg/L
297-124-SK-34	Classroom sink, room 124	4.0	µg/L
297-125-SK-35	Classroom sink, room 125	2.0	µg/L
297-127-SK-36	Classroom sink, room 127	2.0	µg/L
297-128-SK-37	Classroom sink, room 128	5.0	µg/L
297-129-SK-38	Classroom sink, room 129	4.0	µg/L
297-133-SK-39	Classroom sink, room 133	1.0	µg/L
297-136-SK-40	Classroom sink, room 136	1.0	µg/L
297-131-SK-41	Classroom sink, room 131, south sink	3.0	µg/L
297-131-SK-42	Classroom sink, room 131, north sink	4.0	µg/L
297-117-SK-43	Classroom sink, room 117	4.0	µg/L
297-138-SK-44	Classroom sink, room 138	<1.0	µg/L
297-140-SK-45	Classroom sink, room 140	<1.0	µg/L
297-144-SK-46	Classroom sink, room 144	<1.0	µg/L
297-148-SK-47	Classroom sink, room 148	<1.0	µg/L
297-151-SK-48	Classroom sink, room 151	1.0	µg/L
297-152-SK-49	Classroom sink, room 152	1.0	µg/L
297-153-SK-50	Classroom sink, room 153, south sink	2.0	µg/L
297-154-SK-51	Classroom sink, room 154	2.0	µg/L
297-153-SK-52	Classroom sink, room 153, west sink	2.0	µg/L
297-153-SK-53	Classroom sink, room 153, north sink	<1.0	µg/L
297-110B-SK-54	LMC/IMC office sink, room 110B	12.0	µg/L
297-146-SK-55	Classroom sink, room 146	6.0	µg/L

*1. Flush samples are field tested with a Palintest SA1100 scanning analyzer.

*2. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.