

Cowell Elementary School (224)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/14/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
224-130A-SK-01	Kitchen prep sink, west wall	1.3		µg/L	
224-130A-SK-02	Kitchen, kettle filler	5.8		µg/L	
224-100-DF-03	Drinking fountain, hallway 100, next to room 130, left bubbler	2.3		µg/L	
224-100-DF-04	Drinking fountain, hallway 100, next to room 130, right bubbler	1.7		µg/L	
224-100-DF-05	Drinking fountain, hallway 100, next to gym, left bubbler	1.5		µg/L	
224-100-DF-06	Drinking fountain, hallway 100, next to gym, right bubbler	1.2		µg/L	
224-100-DF-07	Drinking fountain, hallway 100, next to room 110, left bubbler	<1.0*1		µg/L	
224-100-DF-08	Drinking fountain, hallway 100, next to room 110, right bubbler	<1.0		µg/L	
224-132-SK-09	Lounge sink, room 132	<1.0		µg/L	
224-105-DF-10	Drinking fountain, hallway 105, across from room 138	<1.0		µg/L	
224-105-DF-11	Drinking fountain, hallway 105, across from room 109, left bubbler	4.0		µg/L	
224-105-DF-12	Drinking fountain, hallway 105, across from room 109, right bubbler	2.1		µg/L	
224-101A-SK-13	Sink, school office 101A	26.9	8.0*2	µg/L	Faucet replaced 12/3/2016
224-105-DF-14	Drinking fountain, hallway 105, across from room 103	2.2		µg/L	
224-175-DF-15	Drinking fountain, hallway 125, next to room 126, left bubbler	9.3		µg/L	
224-125-DF-16	Drinking fountain, hallway 125, next to room 126, right bubbler	4.8		µg/L	
224-127-SK-17	Classroom sink, room 127	5.9		µg/L	
224-128-SK-18	Classroom sink, room 128	14.5		µg/L	
224-126-DF-19	Drinking fountain, room 126	16.4; 20.0	2.0*2	µg/L	Filter installed 2/2018
224-113-DF-20	Drinking fountain, hallway 113, across from room 116	7.9		µg/L	
224-124-SK-21	Classroom sink, room 124	1.6		µg/L	
224-151-DF-22	Drinking fountain, modular #1, room 151	<1.0		µg/L	
224-150-DF-23	Drinking fountain, modular #1, room 150	<1.0		µg/L	
224-152-DF-24	Drinking fountain, modular #2, room 152	<1.0		µg/L	
Phase II Sampled on 2/23/2017					
224-001C-SK-27	Custodial office sink, room 001C	12.0		µg/L	
224-104-SK-28	Classroom sink, room 104	5.0		µg/L	
224-106-SK-29	Classroom sink, room 106	12.0		µg/L	
224-103-SK-30	Classroom sink, room 103	5.0		µg/L	
224-107-SK-31	Classroom sink, room 107	9.0		µg/L	
224-102-SK-32	Classroom sink, room 102	7.0		µg/L	
224-108-SK-33	Classroom sink, room 108	10.0		µg/L	

224-109-SK-34	Classroom sink, room 109	21.0	8.0	µg/L	Faucet replaced 7/2017
224-137-SK-35	Classroom sink, room 137	<1.0		µg/L	
224-136-SK-36	Classroom sink, room 136	1.0		µg/L	
224-138-SK-37	Classroom sink, room 138	<1.0		µg/L	
224-110-SK-38	Classroom sink, room 110	1.0		µg/L	
224-112-SK-39	Classroom sink, room 112	2.0		µg/L	
224-129-SK-40	Classroom sink, room 129	16.0	6.0	µg/L	Faucet replaced 7/2017
224-114-SK-41	Classroom sink, room 114	10.0		µg/L	
224-115B-SK-42	LMC/IMC office sink, room 115B	14.0		µg/L	
224-126-SK-43	Classroom sink, room 126	4.0		µg/L	
224-116-SK-44	Classroom sink, room 116	5.0		µg/L	
224-117-SK-45	Classroom sink, room 117	1.0		µg/L	
224-119-SK-46	Classroom sink, room 119	1.0		µg/L	
224-120-SK-47	Classroom sink, room 120	<1.0		µg/L	
224-121-SK-48	Classroom sink, room 121	<1.0		µg/L	
224-122-SK-49	Classroom sink, room 122	<1.0		µg/L	
224-123-SK-50	Classroom sink, room 123	2.0		µg/L	
224B-151-SK-51	Classroom sink, room 151	<1.0		µg/L	
224B-150-SK-52	Classroom sink, room 150	<1.0		µg/L	
224C-153-SK-53	Classroom sink, room 153	<1.0		µg/L	
224C-152-SK-54	Classroom sink, room 152	<1.0		µg/L	

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.

*2. Follow up sample tested with a Palintest SA1100 scanning analyzer.