

DCIS @ Ford Elementary (293)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/27/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
293-105-sk-01	Kitchen sink, west wall, left faucet	2.6		µg/L	
293-105-SK-02	Kitchen sink, west wall, right faucet	<1.0* ¹		µg/L	
293-106-DF-03	Drinking fountain, cafeteria, west wall, left bubbler	<1.0		µg/L	
293-106-DF-04	Drinking fountain, cafeteria, west wall, right bubbler	<1.0		µg/L	
293-109-DF-05	Drinking fountain, gymnasium, east wall, left fixture	1.1		µg/L	
293-109-DF-06	Drinking fountain, gymnasium, east wall, right fixture	<1.0		µg/L	
293-107-sk-07	Staff lounge sink, room 107	<1.0		µg/L	
293-101B-SK-08	Nurse sink, room, 101B	1.7		µg/L	
293-100-DF-09	Drinking fountain, hallway 100, next to 101B, left bubbler	<1.0		µg/L	
293-100-DF-10	Drinking fountain, hallway 100, next to 101B, right bubbler	<1.0		µg/L	
293-144-DF-11	Drinking fountain, hallway 144, next to auditorium, left bubbler	2.4		µg/L	
293-144-DF-12	Drinking fountain, hallway 144, next to auditorium, right bubbler	1.1		µg/L	
293-144-DF-13	Drinking fountain, hallway 144, between faculty restrooms, left bubbler	<1.0		µg/L	
293-144-DF-14	Drinking fountain, hallway 144, between faculty restrooms, right bubbler	<1.0		µg/L	
293-144-DF-15	Drinking fountain, hallway 144, next to room 142, left bubbler	1.5		µg/L	
293-144-DF-16	Drinking fountain, hallway 144, next to room 142, right bubbler	1.4		µg/L	
293-146-DF-17	Drinking fountain, room 146, between restrooms	1.1		µg/L	
293-128-DF-18	Drinking fountain, hallway 128, next to room 134, left bubbler	<1.0		µg/L	
293-128-DF-19	Drinking fountain, hallway 128, next to room 134, right bubbler	<1.0		µg/L	
293-128-DF-20	Drinking fountain, hallway 128, next to room 129	<1.0		µg/L	
293-110-DF-21	Drinking fountain, hallway 110, next to room 121, left bubbler	2.7		µg/L	
293-110-DF-22	Drinking fountain, hallway 110, next to room 121, right bubbler	1.9		µg/L	
293-110-DF-23	Drinking fountain, hallway 110, next to room 114, left bubbler	<1.0		µg/L	
293-110-DF-24	Drinking fountain, hallway 110, next to room 114, right bubbler	14.3		µg/L	
Phase II Sampled on 4/6/2017					
293-101C-SK-25	Admin office sink, room 101C	<1.0		µg/L	
293-146-SK-26	Classroom sink, room 146	<1.0		µg/L	
293-145-SK-27	Classroom sink, room 145	3.0		µg/L	
293-143-SK-28	Classroom sink, room 143	6.0		µg/L	
293-141-SK-29	Classroom sink, room 141, west wall	8.0		µg/L	

293-141-SK-30	Classroom sink, room 141, southwest corner	>50.0	2.0	µg/L	Replaced fall 2017
293-139-SK-31	Classroom sink, room 139	9.0		µg/L	
293-137-SK-32	Classroom sink, room 137, north wall	5.0		µg/L	
293-137-SK-33	Classroom sink, room 137, southwest corner	<1.0		µg/L	
293-136-SK-34	Classroom sink, room 136, southwest corner	<1.0		µg/L	
293-136-SK-35	Classroom sink, room 136, east wall	1.0		µg/L	
293-134-SK-36	Classroom sink, room 134, left sink	8.0		µg/L	
293-134-SK-37	Classroom sink, room 134, right sink	2.0		µg/L	
293-132-SK-38	Classroom sink, room 132	3.0		µg/L	
293-130-SK-39	Classroom sink, room 130	2.0		µg/L	
293-129-SK-40	Classroom sink, room 129	35.0	12.0	µg/L	Replaced fall 2017
293-127-SK-41	Classroom sink, room 127	6.0		µg/L	
293-125-SK-42	Classroom sink, room 125, left sink	4.0		µg/L	
293-125-SK-43	Classroom sink, room 125, center sink	3.0		µg/L	
293-125-SK-44	Classroom sink, room 125, right sink	5.0		µg/L	
293-123-SK-45	Classroom sink, room 123	4.0		µg/L	
293-121-SK-46	Classroom sink, room 121	4.0		µg/L	
293-124-SK-47	Classroom sink, room 124	13.0		µg/L	
293-126-SK-48	Classroom sink, room 126	9.0		µg/L	
293-133-SK-49	Classroom sink, room 133	6.0		µg/L	
293-140-SK-50	Classroom sink, room 140	>50.0	12.0	µg/L	Replaced fall 2017
293-142-SK-51	Classroom sink, room 142	6.0		µg/L	
293-118-SK-52	Classroom sink, room 118	3.0		µg/L	
293-119B-SK-53	LMC/IMC office sink, room 119B	9.0		µg/L	
293-119C-SK-54	LMC/IMC office sink, room 119C	10.0		µg/L	
293-120-SK-55	Classroom sink, room 120	5.0		µg/L	
293-116-SK-56	Classroom sink, room 116, northwest corner	2.0		µg/L	
293-115-SK-57	Classroom sink, room 115, west wall	2.0		µg/L	
293-115-SK-58	Classroom sink, room 115, northeast corner	6.0		µg/L	
293-113-SK-59	Classroom sink, room 133, west wall, north of door	3.0		µg/L	
293-111-SK-60	Classroom sink, room 111	2.0		µg/L	
293-112-SK-61	Classroom sink, room 112	2.0		µg/L	
293-112-DF-62	Drinking fountain, room 112	1.0		µg/L	
293-114-SK-63	Classroom sink, room 114, east wall	11.0		µg/L	
293-114-SK-64	Classroom sink, room 114, west wall	3.0		µg/L	
293-109A-SK-65	Gymnasium office sink, room 109A	3.0		µg/L	
293-103-SK-66	Classroom sink, room 103	<1.0		µg/L	

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.