

Fairview Elementary (238)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 8/26/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
238-000-DF-01	Drinking fountain, hallway 000, left bubbler	1.5		µg/L	
238-000-DF-02	Drinking fountain, hallway 000, right bubbler	1.5		µg/L	
238-005-SK-03	Lounge sink, room 005, left	<1.0* ¹		µg/L	
238-005-SK-04	Lounge sink, room 005, right	1.5		µg/L	
238-104A-DF-05	Drinking fountain, between rooms 103 and 104, left bubbler	4.8		µg/L	
238-H100-DF-06	Drinking fountain, hallway H100, next to room 105	2.7		µg/L	
238-H140-DF-07	Plumbed water cooler, room H140	<1.0		µg/L	
238-OFFC-SK-08	Nurse sink	1.8		µg/L	
238-H100-DF-09	Drinking fountain, hallway H100, left bubbler, near admin office	<1.0		µg/L	
238-H100-DF-10	Drinking fountain, hallway H100, right bubbler, near admin office	<1.0		µg/L	
238-KITD-SK-11	Kitchen sink, room KITD south wall	<1.0		µg/L	
238-KITD-SK-12	Kitchen sink, room KITD west wall	<1.0		µg/L	
238-LR-DF-13	Drinking fountain, cafeteria	14.6		µg/L	
238-GYM-DF-14	Drinking fountain, gym, left	<1.0		µg/L	
238-GYM-DF-15	Drinking fountain, gym, right	<1.0		µg/L	
238-H100-DF-16	Drinking fountain, hallway H100, next to room 111, left bubbler	<1.0		µg/L	
238-H200-DF-17	Drinking fountain, hallway H200, next to room 211, left bubbler	1.0		µg/L	
238-H200-DF-18	Drinking fountain, hallway H200, next to room 211, right bubbler	2.4		µg/L	
238-H200-DF-19	Drinking fountain, hallway H200, next to room 214, left bubbler	6.3		µg/L	
238-H200-DF-20	Drinking fountain, hallway H200, next to room 214, right bubbler	<1.0		µg/L	
238-H200-DF-21	Drinking fountain, hallway H200, next to room 205, left bubbler	12.0		µg/L	
238-H200-DF-22	Drinking fountain, hallway H200, next to room 205, right bubbler	3.1		µg/L	
Phase II Sampled on 1/31/2017					
238-003-SK-23	Classroom sink, room 003	<0.5* ²		µg/L	
238-004-SK-24	Classroom sink, room 004	<0.5		µg/L	
238-002-SK-25	Classroom sink, room 002	1.2		µg/L	
238-001-SK-26	Classroom sink, room 001	0.7		µg/L	

238-007-SK-27	Classroom sink, room 007	4.3		µg/L	
238-103-SK-28	Classroom sink, room 103	<0.5		µg/L	
238-104-SK-29	Classroom sink, room 104	<0.5		µg/L	
238-102-SK-30	Classroom sink, room 102	0.6		µg/L	
238-105-SK-31	Classroom sink, room 105	<0.5		µg/L	
238-101-SK-32	Classroom sink, room 101	<0.5		µg/L	
238-106-SK-33	Classroom sink, room 106	<0.5		µg/L	
238-107-SK-34	Classroom sink, room 107	4.5		µg/L	
238-111-SK-35	Classroom sink, room 111	0.6		µg/L	
238-109-SK-36	Classroom sink, room 109	<0.5		µg/L	
238-111AD-DF-37	Drinking fountain, room 111AD	4.0		µg/L	
238-108-SK-38	Classroom sink, room 108, left sink	0.5		µg/L	
238-108-SK-39	Classroom sink, room 108, right sink	2.0		µg/L	
238-211-SK-40	Classroom sink, room 211	0.6		µg/L	
238-212-SK-41	Classroom sink, room 212	2.3		µg/L	
238-207-SK-42	Classroom sink, room 207	0.8		µg/L	
238-201-SK-43	Classroom sink, room 201	6.1		µg/L	
238-206-SK-44	Classroom sink, room 206	11.0		µg/L	
238-205-SK-45	Classroom sink, room 205	5.5		µg/L	
238-203A-SK-46	LMC/IMC office sink, room 203A	23.0	16.0	µg/L	Faucet replaced 10/2017 – No drinking notice
238-203B-SK-47	LMC/IMC office sink, room 203B	>50.0	4.0	µg/L	Faucet replaced 10/2017
238-204-SK-48	Classroom sink, room 204	<0.5		µg/L	

*1. Result less than 1.0 ppb which is the lowest reportable level by the lab.

*2. Result less than 0.5 ppb which is the lowest reportable level by the external lab.