

Florence Crittenton (684 & 1101)

All results below 15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 8/25/2016				
Sample ID	Sample Description	Lead Result	Units	Action
684-F117-SK-01	Sink in kitchenette between F117 and F118	<1.0* ¹	µg/L	
684-F120-SK-02	Sink in kitchenette in room F120	<1.0	µg/L	
684-F122-SK-03	Sink in kitchenette between F122 and F123	<1.0	µg/L	
684-F111-DF-04	Drinking fountain, between rooms 110 and 111	<1.0	µg/L	
684-F115-SK-05	Sink, break room	<1.0	µg/L	
684-F116-DF-06	Drinking fountain, office area, next to F116	<1.0	µg/L	
684-F300B-SK-07	Kitchen sink, room F300B	<1.0	µg/L	
1101-113-DF-01	Zuni - Drinking fountain, room 113, next to 113C storage	<1.0	µg/L	
1101-134-DF-02	Zuni - Drinking fountain, hallway 134, by women's RR 134A; left bubbler	<1.0	µg/L	
1101-134-DF-03	Zuni - Drinking fountain, hallway 134, by women's RR 134A; right bubbler	<1.0	µg/L	
1101-114-SK-04	Zuni - Food prep sink, kitchen, room 114	<1.0	µg/L	
1101-131-SK-05	Zuni - Classroom sink, room 131	<1.0	µg/L	
1101-129-SK-06	Zuni - Faculty lounge sink, room 129	<1.0	µg/L	
1101-124-DF-07	Zuni - Drinking fountain, hallway 124, by women's RR 123C; left fixture	<1.0	µg/L	
1101-124-DF-08	Zuni - Drinking fountain, hallway 124, by women's RR 123C; right fixture	<1.0	µg/L	
Phase II Sampled on 3/3/2017				
684-111-SK-08	Classroom sink, room 111, left sink	1.0	µg/L	
684-111-SK-09	Classroom sink, room 111, right sink	<1.0	µg/L	
684-112-SK-10	Classroom sink, room 112, left sink	<1.0	µg/L	
684-112-SK-11	Classroom sink, room 112, right sink	<1.0	µg/L	
684-113-SK-12	Classroom sink, room 113, left sink	<1.0	µg/L	
684-113-SK-13	Classroom sink, room 113, right sink	<1.0	µg/L	
684-202-SK-14	Classroom sink, room 202	<1.0	µg/L	
684-200-SK-15	Community room sink, room 200	<1.0	µg/L	
684-400-SK-16	Resource room sink, room 400	2.0	µg/L	
1101-114-SK-09	Zuni - Kitchen, food prep sprayer, room 114	<1.0	µg/L	
1101-117-SK-10	Zuni - Faculty work room sink, room 117	<1.0	µg/L	
1101-133-SK-11	Zuni - Resource room sink, room 133	<1.0	µg/L	
1101-102-SK-12	Zuni - Nurse sink, room 102	<1.0	µg/L	
1101-110-SK-13	Zuni - Nurse sink, room 110	<1.0	µg/L	
1101-109-SK-14	Zuni - Nurse sink, room 109	<1.0	µg/L	
1101-107-SK-15	Zuni - Nurse sink, room 107	<1.0	µg/L	

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.