

GALS @ Del Pueblo (233)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/23/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
233-151-DF-01	Drinking fountain, cafeteria, west wall, next to kitchen	22.5	Pending construction	µg/L	Shut down – Bubbler replaced 1/2018
233-148-DF-02	Bottle fill, hallway 148, across from room 149	<1.0* ¹		µg/L	
233-148-DF-03	Drinking fountain, hallway 148, left drinking fountain, across from room 149	<1.0		µg/L	
233-148-DF-04	Drinking fountain, hallway 148, right drinking fountain, across from room 149	<1.0		µg/L	
233-148-DF-05	Drinking fountain, hallway 148, across from room 148B, single fixture	2.7		µg/L	
233-148-DF-06	Bottle fill, hallway 148, outside of gym	<1.0		µg/L	
233-148-DF-07	Drinking fountain, hallway 148, left drinking fountain, outside of gym	<1.0		µg/L	
233-148-DF-08	Drinking fountain, hallway 148, right drinking fountain, outside of gym	<1.0		µg/L	
233-100-DF-09	Drinking fountain, hallway 100, between restrooms, left bubbler	1.3		µg/L	
233-100-DF-10	Drinking fountain, hallway 100, between restrooms, right bubbler	1.7		µg/L	
233-101B-SK-11	Admin office sink, room 101B	1.1		µg/L	
233-109-DF-12	Drinking fountain, room 109	3.3		µg/L	
233-11-DF-13	Drinking fountain, hallway 111, next to restrooms	13.7		µg/L	
233-1201-DF-14	Drinking fountain, hallway 120, next to 120B, left fixture	<1.0		µg/L	
233-120-DF-15	Drinking fountain, hallway 120, next to 120B, right fixture	<1.0		µg/L	
233-125-DF-16	Drinking fountain, room 125	13.1		µg/L	
233-132-DF-17	Drinking fountain, hallway 132, next to room 134	6		µg/L	
233-151A-SK-18	Sink, PTA kitchen, room 151A	4.2		µg/L	
233-152A-SK-19	Kitchen prep sink, by dish washer	1.8		µg/L	
Phase II Sampled on 4/7/2017					
233-133-SK-20	Classroom sink, room 133	13.0		µg/L	
233-129-SK-21	Classroom sink, room 129	4.0		µg/L	
233-131-SK-22	Classroom sink, room 131, west wall	8.0		µg/L	
233-128-SK-23	Classroom sink, room 128	6.0		µg/L	
233-126-SK-24	Classroom sink, room 126, southwest corner	13.0		µg/L	

233-126-SK-25	Classroom sink, room 126, southeast corner	3.0		µg/L	
233-125-SK-26	Classroom sink, room 125	5.0		µg/L	
233-121-SK-27	Classroom sink, room 121	11.0		µg/L	
233-123-SK-28	Classroom sink, room 123	7.0		µg/L	
233-124-SK-29	Classroom sink, room 124	7.0		µg/L	
233-119-SK-30	Classroom sink, room 119, sink on left	6.0		µg/L	
233-119-SK-31	Classroom sink, room 119, sink on right	16.0	9.0	µg/L	Faucet replaced 10/2018
233-117-SK-32	Classroom sink, room 117, sink on left	24.0	Pending	µg/L	Faucet replaced 10/2018
233-117-SK-33	Classroom sink, room 117, sink on right	8.0		µg/L	
233-118A-SK-34	LMC / IMC office sink, room 118A	2.0		µg/L	
233-116-SK-35	Classroom sink, room 116	19.0	10.0	µg/L	Faucet replaced 10/2018
233-113-SK-36	Classroom sink, room 113	9.0		µg/L	
233-114-SK-37	Classroom sink, room 114	12.0		µg/L	
233-109-SK-38	Classroom sink, room 109	4.0		µg/L	
233-101A-SK-39	Nurse sink, room 101A	9.0		µg/L	
233-151A-SK-41	PTA kitchen sink, room 151A	4.0		µg/L	

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.