

KIPP NE Denver MS (1109) – Sampled 10/17/2017

All results below 15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Sample ID	Sample Description	Lead Result	Units	Action
1109-151A-SK-01	Kitchen prep sink, room 151A, next to tray return	0.1	µg/L	
1109-151-SK-02	Kitchen prep sink, room 151, across from walk in 151F	0.1	µg/L	
1109-145-DF-03	Drinking fountain, cafeteria, next to hallway 150, left bubbler	<0.1* ¹	µg/L	
1109-145-DF-04	Drinking fountain, cafeteria, next to hallway 150, right bubbler	<0.1	µg/L	
1109-145-DF-05	Bottle filler, cafeteria, next to hallway 150	<1.0* ²	µg/L	
1109-143-DF-06	Bottle filler, hallway 143, next to restrooms	<1.0	µg/L	
1109-143-DF-07	Drinking fountain, hallway 143, next to restrooms, left bubbler	<1.0	µg/L	
1109-143-DF-08	Drinking fountain, hallway 143, next to restrooms, right bubbler	<1.0	µg/L	
1109-147-DF-09	Bottle filler, room 147	<1.0	µg/L	
1109-147-DF-10	Drinking fountain, room 147	<1.0	µg/L	
1109-147-SK-11	Classroom sink, room 147	<1.0	µg/L	
1109-139-DF-12	Bottle filler, gymnasium, southwest corner	<1.0	µg/L	
1109-139-DF-13	Drinking fountain, gymnasium, southwest corner	<1.0	µg/L	
1109-140-SK-14	Classroom sink, room 140	6.0	µg/L	
1109-138-DF-15	Drinking fountain, hallway 138, next to room 140, left bubbler	<0.1	µg/L	
1109-138-DF-16	Drinking fountain, hallway 138, next to room 140, right bubbler	<0.1	µg/L	
1109-138-DF-17	Bottle filler, hallway 138, next to room 140	<0.1	µg/L	
1109-100-DF-18	Drinking fountain, lobby 100, left bubbler	<0.1	µg/L	
1109-100-DF-19	Drinking fountain, lobby 100, right bubbler	<1.0	µg/L	
1109-100-DF-20	Bottle filler, lobby 100	<1.0	µg/L	
1109-102L-SK-21	Nurse sink, room 102L	<1.0	µg/L	
1109-103-SK-22	Faculty lounge sink, room 103	<1.0	µg/L	
1109-136-SK-23	Classroom sink, room 136	<1.0	µg/L	
1109-135-SK-24	Classroom sink, room 135	<1.0	µg/L	
1109-133-SK-25	Classroom sink, room 133	<1.0	µg/L	
1109-131-SK-26	Classroom sink, room 131	<1.0	µg/L	
1109-129-SK-27	Classroom sink, room 129	<1.0	µg/L	
1109-127-SK-28	Classroom sink, room 127	<1.0	µg/L	
1109-125-SK-29	Classroom sink, room 125	0.1	µg/L	
1109-123-SK-30	Classroom sink, room 123	0.1	µg/L	
1109-121-SK-31	Classroom sink, room 121	0.1	µg/L	
1109-120-SK-32	Classroom sink, room 120	0.2	µg/L	
1109-119-SK-33	Classroom sink, room 119	0.2	µg/L	

1109-118-SK-34	Classroom sink, room 118	<1.0	µg/L
1109-116-SK-35	Classroom sink, room 116, on left	<1.0	µg/L
1109-116-SK-36	Classroom sink, room 116, on right	<1.0	µg/L
1109-116-DF-37	Bottler filler, classroom 116	<1.0	µg/L
1109-116-DF-38	Drinking fountain, classroom 116	<1.0	µg/L
1109-114-SK-39	Classroom sink, room 114, on left	<1.0	µg/L
1109-114-SK-40	Classroom sink, room 114, on right	<1.0	µg/L
1109-113A-DF-41	Bottler filler, hallway 113A	<1.0	µg/L
1109-113A-DF-42	Drinking fountain, hallway 113A	<1.0	µg/L
1109-113-SK-43	Classroom sink, room 113, on left	0.2	µg/L
1109-113-SK-44	Classroom sink, room 113, on right	0.2	µg/L
1109-112-SK-45	Classroom sink, room 112, on left	0.1	µg/L
1109-112-SK-46	Classroom sink, room 112, on right	0.1	µg/L
1109-111-SK-47	Classroom sink, room 111, on left	0.3	µg/L
1109-111-SK-48	Classroom sink, room 111, on right	<1.0	µg/L
1109-101-DF-49	Bottle filler, hallway 101, next to room 111	<1.0	µg/L
1109-101-DF-50	Drinking fountain, hallway 101, next to room 111, left bubbler	<1.0	µg/L
1109-101-DF-51	Drinking fountain, hallway 101, next to room 111, right bubbler	<1.0	µg/L
1109-124-SK-52	Classroom sink, room 124	<1.0	µg/L
1109-110-SK-53	Faculty lounge sink, room 110, on left	<1.0	µg/L
1109-110-SK-54	Faculty lounge sink, room 110, on right	<1.0	µg/L
1109-130-SK-55	Classroom sink, room 130	<1.0	µg/L
1109-108-SK-56	Classroom sink, room 108	<1.0	µg/L
1109-107-SK-57	Classroom sink, room 107	0.2	µg/L
1109-106-SK-58	Classroom sink, room 106	0.1	µg/L
1109-200-DF-59	Bottle filler, hallway 200, across from room 200A	<0.1	µg/L
1109-200-DF-60	Drinking fountain, hallway 200, across from room 200A, left bubbler	<0.1	µg/L
1109-200-DF-61	Drinking fountain, hallway 200, across from room 200A, right bubbler	<0.1	µg/L
1109-202-DF-62	Bottle filler, hallway 202, next to restrooms	<1.0	µg/L
1109-202-DF-63	Drinking fountain, hallway 202, next to restrooms, left bubbler	<1.0	µg/L
1109-202-DF-64	Drinking fountain, hallway 202, next to restrooms, right bubbler	<1.0	µg/L
1109-206-SK-65	Science lab sink, room 206, west wall, on left	<1.0	µg/L
1109-206-SK-66	Science lab sink, room 206, west wall, on right	<1.0	µg/L
1109-206-SK-67	Science lab sink, room 206, east wall, on left	<1.0	µg/L
1109-206-SK-68	Science lab sink, room 206, east wall, on right	<1.0	µg/L
1109-205A-SK-69	Science prep room sink, room 205A, south wall	<1.0	µg/L
1109-205A-SK-70	Science prep room sink, room 205A, north wall	<1.0	µg/L
1109-205-SK-71	Science lab sink, room 205, west wall, on left	<0.1	µg/L
1109-205-SK-72	Science lab sink, room 205, west wall, on right	0.1	µg/L
1109-205-SK-73	Science lab sink, room 205, east wall, on left	0.2	µg/L
1109-205-SK-74	Science lab sink, room 205, east wall, on right	<0.1	µg/L
1109-208-SK-75	Art room sink, room 208, north wall, on left	0.3	µg/L
1109-208-SK-76	Art room sink, room 208, north wall, on right	<1.0	µg/L

1109-212-DF-77	Bottle filler, hallway 212, next to restrooms	<1.0	µg/L
1109-212-DF-78	Drinking fountain, hallway 212, next to restrooms, left bubbler	<1.0	µg/L
1109-212-DF-79	Drinking fountain, hallway 212, next to restrooms, right bubbler	<1.0	µg/L
1109-142-SK-80	Classroom sink, room 142	<1.0	µg/L

*1. Result less than 0.1 ppb (µg/L) which is the lowest level that can be reported by the external lab.

*2. Result less than 1.0 ppb (µg/L) which is the lowest level that can be reported by the lab.