

Kaiser Elementary (295)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/23/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
295-131A-SK-01	Kitchen sink, west wall, right faucet	<1.0*1		µg/L	
295-131A-SK-02	Kitchen sink, west wall, middle faucet	1.1		µg/L	
295-131A-SK-03	Kitchen sink, west wall, left faucet	24.6	<1.0	µg/L	Faucet replaced 1/2019
295-131A-SK-04	Kitchen sink, island	13.3		µg/L	
295-131AA-SK-05	Kitchen sink, room 131AA, south wall	>50.0	1.0	µg/L	Faucet replaced 1/2019
295-131AA-SK-06	Kitchen sink, room 131AA, north wall, on right	<1.0		µg/L	
295-131AA-SK-07	Kitchen sink, room 131AA, north wall, on left	<1.0		µg/L	
295-131-DF-08	Drinking fountain, cafeteria, next to kitchen, left bubbler	<1.0		µg/L	
295-131-DF-09	Drinking fountain, cafeteria, next to kitchen, right bubbler	1.0		µg/L	
295-1310-DF-10	Drinking fountain, gymnasium, south wall	<1.0		µg/L	
295-128-DF-11	Drinking fountain, hallway 128, across from cafeteria	<1.0		µg/L	
295-126-SK-12	Classroom sink, room 126	1.8		µg/L	
295-117-DF-13	Drinking fountain, hallway 117, across from room 124, right bubbler	1.0		µg/L	
295-117-DF-14	Drinking fountain, hallway 117, across from room 124, left bubbler	1.0		µg/L	
295-123-SK-15	Classroom sink, room 123	<1.0		µg/L	
295-121-SK-016	Classroom sink, room 121	<1.0		µg/L	
295-117-DF-17	Drinking fountain, hallway 117, across from room 118, right bubbler	<1.0		µg/L	
295-117-DF-18	Drinking fountain, hallway 117, across from room 118, left bubbler	1.6		µg/L	
295-103-DF-19	Drinking fountain, hallway 103, across from room 115, right bubbler	<1.0		µg/L	
295-103-DF-20	Drinking fountain, hallway 103, across from room 115, left bubbler	1.1		µg/L	
295-109-SK-21	Classroom sink, room 109	<1.0		µg/L	
295-103-DF-22	Drinking fountain, hallway 103, across from room 107, right bubbler	1.2		µg/L	
295-103-DF-23	Drinking fountain, hallway 103, across from room 107, left bubbler	1.2		µg/L	
295-107-SK-24	Staff lounge sink, room 107	1.4		µg/L	
295-106-SK-25	Classroom sink, room 106	<1.0		µg/L	
295-127-SK-26	Classroom sink, room 127	2.7		µg/L	
295-127-DF-27	Drinking fountain, room 127	1.6		µg/L	
295-121C-SK-28	Workroom sink, room 121C	1.2		µg/L	

295-101H-SK-29	Nurse sink, room 101H	<1.0	µg/L
295-101F-DF-30	Drinking fountain, hallway 101F, in main office by room 101H	1.0	µg/L
295-136-DF-31	Drinking fountain, room 136	<1.0	µg/L
295-135-DF-32	Drinking fountain, room 135	1.4	µg/L
Phase II Sampled on 4/5/2017			
295-135-SK-33	Classroom sink, room 135	<1.0	µg/L
295-136-SK-34	Classroom sink, room 136	2.0	µg/L
295-104-SK-35	Classroom sink, room 104	1.0	µg/L
295-105-SK-36	Classroom sink, room 105	<1.0	µg/L
295-124-SK-37	Classroom sink, room 124	4.0	µg/L
295-106-SK-38	Classroom sink, room 106, northwest corner	1.0	µg/L
295-106-SK-39	Classroom sink, room 106, southeast corner	2.0	µg/L
295-108D-SK-40	LMC/IMC office sink, room 108D	4.0	µg/L
295-110-SK-41	Classroom sink, room 110	<1.0	µg/L
295-112-SK-42	Classroom sink, room 112	<1.0	µg/L
295-113-SK-43	Classroom sink, room 113	<1.0	µg/L
295-114-SK-44	Classroom sink, room 114	1.0	µg/L
295-115-SK-45	Classroom sink, room 115, left sink	4.0	µg/L
295-115-SK-46	Classroom sink, room 115, center sink	4.0	µg/L
295-115-SK-47	Classroom sink, room 115, right sink	<1.0	µg/L
295-116-SK-48	Classroom sink, room 116, right sink	2.0	µg/L
295-116-SK-49	Classroom sink, room 116, middle sink	5.0	µg/L
295-116-SK-50	Classroom sink, room 116, left sink	<1.0	µg/L
295-119-SK-51	Classroom sink, room 119	2.0	µg/L
295-120-SK-52	Classroom sink, room 120	<1.0	µg/L
295-122-SK-53	Classroom sink, room 122, northeast sink, left faucet	<1.0	µg/L
295-122-SK-54	Classroom sink, room 122, northeast sink, right faucet	<1.0	µg/L
295-122-SK-55	Classroom sink, room 122, southeast sink	<1.0	µg/L
295-125-SK-56	Classroom sink, room 125	<1.0	µg/L

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.