

Merrill (412)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
Phase I Sampled on 10/26/2016					
412-129-SK-01	Kitchen prep sink, room 129, northeast corner	<1.0* ¹		µg/L	
412-120-DF-02	Drinking fountain, hallway 120, next to 120B, left bubbler	2.0		µg/L	
412-120-DF-03	Drinking fountain, hallway 120, next to 120B, right bubbler	1.0		µg/L	
412-128-DF-04	Drinking fountain, cafeteria, southwest corner, left bubbler	5.0		µg/L	
412-128-DF-05	Drinking fountain, cafeteria, southwest corner, right bubbler	3.0		µg/L	
412-125-SK-06	Classroom sink, room 125	<1.0		µg/L	
412-120-DF-07	Drinking fountain, hallway 120, next to room 125, left bubbler	2.0		µg/L	
412-120-DF-08	Drinking fountain, hallway 120, next to room 125, right bubbler	2.0		µg/L	
412-126-DF-09	Drinking fountain, south gymnasium 126, left bubbler	2.0		µg/L	
412-126-DF-10	Drinking fountain, south gymnasium 126, right bubbler	3.0		µg/L	
412-127-DF-11	Drinking fountain, north gymnasium 127, left bubbler	7.0		µg/L	
412-127-DF-12	Drinking fountain, north gymnasium 127, right bubbler	6.0		µg/L	
412-120-DF-13	Drinking fountain, hallway 120, next to room 132, left bubbler	2.0		µg/L	
412-120-DF-14	Drinking fountain, hallway 120, next to room 132, right bubbler	2.0		µg/L	
412-101C-SK-15	Nurse sink, room 101C	2.0		µg/L	
412-100A-SK-16	Faculty lounge sink, room 100A	3.0		µg/L	
412-100-DF-17	Drinking fountain, hallway 100, next to room 109, left bubbler	3.0		µg/L	
412-100-DF-18	Drinking fountain, hallway 100, next to room 109, right bubbler	3.0		µg/L	
412-010-DF-19	Bottle fill, hallway 010, next to room 016	<1.0		µg/L	
412-010-DF-20	Drinking fountain, hallway 010, next to room 016	<1.0		µg/L	
412-018-SK-21	Classroom sink, room 018	5.0		µg/L	
412-019-SK-22	Faculty lounge sink, room 019	7.0		µg/L	
412-222-SK-23	Lounge/office sink, room 222	23.0	4.0* ²	µg/L	Faucet replaced 7/15/2017
412-218-DF-24	Drinking fountain, hallway 218, next to room 222, left bubbler	8.0		µg/L	
412-218-DF-25	Drinking fountain, hallway 218, next to room 222, right bubbler	3.0		µg/L	

412-218-DF-26	Drinking fountain, hallway 218, across from room 226, left bubbler	4.0		µg/L	
412-218-DF-27	Drinking fountain, hallway 218, across from room 226, right bubbler	3.0		µg/L	
412-226-SK-28	Classroom sink, room 226	7.0		µg/L	
412-218-DF-29	Drinking fountain, hallway 218, next to room 218F, left bubbler	3.0		µg/L	
412-218-DF-30	Drinking fountain, hallway 218, next to room 218F, right bubbler	2.0		µg/L	
412-200-DF-31	Drinking fountain, hallway 200, next to room 215, left bubbler	1.0		µg/L	
412-200-DF-32	Drinking fountain, hallway 200, next to room 215, right bubbler	1.0		µg/L	
412-200-DF-33	Drinking fountain, hallway 200, next to room 209	7.0		µg/L	
Phase II Sampled on 9/21/2017					
412-132-SK-34	Classroom sink, room 132	0.9		µg/L	
412-105-SK-35	Classroom sink, room 105	5.9		µg/L	
412-107-SK-36	Classroom sink, room 107	6.0		µg/L	
412-110A-SK-37	Nurse sink, room 110A, left sink	3.0		µg/L	
412-110A-SK-38	Nurse sink, room 110A, right sink	2.0		µg/L	
412-016-SK-39	Art room sink, room 016, left faucet	7.0		µg/L	
412-016-SK-40	Art room sink, room 016, right faucet	2.0		µg/L	
412-224-SK-41	Classroom sink, room 224	3.0		µg/L	
412-221-SK-42	Classroom sink, room 221	5.0		µg/L	
412-220-SK-43	Classroom sink, room 220, south wall, left sink	4.0		µg/L	
412-220-SK-44	Classroom sink, room, 220, south wall, center sink	3.0		µg/L	
412-220-SK-45	Classroom sink, room 220, south wall, right sink	3.0		µg/L	
412-227B-SK-46	Storage room sink, room 227B	15.6	>50.0	µg/L	Faucet replaced 4/12/2018 – No Drinking Notice
412-227-SK-47	Classroom sink, room 227	9.0		µg/L	
412-216-SK-48	Science lab sink, room 216, demonstration sink	>50.0		µg/L	Lab Sink – No Drinking Notice
412-216B-SK-49	Science prep sink, room 216B	24.0		µg/L	Lab Sink – No Drinking Notice
412-216-SK-50	Science lab sink, room 216, east wall, right sink	>50.0		µg/L	Lab Sink – No Drinking Notice
412-216-SK-51	Science lab sink, room 216, south wall	21.0		µg/L	Lab Sink – No Drinking Notice
412-203-SK-52	Science lab sink, room 203	27.0		µg/L	Lab Sink – No Drinking Notice
412-215-SK-53	Science lab sink, room 215, demonstration sink	8.0		µg/L	
412-215-SK-54	Science lab sink, room 215, northwest corner	15.0		µg/L	Lab Sink – No Drinking Notice
412-100-DF-69* ³	Drinking fountain, hallway 100, next to room 117B	2.0		µg/L	

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.

*2. Follow up sample tested with a Palintest SA1100 scanning analyzer.

*3. **412-100-DF-69** was inoperable at the time of planned sampling. A first draw sample was collected from this fountain on 9/12/2018 following repairs.