

Smedley Elementary (274)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 8/24/2016					
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action
274-120-DF-01	Drinking fountain, cafeteria	<1.0*1		µg/L	
274-007-DF-02	Drinking fountain, hallway 007, left	>50.0	6.0	µg/L	Bubbler replaced 4/2018
274-007-DF-03	Drinking fountain, hallway 007, right	>50.0	4.0	µg/L	Bubbler replaced 4/2018
274-008-DF-04	Drinking fountain, room 008, left	13.5		µg/L	
274-000-DF-05	Drinking fountain, hallway 000	<1.0		µg/L	
274-119-DF-06	Drinking fountain, gym, left	3.1		µg/L	
274-113-DF-07	Drinking fountain, hallway 113	<1.0		µg/L	
274-113-DF-08	Bottle fill, hallway 113	<1.0		µg/L	
274-111A-SK-09	Sink, faculty lounge	3.0		µg/L	
274-120B-SK-10	Kitchen sink, left, west wall	5.6		µg/L	
274-120B-SK-11	Kitchen sink, right, west wall	2.8		µg/L	
274-120B-SK-12	Kitchen sink, east wall	9.7		µg/L	
274-100-DF-13	Drinking fountain, hallway 100, next to restrooms, left	8.2		µg/L	
274-100-DF-14	Drinking fountain, hallway 100, next to restrooms, right	4.4		µg/L	
274-100-DF-15	Drinking fountain, hallway 100, next to room 108, left	1.1		µg/L	
274-100-DF-16	Drinking fountain, hallway 100, next to room 108, right	>50.0	<1.0	µg/L	Bubbler replaced and plumbed to filter 4/2018
274-108-DF-17	Drinking fountain, room 108, left	12.7		µg/L	
274-108-DF-18	Drinking fountain, room 108, right	9.2		µg/L	
274-107-DF-19	Drinking fountain, room 107, left	20.1	12.0	µg/L	Bubbler replaced 4/2018
274-107-DF-20	Drinking fountain, room 107, right	5.3		µg/L	
274-201-DF-21	Drinking fountain, hallway 201	<1.0		µg/L	
274-203-SK-22	Sink, room 22	<1.0		µg/L	
Phase II Sampled on 1/20/2017					
274-004AB-SK-23	Office sink, room 004AB	<1.0		µg/L	
274-010-SK-24	Break room sink, room 010	10.0		µg/L	
274-107-SK-25	Classroom sink, room 107	5.0		µg/L	
274-108-SK-26	Classroom sink, room 108	7.0		µg/L	
274-105-SK-27	Classroom sink, room 105	3.0		µg/L	

274-109-SK-28	Classroom sink, room 109	12.0		µg/L	
274-104-SK-29	Classroom sink, room 104	6.0		µg/L	
274-110-SK-30	Classroom sink, room 110	3.0		µg/L	
274-103B-SK-31	LMC/IMC office sink, room 103B	1.0		µg/L	
274-102-SK-32	Classroom sink, room 102	11.0		µg/L	
274-125D-SK-33	Nurse sink, room 125D	31.0	7.0	µg/L	Faucet replaced 7/2017
274-114-SK-34	Classroom sink, room 114	<1.0		µg/L	
274-124-SK-35	Classroom sink, room 124	<1.0		µg/L	
274-123-SK-36	Classroom sink, room 123	<1.0		µg/L	
274-115-SK-37	Classroom sink, room 115	<1.0		µg/L	
274-122-SK-38	Classroom sink, room 122	<1.0		µg/L	
274-116-SK-39	Classroom sink, room 116, on left	2.0		µg/L	
274-116-SK-40	Classroom sink, room 116, on right	1.0		µg/L	
274-206-SK-41	Classroom sink, room 206	2.0		µg/L	
274-204-SK-42	Classroom sink, room 204	<1.0		µg/L	
274-207-SK-43	Classroom sink, room 207	<1.0		µg/L	
274-202-SK-44	Classroom sink, room 202, on extended countertop, on right	<1.0		µg/L	
274-208-SK-45	Classroom sink, room, 208	<1.0		µg/L	

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.