

Summit Academy HS (1105) – Sampled 10/12/2017

All results below 15 ppb – No further action at this time.

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Sample ID	Sample Description	Lead Result	Units	Action
1105-103-DF-01	Bottle fill, hallway 103, next to classroom 118	<0.1*	µg/L	
1105-103-DF-02	Drinking fountain, hallway 103, next to classroom 118, left bubbler	<0.1	µg/L	
1105-103-DF-03	Drinking fountain, hallway 103, next to classroom 118, right bubbler	<0.1	µg/L	
1105-121-SK-04	Nurse sink, room 121	0.3	µg/L	
1105-130-SK-05	All purpose room sink, room 130	<0.1	µg/L	
1105-105-DF-06	Drinking fountain, hallway 105, next to room 124, left bubbler	<0.1	µg/L	
1105-105-DF-07	Bottle fill hallway 105, next to room 124	<0.1	µg/L	
1105-105-DF-08	Drinking fountain, hallway 105, next to room 124, right bubbler	<0.1	µg/L	
1105-224-SK-09	Science lab sink, room 224	0.3	µg/L	
1105-204-DF-10	Drinking fountain, lobby 204	<0.1	µg/L	
1105-200-DF-11	Bottle fill, hallway 200, next to room 217	<0.1	µg/L	
1105-200-DF-12	Drinking fountain, hallway 200, next to room 217, left bubbler	<0.1	µg/L	
1105-200-DF-13	Drinking fountain, hallway 200, next to room 217, right bubbler	<0.1	µg/L	
1105-209-SK-14	Science lab sink, room 209, left faucet	0.2	µg/L	
1105-209-SK-15	Science lab sink, room 209, center faucet	0.2	µg/L	
1105-209-SK-16	Science lab sink, room 209, right faucet	0.1	µg/L	
1105-208-SK-17	Science lab sink, room 208	0.3	µg/L	
1105-207-SK-18	Science lab sink, room 207, left faucet	0.2	µg/L	
1105-207-SK-19	Science lab sink, room 207, right faucet	0.2	µg/L	

*Result less than 0.1 ppb which is the lowest level that can be reported by the lab.