

Denver Language School @ Whiteman Elementary (288)

Sample ID Key:

Building number – room number – fixture type (DF = drinking fountain, SK = sink) – consecutive sample number

Phase I Sampled on 9/15/2016						
Sample ID	Sample Description	Lead Result	Follow Up Result	Units	Action	
288-113-SK-01	Kitchen sink, left	1.4		µg/L		
288-113-SK-02	Kitchen sink, right	<1.0* ¹		µg/L		
288-101-DF-03	Drinking fountain, hallway 101, across from school office	<1.0		µg/L		
288-101-DF-04	Bottle filler, hallway 101, across from school office	<1.0		µg/L		
288-114-DF-05	Drinking fountain, cafeteria, left bubbler	3.3		µg/L		
288-114-DF-06	Drinking fountain, cafeteria, right bubbler	2		µg/L		
288-115-DF-07	Drinking fountain, gym, right	2.1		µg/L		
288-115-DF-08	Drinking fountain, gym, left	2.1		µg/L		
288-109-DF-09	Drinking fountain, room 109	<1.0		µg/L		
288-108-DF-10	Drinking fountain, room 108	<1.0		µg/L		
288-101-DF-11	Drinking fountain, hallway 101, across from 105, left bubbler	4.9		µg/L		
288-101-DF-12	Drinking fountain, hallway 101, across from 105, right bubbler	6.3		µg/L		
288-206-DF-13	Drinking fountain, room 206	<1.0		µg/L		
288-207-DF-14	Drinking fountain, room 207	2.9		µg/L		
288-200-DF-15	Drinking fountain, hallway 200, next to room 208, left bubbler	3.3		µg/L		
288-200-DF-16	Drinking fountain, hallway 200, next to room 208, right bubbler	2.1		µg/L		
288-200-DF-17	Drinking fountain, hallway 200, next to room 201, left bubbler	1.5		µg/L		
288-200-DF-18	Drinking fountain, hallway 200, next to room 201, right bubbler	1.6		µg/L		
288-101-DF-19	Drinking fountain, hallway 101, next to room 120, left bubbler	<1.0		µg/L		
288-101-DF-20	Drinking fountain, hallway 101, next to room 120, right bubbler	<1.0		µg/L		
Phase II Sampled on 3/7/2017						
288-118-SK-21	Classroom sink, room 118	<1.0		µg/L		
288-117-SK-22	Classroom sink, room 117	<1.0		µg/L		
288-119-SK-23	Classroom sink, room 119	<1.0		µg/L		
288-116-SK-24	Classroom sink, room 116	<1.0		µg/L		
288-120-SK-25	Classroom sink, room 120	<1.0		µg/L		
288-102F-SK-26	Admin office sink, room 102F	3.0		µg/L		
288-102D-SK-27	Admin office sink, room 102D	38.0	13.0	µg/L	Faucet replaced 10/2018	
288-103-SK-28	Classroom sink, room 103	<1.0		µg/L		

288-111-SK-29	Classroom sink, room 111	1.0	µg/L
288-110-SK-30	Classroom sink, room 110	1.0	µg/L
288-104-SK-31	Classroom sink, room 104	1.0	µg/L
288-106B-SK-32	LMC/IMC office sink, room 106B	4.0	µg/L
288-109-SK-33	Classroom sink, room 109	1.0	µg/L
288-108-SK-34	Classroom sink, room 108	7.0	µg/L
288-206-SK-35	Classroom sink, room 206	3.0	µg/L
288-207-SK-36	Classroom sink, room 207	<1.0	µg/L
288-208-SK-37	Classroom sink, room 208	4.0	µg/L
288-205-SK-38	Classroom sink, room 205	6.0	µg/L
288-209-SK-39	Classroom sink, room 209	2.0	µg/L
288-204-SK-40	Classroom sink, room 204	3.0	µg/L
288-203-SK-41	Classroom sink, room 203	9.0	µg/L
288-210-SK-42	Classroom sink, room 210	<1.0	µg/L
288-202-SK-43	Classroom sink, room 202	2.0	µg/L
288-211-SK-44	Classroom sink, room 211	4.0	µg/L
288-201-SK-45	Classroom sink, room 201	6.0	µg/L
288-214-SK-46	Workroom sink, room 214	13.0	µg/L

*1. Result less than 1.0 ppb which is the lowest level that can be reported by the lab.